



**Klohn Crippen Berger**

**Teck Metals Ltd.**

**Sullivan TSF 2022**

***Annual Summary of Tailings Facility  
Performance Report***



Platinum  
member

A05807A22



March 2023

March 22, 2023

Teck Metals Ltd.  
Bag 2000  
Kimberley, British Columbia  
V1A 3E1

**Jason McBain**  
**Senior Engineer, Engineering and Remediation**

Dear Mr. McBain:

**Annual Summary of Tailings Facility Performance Report  
Sullivan TSF 2022**

Klohn Crippen Berger is pleased to submit a copy of the 2022 Annual Summary of Tailings Facility Performance Report (AFPR) for Teck Metal Ltd.'s Sullivan Mine located near Kimberley, British Columbia. This report documents our visual observations of the existing conditions of the Sullivan Mine tailings embankments and our review of the instrumentation data to August 31, 2022. The reporting period for this 2022 AFPR is September 1, 2021, through August 31, 2022.

We appreciate the opportunity to continue to provide our services to Teck Metals. Please call the undersigned at 780-733-4592 if you have any questions.

Yours truly,

**KLOHN CRIPPEN BERGER LTD.**



Pamela Fines, M.A.Sc., P.Eng.  
Associate / Manager, Edmonton

PF/bb

# Teck Metals Ltd.

**Sullivan TSF 2022**

## *Annual Summary of Tailings Facility Performance Report*

## CLARIFICATIONS REGARDING THIS REPORT

This report is an instrument of service of Klohn Crippen Berger (KCB). The report has been prepared for the exclusive use of Teck Metals Ltd. (Client) and the applicable regulatory authorities for the specific application to the 2022 Annual Summary of Tailings Facility Performance Report, and it may not be relied upon by any other party without KCB's written consent.

KCB has prepared this report in a manner consistent with the level of care, skill and diligence ordinarily provided by members of the same profession for projects of a similar nature at the time and place the services were rendered. KCB makes no warranty, express or implied.

Use of or reliance upon this instrument of service by the Client is subject to the following conditions:

1. The report is to be read in full, with sections or parts of the report relied upon in the context of the whole report.
2. The Executive Summary is a selection of key elements of the report. It does not include details needed for the proper application of the findings and recommendations in the report.
3. The observations, findings and conclusions in this report are based on observed factual data and conditions that existed at the time of the work and should not be relied upon to precisely represent conditions at any other time.
4. The report is based on information provided to KCB by the Client or by other parties on behalf of the client (Client-supplied information). KCB has not verified the correctness or accuracy of such information and makes no representations regarding its correctness or accuracy. KCB shall not be responsible to the Client for the consequences of any error or omission contained in Client-supplied information.
5. KCB should be consulted regarding the interpretation or application of the findings and recommendations in the report.

## EXECUTIVE SUMMARY

This report presents the 2022 Annual Summary of tailings facility performance at Sullivan Mine located in Kimberley, British Columbia. The 2022 annual facility performance report (AFPR) is the 31st consecutive annual inspection of the embankments at the facility carried out by Klohn Crippen Berger Ltd. (KCB).

As per previous AFPRs by KCB, off-site water discharge quality, groundwater quality and monitoring, and geochemical assessment and monitoring are excluded from the scope of this report. These aspects are reviewed by others and are reported separately. These issues would only be referred to if they were contributory to facility integrity for any of the tailings structures. This has not been the case to date, including the 2022 review period.

The report presents the key findings from the site visit by the Engineer of Record (EoR), Ms. Pamela Fines, P.Eng. and Ms. Makayla Rettger, EIT (SK) on May 25 to 26, 2022, as well as a review of the instrumentation data collected, and routine work performed at Sullivan Mine between September 1, 2021, and August 31, 2022.

Based on the visual inspection of the site during the AFPR and a review of available instrument data, the embankments appear to continue to be in good physical condition, and the observed performance has been consistent with historical performance and is satisfactory. There was no evidence of any potential dam safety concerns for facilities that have been inactive for at least >25 years and, in some cases, more than 50 years.

### Facility Description

After almost a century of operations, the Sullivan Mine was closed at the end of 2001. Reclamation work on the tailings area was formally initiated in 1990 and was essentially completed by 2008.

There is a total of 15 earthfill embankment structures that create seven separate storage facilities for tailings, Acid Rock Drainage (ARD) water, and water treatment sludge. The earthfill structures have a combined length of about 10.4 km, with maximum heights varying from 4.2 m to 29 m. A summary of the maximum height and crest lengths of the main embankments for each facility is shown in Table ES.1 below.

While many of the tailings facilities were initially designed and constructed through the 1970s and 1980s or earlier, field investigations and design reviews (stability and performance assessments) have been periodically completed since that time. Over the 10 years leading up to closure, a significant amount of work was conducted to enhance long-term stability; modifications to the containment structures included flattening of slopes and/or construction of toe berms such that the structures meet or exceed industry recommended Factors of Safety (FoS) under static and dynamic loading, considering the Maximum Credible Earthquake and assuming all saturated tailings liquefy. In addition, a closure surface water management plan was put in place including construction of surface water diversions and spillways to safely handle flows from the respective Inflow Design Floods (IDF). Finally, these tailings facilities all reside above original ground and continue to drain at variable rates to the point where most of the contained tailings are largely unsaturated. As a result, the portion of

tailings vulnerable to liquefaction has significantly reduced from that assumed during design of the stabilization measures prior to closure.

The only active facility in terms of receiving solid materials is the Sludge Impoundment. No modifications have been required for the Sludge Impoundment embankments to date. This is because the original design capacity of the facility far exceeded production requirements and there had been little accumulation of sludge immediately against the embankments. Teck is currently completing a site-wide review of their water management plan including the Sludge Impoundment. A design review is pending for the Sludge Impoundment following completion of this review and an assessment of future water treatment plans which may impact the Sludge Impoundment storage requirements.

**Table ES.1 Summary of Storage Facilities at Sullivan Mine**

Storage Facility	Embankments	Type	Approximate Embankment Length (m)	Approximate Maximum Embankment Height (m)	Starter Dike Constructed (Year) <sup>1</sup>	Year of Last Dike Raise (Year)
Iron TSF	Iron Dike	Iron Tailings	1500	29.0	1975	1999
Old Iron TSF	Old Iron Dike	Iron Tailings	520	7.6	Prior to 1948	Unknown
	Iron TSF Divider Dike	Iron Tailings	1190	3.6 <sup>3</sup>	Post 1948	Unknown
Siliceous TSF	No. 1 Siliceous Dike	Silica Tailings	2000	4.9 <sup>3</sup>	1923	1979
	No. 2 Siliceous Dike	Silica Tailings	730	9.5	1975	1982
	No. 3 Siliceous Dike	Silica Tailings	1540	12.5	1975	1984
Gypsum TSF	East Gypsum Dike	Gypsum	670	16.8	1969	1983
	West Gypsum Dike	Gypsum	640	22.9	1969	1986
	Northeast Dike	Gypsum, Seepage Water	120	10.0	1985	1985
	Recycle Dam	Seepage/ARD Water	90	6.0	1985	1985
Calcine TSF	Calcine Dike	Calcine	520	4.6 <sup>3</sup>	1972	1986
ARD Pond <sup>2</sup>	North Dam	ARD/Seepage Water	460	7.6	2001	2001
	South Dam	ARD/Seepage Water	330	16.8	1976	2001
Sludge Impoundment	North Dike	Sludge	120	4.3	1978	1978
	South Dike	Sludge	200	6.1	1978	1978

**Notes:**

<sup>1</sup> Starter Dike information based on data from Annual Inspection Report by SRK-Robinson dated June 1991.

<sup>2</sup> The ARD Pond is established at the site of the old Cooling Pond.

<sup>3</sup> Tailings were placed downstream of both Iron TSF Divider Dike and No. 1 Siliceous Dike. The original height of the Iron TSF Divider and No. 1 Siliceous Dikes from original ground is 10.7 m and 16.8 m, respectively. A municipal landfill is downstream from the Calcine Dike. The height of the Calcine Dike from original ground is 15.2 m.

## Credible Failure Modes Review

KCB understands that Teck's long-term goal for all of their tailings facilities, where physically possible, is to reach landform status, with all potential failure modes that could result in catastrophic release of tailings and/or water being either not present or having been reduced to non-credible. Teck's long-term goal for the Sullivan facilities is for all potential failure modes to be non-credible, based on extreme loading conditions, or to manage the risk to ALARP (i.e., as low as reasonably practicable) using appropriate loading conditions when it is not practicable to address extreme loading conditions.

The Sullivan risk register was reviewed by KCB and Teck in May 2022. There were no changes to the key hazards and the existing controls were adequate to manage potential failure modes.

To supplement the risk review, Teck, with support from KCB, conducted a credible catastrophic failure mode assessment in April 2022. Teck's definition of a "catastrophic" failure is one with a risk to life safety or irreversible impact to a rare or valued ecosystem, social or cultural heritage element. The assessment concluded that, based on the available information and current understanding of the site, there are no credible "catastrophic" failure scenarios for the Sullivan tailings facilities.

The following is a summary of the controls in place at Sullivan Mine to manage the risks associated with the key failure modes for the facilities. The slope instability failure mode is considered credible (though non-catastrophic), while the internal erosion and overtopping failure modes are not credible for the current and historic loading conditions. Based on the observations above and the available information, Teck is managing the potential failure mechanisms for the TSFs appropriately.

## Overtopping

The likelihood of overtopping failures leading to catastrophic consequences up to and including Extreme consequence loading conditions is negligible, and therefore non-credible, for the inactive tailings storage facilities given the closure water management measures already in place (e.g. drainage channels, spillways, etc. designed to discharge the probable maximum flood (PMF)).

This is also applicable for the active water storage facilities, ARD Pond and Iron Pond, because they have emergency spillways designed to safely pass the PMF. The likelihood is even more remote for the ARD Pond because it can store a PMF before the water level rises to the invert of the spillway.

For the active Sludge Impoundment, the likelihood of an overtopping failure leading to catastrophic consequences is non-credible as there is no population in the vicinity of the dam.

## Internal Erosion / Piping

The likelihood of internal erosion/piping failure modes resulting in catastrophic consequences is considered to be negligible, and therefore non-credible, for the tailings facilities because the pond water levels are low (Iron Pond) or completely absent (inactive facilities) and the associated piezometric surfaces within the tailings are very low.



The likelihood of internal erosion/piping failure modes resulting in catastrophic consequences is considered negligible for the ARD Pond Dams. These dams have filter zones in the dam cross-section. There is a seepage pathway on the left abutment of the South Dam that responds to the reservoir water fluctuations, however investigations and assessments have determined that the soils are internally stable and not susceptible to internal erosion.

For the Sludge Impoundment, the likelihood of an internal erosion/ piping failure leading to catastrophic consequences is considered to be negligible, and therefore non-credible, due to the inclusion of filters in the embankment and the lack of a permanent pond.

### Slope Stability

Static stability factors of safety are well above the minimum recommended values for all the structures and the likelihood of failure under static loadings leading to catastrophic consequences is considered negligible and non-credible.

The likelihood of seismic instability (foundation and slope) failure modes leading to catastrophic consequences is considered to be negligible, and therefore non-credible, for the facilities because of the seismic stabilization measures completed prior to closure. As previously indicated, since closure in 2001, the phreatic surface in the tailings facilities has decreased significantly so that the portion of tailings vulnerable to seismic liquefaction has also significantly reduced compared to original design assumptions. The likelihood of seismic instability leading to catastrophic consequences for the Gypsum and Siliceous TSFs is currently judged to be low, pending further review once the assessments from the investigation are completed. The likelihood of slope instability leading to catastrophic consequences for these two facilities is considered to be non-credible due to the lack of a permanent pond and very low phreatic surface within the tailings, which means that while slumping could occur within the facility, downstream consequences will be limited. There are no liquefiable materials present in the foundation and embankment fill of the ARD Pond Dams and the deformations induced by the maximum credible earthquake (MCE) are computed to be small and acceptable. Therefore, the likelihood of seismic instability leading to catastrophic consequences is considered negligible, and therefore non-credible, for the ARD Pond Dams. It should be noted that a due diligence update of the seismic stability of all structures is underway to better reflect existing conditions and to incorporate the revised seismic hazard assessment. This work is important to update the supporting documentation but is not expected to materially change the current conclusions.

### Key Observations (Instrumentation and Visual)

Notification levels have been established for all instruments installed prior to 2020. The current notifications levels for piezometers are not intended to be indicative of a dam safety concern but rather to identify any measured change from historic or expected behaviour that warrants a due diligence review by Teck and the Engineer of Record (or designate) to understand the likely cause of that change. The current monitoring period is from September 1, 2021 to August 31, 2022. The previous monitoring period was from September 1, 2020 to August 31, 2021.

Notification levels tied to seismic stability assumptions for two facilities and internal erosion at the ARD Pond Dams and the Silicious Pond Dams are now in place. The alert levels update also includes updated levels based on more recent historical performance.

A facility-by-facility indication of condition and stability follows, inclusive of those for facilities deemed to have no credible failure modes leading to catastrophic consequences.

### *Iron TSF*

Based on the visual observations and instrumentation review, the Iron TSF and its emergency spillway are in good condition and are performing satisfactorily.

Seepage near station 5+00 is monitored by Weir #3 and Weir #4 installed in the drainage ditch. Seepage near station 24+00 is collected in an existing low-lying area beyond the toe of the embankment. There are no obvious changes in the seepage conditions compared to previous years.

All 30 piezometers showed relatively constant piezometric, or slightly increased readings compared to the previous monitoring period. Increased readings can be attributed to changes in weather conditions (i.e., wetter spring). The readings were generally consistent with historic monitoring trends.

### *Old Iron TSF*

Based on the visual observations and instrumentation review, the Old Iron TSF and the Iron TSF Divider Dike are in good condition, with no visible changes from previous inspections, and are performing satisfactorily.

Five of the nine currently monitored piezometers in the Old Iron TSF showed a slight increase in piezometric levels when compared to the previous monitoring period. The remaining four piezometers showed a decrease or no change in piezometric levels compared to the previous monitoring period. The readings were generally consistent with historic monitoring trends.

### *Siliceous TSF*

Based on the visual observations and instrumentation review, the Siliceous TSF is in good condition, with no visible changes from previous inspections, and is performing satisfactorily.

Visual observation of seepage indicates similar flows as previous years with no indication of sediment in the seepage flows.

17 out of 18 piezometers currently being read showed stable or decreasing piezometric levels compared to the previous monitoring period. The remaining piezometer showed a slight increase from the previous monitoring period. The readings were generally consistent with historic monitoring trends.

### *Gypsum TSF*

Based on the visual observations and instrumentation review, the East and West Gypsum TSFs, including the Northeast Gypsum Dike and the Recycle Dam, are in good condition with no visual changes from previous inspections, and are performing satisfactorily.

All 15 piezometers currently being read at the Gypsum TSF showed reduced or stable piezometric levels compared to the previous monitoring period. The readings were generally consistent with historic monitoring trends.

There are continued indications of burrowing animal activity at the toe of the embankments; the extent of these observations is not considered a dam safety issue but represents a safety hazard for personnel. Teck has worked to fill in the burrows, and this will need to continue for the new burrows identified.

The Sondex gauge was not scheduled to be read during this monitoring period. The inclinometer was read during this reporting period but the data suggests that the casing is settling and can no longer provide reliable data. The instrument will be removed from the instrument list.

### *ARD Pond*

Based on the visual observations and instrumentation review, the North and South Dams are in good condition with no visual changes from previous inspections and are performing satisfactorily.

All of the 13 currently monitored piezometers in the ARD Pond Dams indicated a slight increase or stable piezometric level compared to the previous monitoring period. The increase could be attributed to weather conditions such as increased precipitation from the previous year. The readings were generally consistent with historic monitoring trends.

### *Calcine TSF*

Based on visual observations, the Calcine TSF is in good condition with no visual changes from previous inspections and is performing satisfactorily.

### *Sludge Impoundment*

Based on the visual observations, the North and South Dikes of the Sludge Impoundment are in good condition with no visual changes from previous inspections and are performing satisfactorily. Reporting for these instruments began in October 2021, and therefore comparison to previous monitoring periods is unavailable at this time.

### **OMS and MERP Manuals**

The Operation, Maintenance, and Surveillance (OMS) Manual for the Sullivan Mine Tailings Facilities was updated in March 2022. The OMS Manual will be reviewed and updated again in early 2023 to include GISTM (2020) criteria.

The Mine Emergency Preparedness and Response Plan (MERP) was updated in 2022.

## Deficiencies and Non-conformances

There were no new deficiencies or non-conformances identified, and therefore, no new recommendations arising from the current AFPR.

Previous recommendations that are still outstanding are summarized in the table below.

Consistent with past annual reviews, deficiencies and non-conformances are grouped according to the following four categories:

- **Deficiency (D):** An unacceptable dam performance condition based on analysis results and/or site observations/instrument data with respect to criteria outlined in the 2022 HSRC and 2016 Guidance Document, best practices, and/or applicable regulatory requirements.
- **Potential Deficiency (PD):** A dam performance condition that requires further evaluation to determine if the condition is a deficiency.
- **Non-Conformance (NC):** Defined as a deviation from established policies, procedures, operating instructions, maintenance requirements, or surveillance plans. A non-conformance is not an indication of unacceptable dam performance.
- **Items Requiring Updates to Meet Updated Regulatory Standards (RS):** Condition where regulatory requirements have changed and have become more stringent following initial design and/or construction.

## Independent Dam Safety Review

The most recent Dam Safety Review (DSR) for the Sullivan Mine TSFs and dams was initiated by Haley and Aldrich in 2018. The DSR report was finalized in January 2021. The HSRC regulations (EMLCI 2022) mandate that a DSR be undertaken every five years regardless of the consequence classification of the structures. Therefore, the next DSR is scheduled to be initiated in 2023.

**Table ES.2 Summary of Outstanding Recommendations from Past DSIs and New Recommendations from Current Annual Performance Report UPDATED IN SECTION 6**

Structure	ID No.	Deficiency of Non-Conformance	Applicable Regulation or OMS Reference	Recommended Action	Deficiency Type	Priority	Recommended Deadline/Status
<b>Previous Recommendations Closed/Superseded</b>							
<b>Previous Recommendations Ongoing</b>							
Sludge Impoundment	2017-3	A review of the Sludge Impoundment is needed.	EMLCI HSRC (2022) & CDA Guidelines: Application to Mining Dams (2019)	Review of the current design freeboard and design sludge levels is required. To facilitate the design update, the Sludge Impoundment surface should be surveyed to obtain average sludge deposition rates. Review of entire facility should be completed to address storage, life expectancy of the facility, and regulatory requirements.	RS	3	Q4 2024 UPDATE – Site investigation completed. The site investigation data will be combined with other groundwater information and form the basis for a workshop between Teck and KCB on the future of the facility. After the workshop is completed, a scope of work will be developed based on the workshop outcomes.

## TABLE OF CONTENTS

CLARIFICATIONS REGARDING THIS REPORT.....	I
EXECUTIVE SUMMARY .....	II
<b>1 INTRODUCTION.....</b>	<b>1</b>
1.1 Purpose, Scope of Work, and Methodology.....	1
1.2 Regulatory Requirements.....	1
1.2.1 Mines Act and HSRC .....	1
1.2.2 Water Act and BC Dam Safety Regulation .....	2
1.2.3 Permits and Licenses .....	2
1.3 Facility Description .....	3
1.4 Background Information and History .....	6
1.4.1 Reference Reports .....	7
1.4.2 Reference As-Built Drawings .....	7
1.4.3 Units of Measure and Coordinates .....	7
<b>2 MINE ACTIVITIES IN 2022.....</b>	<b>8</b>
2.1 Tailings/Sludge Deposition and Available Storage.....	8
2.2 Main Construction Activities (September 2021 to August 2022) .....	8
2.3 Site Investigation.....	8
2.4 Updates to Embankment Cross-Sections .....	8
2.5 Dam Safety Review.....	9
<b>3 CLIMATE REVIEW AND WATER MANAGEMENT – TAILINGS AREA .....</b>	<b>10</b>
3.1 Overview .....	10
3.2 Climate .....	10
3.2.1 Precipitation .....	10
3.2.2 Evaporation .....	12
3.3 Water Levels in ARD Pond and Iron Pond.....	12
3.3.1 Area-Volume Curves.....	12
3.3.2 Pond Water Levels.....	13
3.4 Tailings Area Water Balance.....	14
3.4.1 General .....	14
3.4.2 Water Balance Schematic.....	14
3.4.3 Inflows.....	16
3.4.4 Outflows .....	16
3.4.5 Water Balance Summary .....	17
3.5 Flood Management .....	19
3.6 Freeboard and Storage – Water Storage Ponds .....	19

## TABLE OF CONTENTS

(continued)

3.6.1	Iron Pond .....	19
3.6.2	ARD Pond.....	20
3.7	Off-Site Surface Water Discharge Volumes .....	21
3.8	Water Discharge Quality .....	21
<b>4</b>	<b>SITE OBSERVATIONS AND INSTRUMENTATION REVIEW .....</b>	<b>22</b>
4.1	Visual Observations.....	22
4.1.1	ARD Pond.....	22
4.1.2	Iron TSF and Iron Dike .....	23
4.1.3	No. 1, 2, and 3 Siliceous TSFs.....	23
4.1.4	East and West Gypsum TSFs .....	24
4.1.5	Northeast Gypsum Dike and Recycle Dam.....	24
4.1.6	Sludge Impoundment .....	24
4.1.7	Calcine TSF.....	25
4.1.8	Old Iron TSF .....	25
4.2	Instrumentation Data Review .....	25
4.2.1	Iron TSF.....	27
4.2.2	Old Iron TSF .....	28
4.2.3	Siliceous TSF .....	28
4.2.4	East and West Gypsum TSFs .....	29
4.2.5	ARD Pond.....	30
4.2.6	Calcine TSF.....	32
4.2.7	Sludge Impoundment .....	32
<b>5</b>	<b>TAILINGS FACILITY ASSESSMENT .....</b>	<b>33</b>
5.1	Failure Modes Review .....	33
5.1.1	Overtopping.....	33
5.1.2	Internal Erosion and Piping.....	34
5.1.3	Slope Instability .....	35
5.2	OMS Manual .....	36
5.3	Mine Emergency Response Plan .....	36
<b>6</b>	<b>SUMMARY.....</b>	<b>37</b>
<b>7</b>	<b>CLOSING.....</b>	<b>39</b>
	<b>REFERENCES.....</b>	<b>40</b>

## TABLE OF CONTENTS

(continued)

### List of Tables

Table 1.1	Summary of Storage Facilities at Sullivan Mine.....	5
Table 1.2	Historical Development.....	6
Table 3.1	Monthly Total Precipitation at Sullivan Mine 2021 – 2022 Compared to Normals from Kimberley PCC Station .....	11
Table 3.2	Mean Monthly Evapotranspiration Rates at Kimberley A station .....	12
Table 3.3	ARD Pond Monthly Water Balance Summary.....	18
Table 3.4	Relevant Iron Pond Characteristics .....	20
Table 3.5	Relevant ARD Pond Characteristics .....	20
Table 3.6	Summary of Treated Water Discharge to St. Mary River.....	21
Table 4.1	Monitoring Frequencies for 2022 Reporting Period.....	26
Table 6.1	Summary of Outstanding Recommendations from Past DSIs and New Recommendations from Current Annual Inspection .....	38

### List of Figures

Figure 1	Location and Site Plan
Figure 2	Tailings Seepage Collection and DWT Plant Location
Figure 3	General Arrangement of Design Sections
Figure 4	General Arrangement of Tailings Facilities, Photo Locations
Figure 5	Instrument Location Plan Iron Dike
Figure 6	Iron Dike Sections D and E
Figure 7	Iron Dike Section F
Figure 8	Instrument Location Plan Old Iron & Iron TSF Divider Dikes
Figure 9	Old Iron Dike Section G
Figure 10	Instrument Location Plan No. 1, 2, & 3 Siliceous Dikes
Figure 11	No. 1 Siliceous Dike Section A
Figure 12	No. 2 and No. 3 Siliceous Dikes Sections B and C
Figure 13	Instrument Location Plan West Gypsum Dike



## TABLE OF CONTENTS

(continued)

Figure 14	West Gypsum Dike Sections P and Q
Figure 15	West Gypsum Dike Section R
Figure 16	Instrument Location Plan East Gypsum Dike
Figure 17	East Gypsum Dike Sections S and T
Figure 18	Instrument Location Plan Northeast Gypsum Dike and Recycle Dam
Figure 19	Northeast Gypsum Dike and Recycle Dam Section U
Figure 20	ARD Storage Pond Plan and Layout
Figure 21	ARD Storage Pond North Dam Sections H and I
Figure 22	ARD Storage Pond North Dam Section J and K
Figure 23	ARD Storage Pond South Dam Sections L and M
Figure 24	ARD Storage Pond South Dam Section N
Figure 25	Instrument Location Plan Calcine Dike
Figure 26	Calcine Dike Section O
Figure 27	Sludge Impoundment Dikes Plan
Figure 28	Sludge Impoundment Dikes Section Z

### List of Appendices

Appendix I	2021 Visual Inspection
Appendix II	Site Visit Photographs
Appendix III	2021 Instrumentation Monitoring
Appendix IV	Iron Dike Instrumentation
Appendix V	Old Iron Instrumentation
Appendix VI	Siliceous Dike Instrumentation
Appendix VII	W Gypsum Dike Instrumentation
Appendix VIII	E Gypsum Dike Instrumentation
Appendix IX	NE Gypsum Dike Instrumentation
Appendix X	ARD Instrumentation
Appendix XI	Sludge Pond Dike Crest Survey
Appendix XII	Pond Storage Curves

## 1 INTRODUCTION

### 1.1 Purpose, Scope of Work, and Methodology

This report presents the results of the 2022 Annual Summary of Tailings Facility performance of the tailings embankments and other dams at the Teck Metals Ltd. (Teck) former Sullivan Mine, located in Kimberley, British Columbia. The work was carried out in general accordance with our proposal letter dated March 18, 2022 and the Teck Guideline for Tailing and Water Retaining Structures (Teck 2019).

The scope of work consists of:

- a visual inspection of the physical condition of the various containment embankments and water retention dams during the site visit May 25 and 26, 2022;
- a review of the climate and water balance data for the site;
- a review of the annual flow rates recorded from weirs for the Acid Rock Drainage (ARD) pond and Iron Tailings Storage Facility (TSF);
- a review of updated piezometer and settlement records provided by Teck in 2022; and
- a review of the risk register for the storage facilities.

The reporting period for this annual report (AFPR) is September 1, 2021 to August 31, 2022. The previous monitoring period was from September 1, 2020 to August 31, 2021. Figures 1 through 3 show the project location and general layout of the tailings facilities.

This is the 31<sup>st</sup> AFPR of the Sullivan Mine tailings embankments carried out by Klohn Crippen Berger Ltd. (KCB). Annual reports for the periods preceding KCB's involvement were prepared by SRK-Robinson Inc. from 1989 to 1991 and by Robinson Dames and Moore from 1984 to 1988.

As per previous annual inspection reports by KCB, this report focuses on the geotechnical performance of the tailings embankments and water balance for the tailings facilities. Off-site water discharge quality, groundwater quality and monitoring, and geochemical assessment and monitoring are excluded from the scope of this report. These aspects are reviewed by others and are reported separately. These issues would only be referred to if they were contributory to facility integrity for any of the tailings structures. This has not been the case to date, including the 2022 review period.

### 1.2 Regulatory Requirements

#### 1.2.1 Mines Act and HSRC

This annual inspection addresses the performance of the tailings/sludge storage facilities and associated water management infrastructure in accordance with the Health, Safety, and Reclamation Code for Mines in British Columbia (EMLCI 2022) and Guidance Documents (EMLCI 2016), which forms part of the Mines Act (RSBC 1996).

As required by the HSRC, the following persons have been designated:

- Engineer of Record – Ms. Pamela Fines, P.Eng. (KCB)
- Responsible Tailings Facility Engineer – Mr. Jason McBain, P.Eng. (Teck)

### 1.2.2 Water Act and BC Dam Safety Regulation

None of the tailings embankments or dams at Sullivan Mine require a water licence and are therefore not regulated by the BC Dam Safety Regulations. A conditional water licence (C050428) has been issued for the construction of the sludge impoundment. The BC Dam Safety Regulation was referenced for guidance related to dam safety, where appropriate.

### 1.2.3 Permits and Licenses

Sullivan Mine is regulated by the following permits:

- Reclamation Permit M-74 (amended June 3, 2020) issued by the Ministry of Mines. This permit is issued under the provision of the Mines Act (RSBC 1996) and addresses reclamation, metal leaching, and acid rock drainage requirements at Sullivan Mine. The requirements of the permit are:
  - ◆ monitoring programs of vegetation, surface water, and groundwater;
  - ◆ annual reporting as required under the HSRC (EMLCI 2022); and
  - ◆ informing the ministry of changes at the mine that might impact the amount of the reclamation security.
- Effluent Permit PE-00189 (October 24, 2016) issued by the Ministry of Environment and Climate Change Strategy. This permit is issued under the provision of the Environmental Management Act (SBC 2003) and authorizes the discharge of effluent from the drainage water treatment plant to the St. Mary River as well as sludge to the land-based storage pond, and effluent from the 3700 foot portal to Kimberley Creek. Requirements under this permit include:
  - ◆ General requirements (Section 2 of the permit) which state the conditions under which the Drainage Water Treatment Plant (DWTP) and Sludge Impoundment must be operated (i.e. maintaining the infrastructure in good working order, addressing emergencies, modification to infrastructure and processes, and suspension).
  - ◆ Monitoring and reporting requirements (Sections 3 and 6 of the permit) which describe monitoring work to conduct on the discharges and receiving environment as well as the reporting frequency (i.e., spring and fall).
- Permit PR6742 (January 2, 2018) issued by the Ministry of Environmental Protection & Sustainability: Waste Management. This permit is issued under the provision of the Environmental Management Act (SBC 2003) and authorizes the discharge of refuse to a landfill. The landfill is located within the boundaries of the Old Iron TSF (northwest corner) and is denoted as E242184 and E310949 by the Ministry. Requirements under this permit include:

- ◆ reporting of volumes of material placed within the landfill; and
- ◆ regular inspection and maintenance of the landfill works.

### 1.3 Facility Description

There is a total of 15 earthfill embankment structures that form the seven separate storage facilities. A summary of the seven facilities and their associated embankment structures is provided in Table 1.1. The earthfill structures have a combined crest length of just over 10.4 km, with the maximum heights varying from 4.2 m to 29 m. A plan of the storage facilities and their retaining structures is provided in Figure 1.

The two water retaining dams<sup>2</sup>, designated as the North Dam and South Dam, that form the ARD Pond are shown in Figure 20. This pond, located at the former Cooling Pond site, annually stores the mine contact water collected from the Sullivan Mine site requiring treatment. The two sludge retention embankments, designated as the North and South Dikes, that form the Sludge Impoundment are shown in Figure 27. This impoundment is located south of the St. Mary River and stores sludge produced from treatment of mine contact water at the DWTP<sup>1</sup>.

Other than the above earthfill structures, the other embankments listed in Table 1.1 have been used primarily for tailings storage. Typically, these embankments consist of an initial earthfill starter section raised incrementally over the years using the upstream method of construction. The design and construction records for the original Old Iron TSF Dikes and the No. 1 Siliceous Dike (which were constructed during the 1920's to 1940's), are not available, so it is unclear how these were originally constructed. In the 1990's, following the static liquefaction failure experienced at the Iron Dike (Davies et al, 1998) in 1991, the long-term stability of all the tailings embankments were assessed which led to the construction of stabilization measures (i.e. slopes flattening and/or toe buttresses) to meet required design criteria. A discussion of the design basis and criteria is provided in Section 5.1.

The Iron Pond, the ARD Pond, the West Gypsum Seepage Collection Pond, and the Northeast Gypsum and Recycle Dam seepage collection ponds are the only storage facilities that are still active as they are used as integral components of the overall surface water and groundwater management strategy at the Sullivan Mine. The Sludge Impoundment is also active but does not retain ponded water. The other tailings facilities have been decommissioned and surface reclamation is complete. The reclamation included draining and covering the TSF surface and constructing surface water runoff conveyance channels and spillways.

Water collected at Sullivan Mine through mine drainage, contaminated groundwater, and seepage from TSFs and waste dumps is stored in the ARD Pond and then pumped to the DWTP. The ARD Pond serves as a flow equalization basin to facilitate seasonal operating campaigns at the DWTP. The treated water is released to the environment (St. Mary River) and the sludge is deposited in the Sludge Impoundment. The ARD Pond was designed with a spillway, which connects to the Iron Pond

---

<sup>1</sup> In this report KCB refers to water retaining earthfill embankments as "dams" and refers to the earthfill embankments that are constructed for tailings storage and sludge storage as "dikes."

in the Iron TSF. The Iron TSF has an emergency spillway to safely convey excess water offsite from flood events up to and including the PMF. This spillway discharges flood flows into Cow Creek, which in turn discharges into the St. Mary River.

Site location plans and typical embankment sections are provided in Figures 5 through 28.

**Table 1.1 Summary of Storage Facilities at Sullivan Mine**

Storage Facility	Embankments	Type	Approximate Embankment Length (m)	Approximate Maximum Embankment Height (m)	Starter Dike Constructed (Year) <sup>1</sup>	Year of Last Dike Raise (Year)
Iron TSF	Iron Dike	Iron Tailings	1500	29.0	1975	1999
Old Iron TSF	Old Iron Dike	Iron Tailings	520	7.6	Prior to 1948	Unknown
	Iron TSF Divider Dike	Iron Tailings	1190	3.6 <sup>3</sup>	Post 1948	Unknown
Siliceous TSF	No. 1 Siliceous Dike	Silica Tailings	2000	4.9 <sup>3</sup>	1923	1979
	No. 2 Siliceous Dike	Silica Tailings	730	9.5	1975	1982
	No. 3 Siliceous Dike	Silica Tailings	1540	12.5	1975	1984
Gypsum TSF	East Gypsum Dike	Gypsum	670	16.8	1969	1983
	West Gypsum Dike	Gypsum	640	22.9	1969	1986
	Northeast Dike	Gypsum, Seepage Water	120	10.0	1985	1985
	Recycle Dam	Seepage/ARD Water	90	6.0	1985	1985
Calcine TSF	Calcine Dike	Calcine	520	4.6 <sup>3</sup>	1972	1986
ARD Pond <sup>2</sup>	North Dam	ARD/Seepage Water	460	7.6	2001	2001
	South Dam	ARD/Seepage Water	330	16.8	1976	2001
Sludge Impoundment	North Dike	Sludge	120	4.3	1978	1978
	South Dike	Sludge	200	6.1	1978	1978

**Notes:**

1. Starter Dike information based on data from Annual Inspection Report by SRK-Robinson dated June 1991.
2. The ARD Pond is established at the site of the old Cooling Pond.
3. Tailings were placed downstream of both Iron TSF Divider Dike and No. 1 Siliceous Dike. The original height of the Iron TSF Divider and No. 1 Siliceous Dikes from original ground is 10.7 m and 16.8 m, respectively. A municipal landfill abuts the downstream slope of the Calcine Dike. The height of the Calcine Dike from original ground is 15.2 m.

## 1.4 Background Information and History

After almost a century of operations, the Sullivan Mine was closed at the end of 2001 with approximately 94,000,000 tonnes of tailings stored in various TSFs and approximately 16,900,000 tonnes of mine waste stored at the former mine. Reclamation work on the tailings areas was formally initiated in 1990 and was essentially complete by 2008.

The mine had been mainly underground and operated on a near-continuous basis from the early 1900's to 2001. In the last decade prior to closure, the mine was processing primarily lead/zinc ore. For most of the mine's operating life, mill tailings were hydraulically transported to an area immediately southeast of the concentrator for disposal and storage. The historical development of the tailings area is summarized in Table 1.2. Gypsum and circulation water from operation of the fertilizer plant have also been stored in the tailings area. These by-products from the fertilizer plant were produced from about 1969 to 1987.

The DWTP, which began operating in 1979, continues to operate as part of the water management plan for the site. The DWTP treats acid rock drainage and other seepage produced from the underground mine and waste storage facilities. Sludge from the DWTP is located in an impoundment about 2 km south of Marysville near the DWTP. Figure 2 illustrates the relative locations of the DWTP, the tailings facilities, and the pipelines from the underground mine and highlights the primary seepage collection system.

**Table 1.2 Historical Development**

Date	Process	Storage Area	Comments
Prior to 1941	Milling/Flotation for lead and zinc recovery	One tailings stream to Old Iron TSF	
1941 to 1985	Tin Recovery Circuit	Iron Tailings to Old Iron TSF and Iron TSF Siliceous tailings to No. 1, 2, and 3 Siliceous Cells	
1953 to 1987	Fertilizer production including roasting of iron concentrate Waste products include iron oxide and gypsum	Iron oxide (known as calcine tailings) to Calcine TSF Gypsum tailings to East and West Gypsum Cells	Gypsum TSF not developed until 1968; prior to that gypsum tailings were stored and seasonally discharged to the St. Mary River during spring freshet
1975 to 1987	Fertilizer Plant effluent water	Stored and recycled from Cooling Ponds 1 and 2	
1987 to 2001	Fertilizer plant closed; single mill tailings stream	Single stream to Iron TSF	
1979 to present	Drainage Water Treatment Plant (DWTP) Sludge Impoundment	Sludge Impoundment	Located offsite, 1.5 km south of Marysville, 0.5 km south of DWTP
2001 to present	Water storage for feed to DWTP	Cooling Ponds 1 and 2 converted to ARD Pond	

### 1.4.1 Reference Reports

In 1991, Teck retained KCB to conduct forensic investigations to assess the failure of the (then) Active Iron Tailings Pond Dike. The work included the design of remedial measures to reinstate the Iron Dike and then subsequently extended to include a review the existing and long-term stability of a number of other tailings dikes. These studies were part of Teck efforts toward decommissioning and eventual closure of the Sullivan Mine tailings facilities. Stability assessments, and the design and implementation of stabilization measures if required, were completed for the Iron Dike, the East and West Gypsum Dikes, the No. 1, No. 2, and No. 3 Siliceous Dikes, and the Old Iron Dike. The design and construction of two new dams for the ARD pond were also completed, including new spillways and a downstream flood impact study. Additional post-closure assessments have been performed as required based on performance. The details of the design and construction records for the facilities are documented in KCB (and predecessor companies) reports.

### 1.4.2 Reference As-Built Drawings

Teck has updated as-built drawings for the various facilities post reclamation. An updated LiDAR imaged created in December 2012 was used to update the figures attached to this report. There have been no significant construction/modifications to the as-built conditions since the drawings by TM Tech Services were issued. A 2019 LiDAR survey was completed but a comparison to the 2012 surface showed very little change and the drawings have not been updated with the new survey surface.

### 1.4.3 Units of Measure and Coordinates

To facilitate the long-term monitoring of the site, this report has converted historical values recorded in imperial units of measure in the Sullivan Mine Grid coordinate system to metric units in UTM (NAD 83). Some figures still reference stationing along embankments in imperial units.



## 2 MINE ACTIVITIES IN 2022

### 2.1 Tailings/Sludge Deposition and Available Storage

The Sullivan Mine closed in 2001 and, therefore, all of the tailings storage facilities are no longer active.

The Sludge Impoundment continues to be active and provides storage of sludge generated from treatment of mine contact water through the DWTP. The average annual sludge deposition rate since closure is 2,800 tonnes/year and the total deposited sludge volume is approximately 182,000 tonnes.

### 2.2 Main Construction Activities (September 2021 to August 2022)

Construction related activities that take place each year are primarily associated with ongoing care and maintenance, such as road grading, cleaning of ditches, rodent burrow infilling, removal of trees and shrubs from embankment slopes as necessary, maintenance of the seepage collection system, maintenance of instrumentation and management of instrumentation data.

Specific key activities conducted over the current inspection period from September 1, 2021 to August 31, 2022 included:

- Backfilling of a void near the 943 pump station.
- Repair of steel v-notch weir plates.
- Lowering of low operating level in the Iron Pond.

Prior to the site visit in 2022, site staff lowered the intake levels for the 945/946 pumps located near the West Gypsum seepage collection pond and drew down the pond level. This allowed for a cleanout and regrading of the weir channels that drain towards the seepage pond. Plans were in development to remove an access road around the seepage collection pond to allow the pond to be lowered even further. Reducing the storage of water anywhere on the TSF is recommended and the area will be inspected again during the 2023 AFRP site visit.

### 2.3 Site Investigation

A site investigation was completed in October and November 2020 at the ARD South Dam, Iron TSF, Old Iron TSF, Siliceous TSF and Gypsum TSF. Site investigation was also completed at the Sludge Impoundment in September 2021. New instruments were installed during the 2020 and 2021 site investigations. Notification levels for the new instruments are being developed.

### 2.4 Updates to Embankment Cross-Sections

Typical cross-sections for each embankment have been previously updated using the 2012 LiDAR data and are shown in the figures included with this report.

A comparison of select cross-sections generated between the 2012 LiDAR surfaces and the 2019 LiDAR surfaces indicated no significant changes to the physical configuration of the embankments on the site. The updated sludge surface in the Sludge Pond from the 2019 LiDAR is provided in Figure 27.

## 2.5 Dam Safety Review

The most recent Dam Safety Review (DSR) for the Sullivan Mine TSFs and dams was initiated by Haley and Aldrich in 2018. The DSR report was finalized in January 2021. The previous DSR was completed by Golder Associates in 2013. The HSRC regulations (EMLCI 2017) mandate that a DSR be undertaken every five years regardless of the consequence classification of the structures. Therefore, the next DSR is scheduled to be initiated in 2023

## 3 CLIMATE REVIEW AND WATER MANAGEMENT – TAILINGS AREA

### 3.1 Overview

The water management system at Sullivan Mine involves the collection and treatment of mine drainage, contaminated groundwater, and seepage from TSFs and waste dumps. The only active storage facilities used as part of the water management system are the ARD Pond, Iron Pond and West Gypsum Seepage Collection Pond. Details of the system are included in the Sullivan Mine Seepage Collection Manual (Teck, 2021).

In general, water from the mine and tailings areas is collected and conveyed to the ARD Pond for storage to facilitate seasonal operating campaigns at the DWTP. The main sources of water include:

- Mine water from the underground workings is pumped seasonally from the 3700 ft portal and flows via gravity to the ARD Pond.
- Water collected from the Upper and Lower Mine Yard seepage collection systems flows via gravity in the 3900 line to the ARD Pond.
- Water from the tailings seepage collection pumps and sumps, is pumped as required to the ARD Pond.

The main function of the Iron Pond is to provide storage of contaminated/contact water during spring runoff events. In addition, the system has the flexibility to by-pass the ARD Pond with temporary routing of mine and seepage water to the Iron Pond, where it can then be pumped to the ARD Pond or directly to the DWTP if required.

The ARD Pond has a storage capacity that allows for efficient operation of the DWTP for discrete periods of time and provides control over the time period when treated effluent is discharged to St. Mary River.

It should be noted that studies are underway to identify options and opportunities to improve the current water management system which, at the same time, can contribute to Teck's overall objective of continual risk reduction for the Sullivan Mine.

### 3.2 Climate

#### 3.2.1 Precipitation

Climate stations in the Environment Canada (EC) database relevant to the Sullivan Mine Tailings Facilities precipitation and active during the time period of this water balance assessment are Kimberley PCC (Station No. 1154203) located approximately 3 km southwest of the mine and Cranbrook A (Station No. 1152105) located about 13 km southeast of the mine.

For the purpose of this assessment, site precipitation was estimated as the daily precipitation recorded at Kimberley PCC, with any missing data filled by precipitation recorded at the Cranbrook A station. Table 3.1 summarizes the total precipitation and snowpack estimated for the mine from


September 1, 2021, to August 31, 2022 and provides a comparison with the corresponding climate normals for Kimberley calculated between 1981 – 2010 (EC 2019). The total precipitation for the current monitoring period and the climate normals are also graphically shown on Figure 3.1.

On an overall annual basis, the conditions over the current monitoring period were drier than the Kimberley PCC normal levels. However, on a monthly basis, it was wetter than normal in December and October, and drier than normal in September, November, and from January to August.

**Table 3.1 Monthly Total Precipitation at Sullivan Mine 2021 – 2022 Compared to Normals from Kimberley PCC Station**

Month	2021 - 2022 Total Precipitation (mm)	Normal Total Precipitation (mm)	2021 - 2022 Snow Depth (cm)	Normal Snow Depth (cm)
Sep 2021	25.4	30.9	0	0.0
Oct 2021	26.6	25.8	0	0.0
Nov 2021	42.7	45.6	6.9	6.0
Dec 2021	71.7	44.7	78.8	22.0
Jan 2022	25.3	39.2	27.2	34.0
Feb 2022	4	28.9	4	39.0
Mar 2022	15.3	26.6	6.6	19.0
Apr 2022	8.9	28.2	2	0.0
May 2022	24.9	42.7	0	0.0
Jun 2022	53.5	55.8	0	0.0
Jul 2022	22	36.2	0	0.0
Aug 2022	6	27.0	0	0.0
<b>Total</b>	<b>326.3</b>	<b>431.6</b>	<b>125.5</b>	<b>120</b>

**Figure 3.1 Monthly Total Precipitation at Sullivan Mine 2021-2022 Compared to Normals from Kimberley PCC Station**



The precipitation data collected for the water balance is for the ARD Pond and its surrounding catchment. All water collected in the mine and tailings areas is pumped to the ARD Pond, and these flows are measured and recorded by Teck.

### 3.2.2 Evaporation

Monthly lake evaporation data at the tailings area for the reporting period was estimated using the WREVAP model by SRK (2014). The WREVAP model uses the dew point temperature, average temperature, and global solar radiation to estimate the lake evaporation. The mean monthly lake evaporation depths modelled for data collected at Kimberley A station is shown in Table 3.2.

**Table 3.2 Mean Monthly Evapotranspiration Rates at Kimberley A Station**

Month	Mean Evaporation (mm)
September	65
October	30
November	5
December	0
January	0
February	4
March	36
April	71
May	117
June	135
July	163
August	130
<b>Total</b>	<b>756</b>

### 3.3 Water Levels in ARD Pond and Iron Pond

The two key water storage ponds at the tailings area are the ARD Pond and Iron Pond. The area-volume curves and measured water elevations for these ponds are provided in the following sections.

#### 3.3.1 Area-Volume Curves

##### ARD Pond

The ARD Pond is formed by the South and North Dams built in 2001. The dam crest elevation is at El. 1048.0 m and the pond's spillway crest elevation is at 1047.4 m. Flood discharges from the ARD Pond spillway reports to the Iron Pond. The Maximum Operating Level (MOL) for the pond is set at El. 1046.5 m (KCC, 2000). Figure XII.1 shows the pond area-volume curve used for the water balance assessment. Based on that curve, the pond surface area is approximately 10 ha and its storage volume is approximately 710 dam<sup>3</sup> at MOL.

## Iron Pond


During normal operation, surface runoff from the Iron TSF and the upstream area is collected in the Iron Pond where it is then pumped to the ARD Pond or directly to the DWTP. In addition, the Iron Pond also provides emergency storage when the capacity of the ARD Pond is exceeded. The LiDAR survey from 2012, provided by Teck, shows the elevation of the top of the embankment to be at 1042.0 m and the elevation of the emergency spillway crest at 1041.0 m, which is consistent with the original design. The stage-storage curve (KCB 2007) for the pond is shown on Figure XII.2 and indicates that the storage capacity of the Iron Pond at the emergency spillway crest elevation of 1041.0 m is about 380 dam<sup>3</sup>.

### 3.3.2 Pond Water Levels

#### ARD Pond

Figure 3.2 shows the water levels measured by Teck in the ARD Pond from September 2021 to August 2022. The pond level was recorded daily.

**Figure 3.2 ARD Pond Level 2021 – 2022**




Based on the pond water levels, the maximum level observed during the reporting period was El. 1043.6 m, which occurred on March 16, 2022. This is 2.9 m lower than the maximum operating level (MOL) and is 3.8 m below the spillway crest elevation. There was no water discharged from the ARD Pond spillway to the Iron Pond during the water balance reporting period. The spillway has never discharged since the ARD pond was constructed.

## Iron Pond

Figure 3.3 shows the measured water levels by Teck in the Iron Pond from September 2021 to August 2022. The pond level was recorded daily.

Based on pond water levels, the maximum level observed during the reporting period was El. 1038.6 m around January 13, 2022, which is 2.4 m below the spillway invert elevation. There was no water discharged from the Iron Pond spillway during the water balance period, and records show that water has never been discharged to the spillway since it was constructed after mine closure.

**Figure 3.3 Iron Pond Level 2021 – 2022**



## 3.4 Tailings Area Water Balance


### 3.4.1 General

Teck manages and tracks the annual water balance for the Sullivan Mine. This section provides a review of the water balance for the current monitoring period from September 1, 2021 to August 31, 2022. The focus of the water balance is for the ARD Pond, as it is the central facility where all collected mine contact water is directed to for storage and then conveyed to the DWTP for treatment.

### 3.4.2 Water Balance Schematic

Figure 3.4 shows a schematic of the tailings area.

Figure 3.4 Tailings Area Water Balance Schematic





### 3.4.3 Inflows

As shown on Figure 3.4, inflows to the ARD Storage Pond include the following:

- Seepage from the Iron Pond, Gypsum TSF, and Siliceous TSF, which is collected in the West Gypsum Seepage Collection Pond and directed to the ARD Pond through Pumps 945 and 946.
- Discharge from the mine through the 3700 and 3900 Mine Lines. The 3700 line carries water from the underground mine to the ARD Storage Pond. The 3900 line collects water from the waste dumps, aquifer dewatering wells, and Sullivan Creek as well as pump 940, which collects seepage from the Old Iron TSF, and carries the water to the ARD Pond.
- Pumped flows from the Iron Pond.
- Direct precipitation on the ARD Storage Pond surface and runoff from the surrounding catchment.

Pump data noted above was provided by Teck, rainfall data was obtained from Environment Canada weather stations and runoff was estimated using runoff parameters for the surrounding catchment.

Precipitation and runoff are calculated for the ARD Pond only. All other inflows are captured as measured pump flows to the ARD Pond, which already include precipitation and runoff from all other tailings areas. The ARD Pond catchment area is 0.179 km<sup>2</sup> (SRK 2014), including the pond and its surrounding catchment. Precipitation and runoff inflows were estimated based on the precipitation depths presented in Table 3.1, and estimated pond and catchment areas, which vary by pond level. The following inputs and assumptions were used for the precipitation and runoff estimates:

- monthly yield coefficients ranging from 0.15 to 0.30, as estimated by SRK (2014);
- precipitation accumulated as snow November through March; and
- 100% of accumulated snow melted in March, based on the snowpack data shown in Table 3.1.

### 3.4.4 Outflows

Outflows from the ARD Storage Pond include the following:

- Seepage through the South Dam (Weir #1 ARDWU), reporting to the West Gypsum Seepage Collection Pond. The weir also collects runoff from the dam face and upstream area.
- Water pumped from the ARD Pond to the DWTP.
- Evaporation from the pond surface.

Water is pumped from the ARD Pond to the DWTP through pumps 947/948/949/950/952. The water is treated and then released to the St. Mary River.

Evaporation losses from the ARD Pond were estimated by multiplying the monthly evaporation depth shown in Table 3.2 by the estimated water surface area of the pond based on the measured pond elevation. Evaporation losses from other areas are reflected in the measured pump flows.

### 3.4.5 Water Balance Summary

A summary of the estimated monthly inflow and outflow volumes for the ARD Pond is provided in Table 3.3. The water storage in the ARD Storage Pond is calculated monthly based on the inflows and outflows and compared to the observed storage (calculated from the measured water elevation and stage-elevation curve), as summarized in Table 3.3. These volumes are based on the original capacity of the pond, so the accumulation of solids in the pond means that the actual water volume is somewhat less than the table indicates but recent bathymetry indicate that accumulated sediment is minimal and will not have a significant impact on the storage volume.

Agreement between the observed and calculated storage is variable on a monthly basis. The difference between the observed and calculated year-end storage volumes amounts to 17% of the annual inflow to the pond.

The calculated annual difference of 17% over the current monitoring period is slightly greater than the calculated annual difference of 14% for the previous monitoring period.

**Table 3.3 ARD Pond Monthly Water Balance Summary**

Description	Units	Sep 2021	Oct 2021	Nov 2021	Dec 2021	Jan 2022	Feb 2022	Mar 2022	Apr 2022	May 2022	Jun 2022	Jul 2022	Aug 2022	Sept. 2021– Aug. 2022
Beginning Water Level	(m)	1040.09	1038.78	1037.66	1039.43	1040.96	1042.17	1043.06	1042.05	1040.39	1039.47	1039.43	1041.02	1040.71
Beginning Storage	(dam <sup>3</sup> )	189.90	117.56	66.11	152.12	245.25	330.76	399.51	321.03	208.64	154.26	151.93	248.88	228.81
<b>Inflow:</b>														
Pump 905/906/907/908	(dam <sup>3</sup> )	0.0	0.0	0.0	0.0	0.0	0.4	13.5	11.4	10.8	0.0	0.0	0.0	36.1
Pump 945 / 946	(dam <sup>3</sup> )	33.9	35.8	40.4	41.2	42.1	39.3	107.2	62.9	50.5	46.0	37.6	37.6	574.6
Mine Line 3700	(dam <sup>3</sup> )	177.8	80.4	0.0	0.0	0.0	0.0	0.0	169.1	173.9	16.3	0.0	0.0	617.5
Mine Line 3900	(dam <sup>3</sup> )	61.3	60.3	59.4	68.6	59.8	50.1	63.0	91.1	115.8	116.6	90.3	90.3	926.7
Precipitation and Runoff	(dam <sup>3</sup> )	1.8	2.0	2.6	5.1	2.0	0.3	20.8	0.7	1.8	4.2	1.8	1.8	45.0
<b>Total Inflow</b>	<b>(dam<sup>3</sup>)</b>	<b>274.8</b>	<b>178.5</b>	<b>102.4</b>	<b>114.9</b>	<b>103.9</b>	<b>90.1</b>	<b>204.6</b>	<b>335.2</b>	<b>352.9</b>	<b>183.1</b>	<b>129.7</b>	<b>129.7</b>	<b>2199.8</b>
<b>Outflow:</b>														
Pump 947/948/949/950/952	(dam <sup>3</sup> )	307.6	211.6	0.0	0.0	0.0	0.0	230.5	483.4	385.7	159.7	0.0	0.0	1778.4
Weir 1 ARDWU	(dam <sup>3</sup> )	Negligible												
Evaporation	(dam <sup>3</sup> )	3.0	1.4	0.3	0.0	0.0	0.3	2.5	4.2	6.5	8.2	10.7	10.7	47.8
<b>Total Outflow</b>	<b>(dam<sup>3</sup>)</b>	<b>310.6</b>	<b>213.0</b>	<b>0.3</b>	<b>0.0</b>	<b>0.0</b>	<b>0.3</b>	<b>233.0</b>	<b>487.6</b>	<b>392.2</b>	<b>168.0</b>	<b>10.7</b>	<b>10.7</b>	<b>1826.6</b>
Calculated Net Change in Storage	(dam <sup>3</sup> )	-35.7	-34.5	102.0	114.8	103.8	89.8	-28.5	-152.4	-39.3	15.2	119.0	119.0	373.2
Calculated Month-End Storage	(dam <sup>3</sup> )	154.2	83.0	168.2	267.0	349.1	420.6	371.0	168.6	169.3	169.4	270.9	367.9	602.0
Observed Month-End Storage	(dam <sup>3</sup> )	117.6	66.1	152.1	245.3	330.8	399.5	321.0	208.6	154.3	151.9	248.9	230.6	230.6

### 3.5 Flood Management

Reclamation work on the tailings areas commenced in 1990 and continued after mine closure in 2001 until it was completed in 2008. The reclamation work primarily comprised the development and construction of a multi-layer soil cover system of float rock and till over the tailings areas. A summary of the flood management structures and applicable design criteria is presented below.

- Surface water collection/diversion channels and spillways have been designed and constructed in the tailings areas for flood management. The main channels and spillways are Dobson's Draw diversion, Siliceous Spillway and outlet channel, ARD Pond spillway, Channel C within the Iron Pond and the Iron Pond emergency spillway. They are designed to safely pass the Probable Maximum Flood (PMF) events. The channels are riprap lined and the spillways include stilling basins.
- As previously indicated, the Iron Pond is intended to provide storage of mine contact surface water during spring runoff events. The Iron Pond is designed to store the 100-year snowmelt event above the maximum operating level and controlled release of the 1000-year snowmelt event has also been provided for, if it cannot be stored. If the pond level at the start of the snowmelt event was below the maximum operating level then a larger than 100-year snowmelt event could be stored before discharge via the emergency spillway. The emergency spillway for the Iron Pond is designed to safely pass the PMF. Key characteristics of the Iron Pond are provided in Section 3.6.1.
- As previously indicated, the ARD Pond is the central water storage facility where all collected contaminated/contact water is directed to for storage and then subsequently conveyed to the DWTP for treatment. The ARD Pond has been designed to store the 48-hour PMF and also includes a spillway designed to safely pass a 24 hr PMF (after the 48-hour PMF has been stored). Note that, in essence, the ARD Pond is capable of safely handling two 48-Hr PMFs occurring in succession. Key characteristics of the ARD Pond are provided in Section 3.6.2.

It should be highlighted that the 24-Hr PMF, which was selected as the Inflow Design Flood (IDF) for the Sullivan Mine tailings facilities, exceeds the minimum criteria for their respective consequence classifications, as specified in CDA (2013, 2014) and EMLCI (2017). Teck has elected to adopt higher IDF values within the framework of continual risk reduction.

### 3.6 Freeboard and Storage – Water Storage Ponds

#### 3.6.1 Iron Pond

The maximum operating level of the Iron Pond is El. 1038.9 m. The stage-storage curve of the pond is shown on Figure XII.2, and its key design and performance characteristics are provided in Table 3.4.

**Table 3.4 Relevant Iron Pond Characteristics**

Item	Value
Top of the Dike Elevation (m)	1042.0
Spillway Crest Elevation (m)	1041.0
Maximum Operating Level (m)	1038.9
Storage Capacity at the MOL (dam <sup>3</sup> )	76.9
Designed Storage Capacity up to the Spillway (dam <sup>3</sup> )	614.2
Minimum Water Level in 2021-2022 (m)	1037.0
Maximum Water Level in 2021-2022 (m)	1038.6
Maximum Storage in 2021-2022 (dam <sup>3</sup> )	46.3
Minimum Available Capacity Below MOL 2020-2021 (dam <sup>3</sup> )	30.7

As previously discussed in Section 3.3.2, and shown on Figure 3.3, the maximum water level elevation recorded in the Iron Pond over this monitoring period was 1038.6 m, which is 2.4 m below the emergency spillway crest elevation and 3.4 m below the minimum Iron Dike crest elevation.

### 3.6.2 ARD Pond

The maximum operating level of the ARD Pond is set at El. 1046.5 m, which is 0.9 m lower than the spillway invert (El. 1047.4 m). It allows for a flood storage depth of 0.8 m for a 48-hour Probable Maximum Flood (PMF) plus 0.1 m freeboard to the spillway invert. The elevation of the top of the dam is set at 1048.0 m, providing a vertical distance of 0.6 m above the spillway invert. This vertical distance allows for a 0.3 m surcharge above the spillway crest and a dam freeboard of 0.3 m (KCB 2018) when routing the IDF (PMF) through the spillway to the Iron Pond.

The stage-storage curve of the pond is shown on Figure XII.1, and its key design and performance characteristics are provided in Table 3.5.

**Table 3.5 Relevant ARD Pond Characteristics**

Item	Value
Top of Dam Elevation (m)	1048.0
Spillway Crest Elevation (m)	1047.4
Maximum Operating Level (m)	1046.5
Storage Capacity at the MOL (dam <sup>3</sup> )	710.7
Designed Storage Capacity for PMF (dam <sup>3</sup> )	50.0
Designed Freeboard for PMF (m)	0.3
Minimum Water Level in 2021-2022 (m)	1036.6
Maximum Water Level in 2021-2022 (m)	1043.6
Maximum Storage in 2021-2022 (dam <sup>3</sup> )	442.5
Minimum Available Capacity Below MOL 2021-2022 (dam <sup>3</sup> )	268.2

As previously discussed in Section 3.3.2, and shown on Figure 3.2, the maximum water level elevation recorded in the ARD Pond over this monitoring period was 1043.6 m, which is 3.8 m below the spillway crest elevation and 4.4 m below the dam crest elevation.

### 3.7 Off-Site Surface Water Discharge Volumes

There were no off-site water discharges from the ARD Pond and Iron Pond spillways during the reporting period. These spillways have not operated since they were constructed (in 2001 for the ARD Pond spillway, and in 2007 with modifications in 2009 for the Iron Pond emergency spillway).

The only discharge to the environment is treated effluent water from the DWTP, which enters the St. Mary River. Table 3.6 provides a summary of the monthly discharge volumes, as provided by Teck. As shown, the total water discharge volume from the DWTP between September 2021 and August 2022 was 1876 dam<sup>3</sup>.

**Table 3.6 Summary of Treated Water Discharge to St. Mary River**

Month	Total Volume (dam <sup>3</sup> )	Average Discharge per Day (dam <sup>3</sup> )
Sep 2021	307.58	10.25
Oct 2021	211.57	6.82
Mar 2022	230.54	7.44
Apr 2022	483.42	16.11
May 2022	385.66	12.44
June 2022	159.69	5.32
August 2022	97.72	3.15
<b>Total</b>	<b>1876.17</b>	

The average daily discharge volumes over this monitoring period were less than the maximum daily limit of 28 dam<sup>3</sup> as compliant with the permit PE-00189.

### 3.8 Water Discharge Quality

Water discharge quality is not included in the scope of this report. Teck separately reports groundwater quality and discharge water quality to the BC Ministry of Environment as specified in Permit PE-00189.

## 4 SITE OBSERVATIONS AND INSTRUMENTATION REVIEW

### 4.1 Visual Observations

The on-site inspection of the embankments was carried out by Ms. Pamela Fines, P.Eng. (Engineer of Record) and Ms. Makayla Rettger, EIT. (SK) of KCB from May 25 to May 26, 2022. The weather during the inspection was cool with mostly clear skies. The 2022 Inspection Checklists that were completed for each embankment are included in Appendix I. A summary of the visual observations of each embankment is below.

Selected photographs of the various embankments taken during the site visit are presented in Appendix II and are referenced throughout this report. Appendix II has been subdivided so as to group the photographs according to the facilities, as follows:

- |   |       |
|---|-------|
| ▪ ARD Pond, ARD Spillway, Weirs 1 and 2                 | II-1  |
| ▪ Iron TSF, Iron Pond, Emergency Spillway, Weir 3 and 4 | II-9  |
| ▪ Siliceous TSF, Siliceous Spillway, Siliceous Decants  | II-21 |
| ▪ Gypsum TSF,   | II-28 |
| ▪ Sludge Impoundment                                    | II-32 |
| ▪ Calcine TSF   | II-35 |
| ▪ Old Iron TSF, Iron TSF Divider Dike                   | II-36 |

#### 4.1.1 ARD Pond

The visual inspection indicated that the North and South Dam were in good physical condition with no signs of structural distress. The riprap on the upstream side of both dams was in good condition with no evidence of movements or damage (Photo II.1 and II.2). It was noted that there is sporadic vegetation growth on the upstream face of both dams but is not a dam safety concern and should be managed as part of the ongoing vegetation management program on site. Several large pieces of wood were observed on the upstream slope of the North Dam, the debris is not a dam safety concern but should be removed as part of good practice to prevent them from possibly blocking the spillway during a flood event.

An area of surface erosion was observed below an outlet pipe adjacent to the pumphouse located near the South Dam of the ARD Pond (Photo II.3). This area should be monitored and repaired if it begins to encroach on the pumphouse. This is not a dam safety concern but the pumphouse is an integral part of site water management.

The downstream slope of the North Dam appeared to be in similar condition to the previous years. The slope is well grassed with no significant patches of bare or loose soil observed (Photo II.4). Localized depressions/steepened slopes along the toe of the North Dam have been noted during the annual inspections. These areas were purposely constructed by locally excavating into the dam slope to manage seepage exiting from the dam. Seepage collects in the toe ditch and flows to the seepage

pond at the west end of the dam. Vegetation clearing was completed before the 2022 inspection and the slope and toe area were easier to observe (Photo II.5).

The downstream slope of the South Dam appeared to be in similar condition to previous annual inspections (Photo II.6). The slope is well grassed with no significant patches of bare or loose soil observed.

The ditch south of the South Dam that feeds into Weir #1 and Weir #2 is heavily vegetated with grass and other plants, which may impede flow (Photo II.7). Teck has done significant work at all the weirs to reduce the amount of water bypassing the weirs, the low permeability cut-off material can be seen in Photo II.7. The ditches should be cleaned as part of the vegetation management program documented in the OMS manual.

#### **4.1.2 Iron TSF and Iron Dike**

The visual inspection indicated that the Iron Dike was in good physical condition with no signs of structural distress. No cracking or other unusual physical conditions were noted along the crest or downstream slopes. Dike slopes and crest were grassed with no significant areas observed with bare or loose soil (Photos II.9).

Seepage continued similarly to previous years at the downstream toe of the embankment near station 5+00. Seepage is monitored by two weirs (Weir #3 and Weir #4) installed within the drainage ditch (Photos II.13 through II.16). The notch in the weir plate in Weir #4 has become worn and should be replaced or repaired (Photo II.16). Seepage was also occurring near the downstream toe of the dike near station 24+00 and is being collected in the existing ditch and low-lying area, this seepage should continue to be monitored visually as part of routine inspections and collection of weir flow data.

The visual inspection of the Iron Pond (contained within the Iron TSF) indicated that it was in good condition.

The Emergency Spillway Channel extends from the southwest corner of Iron TSF and down the west side of the West Gypsum TSF. The visual inspection indicated the spillway was in good physical condition (Photos II.17 through II.20). Some grass, shrubs, and other vegetation were present in the lower portion of the spillway near the southwest corner of the West Gypsum TSF and the 951 Pump House. The rip rap appeared to be in good condition with no signs of movement or particle breakdown. Vegetation clearing in the spillway should be completed as part of the ongoing vegetation management program documented in the OMS manual.

#### **4.1.3 No. 1, 2, and 3 Siliceous TSFs**

The visual inspection indicated that the No. 1, 2, and 3 Siliceous Dikes were in good physical condition with no signs of structural distress (Photos II.21 through II.25). Seepage of variable amounts generally occurs from the toes of all Siliceous Dikes during the spring from runoff due to snowmelt water infiltration through the cover system. This seepage occurred during operations and has continued but at much lower rates after mine closure. The observed seepage conditions appeared to be similar to



those observed in previous annual inspections. The seepage water is collected by drainage ditches. Inspection of seepage locations along the Siliceous dikes is performed by Teck on a regular basis. Signs of surface seepage emerging from the downstream slopes of the embankments were not evident during KCB's site visit.

A small trickle of flow was observed from the historical drain pipe installed into the No. 3 Siliceous Dike (Photo II.25). It is KCB's understanding that flow is relatively constant through these pipes during the entire year. A decant installed in 2000 within the No. 2 Siliceous Dike was dry and generally only sees flow during freshet. Flow from both decants are monitored and recorded as part of the regular inspections by Teck and KCB as noted in the OMS manual. Any changes in flow rate or sediment in the flow should be reported to KCB.

The surface water runoff conveyance channel from No. 1 Siliceous Cell across No. 3 Siliceous Cell, the diversion channel to the north of No. 1 and No. 3 cells, and the emergency spillway channel constructed on the east slope of No. 3 Siliceous Dike were in good physical condition at the time of the site visit with no sign of movement or particle breakdown (Photo II.26 and II.27). The upper portion of the spillway across the No. 3 Siliceous cell is heavily grassed.

#### **4.1.4 East and West Gypsum TSFs**

The visual inspection indicated that the East Gypsum Dike was in good physical condition with no signs of structural distress (Photo II.28). Embankment slopes were well-grassed with no significant areas of bare or loose soil observed. Several large rodent burrows were observed along the dam slopes and toe but are not considered to be a dam safety issue. However, the burrows are safety hazard to personnel walking along the dam toe and slope. Rodent burrows should be infilled as they're identified. No seepage was observed in the ditch at the toe of the embankment.

The visual inspection indicated that the West Gypsum Dike was in good physical condition with no signs of structural distress. Embankment slopes were well-grassed with no significant areas of bare or loose soil observed (Photo II.29). Animal burrows were observed near the embankment toe. These burrows are not a dam safety issue; however, the burrows are safety hazard to personnel walking along the dam toe and slope. Rodent burrows should be infilled as they're identified.

#### **4.1.5 Northeast Gypsum Dike and Recycle Dam**

The visual inspection indicated that the Northeast Gypsum Dike and the Recycle Dam were in good physical condition with no signs of structural distress. The slopes of both embankments were well grassed (Photos II.30 and II.31). Animal tracks were observed along the downstream slope of the Northeast Gypsum Dike and don't appear to have changed significantly since being observed during last year's inspection.

#### **4.1.6 Sludge Impoundment**

Both the North and South Dikes of the Sludge Impoundment were observed to be in good physical condition during the inspection. The sludge level in the impoundment adjacent to the North Dike is

nearing the design levels of approximately one metre below the crest elevation; deposited sludge is approximately 2.0 m below the crest elevation at the South Dike.

Vegetation is becoming established on both dams (Photo II.32 through II.34) and should be removed as part of the vegetation management program documented in the OMS manual. Vegetation management should include clearing of any slash piles created from past clearing activities at the sludge impoundment.

#### **4.1.7 Calcine TSF**

The visual inspection indicated that the Calcine Dike was in good physical condition with no signs of structural distress (Photo II.35). The downstream slope of the embankment is sporadically vegetated and is buttressed by a municipal landfill.

The old beach surface is at crest level upstream of the dike and gently slopes downward towards the north (upstream). There was no free water observed during the inspection and vegetation has become established over the entire impoundment. Calcine removal from a pit developed at the northwest side of the lower cell ceased in 2011/2012 and this area was reclaimed. The pit is well drained and no standing water was observed.

#### **4.1.8 Old Iron TSF**

The visual inspection indicated that the Old Iron Dike and Iron TSF Divider Dike were in good physical condition with no signs of structural distress. The downstream slope of the Old Iron Dike was grassed with no significant areas of bare or loose soil (Photo II.37 and II.8). There were no signs of seepage. The Iron TSF Divider Dike is buttressed by the Iron TSF and is currently being used as an access road between the two TSFs (Photo II.39). No physical changes were observed from the previous annual inspection. The Iron TSF Divider Dike is buttressed on both sides with tailings.

### **4.2 Instrumentation Data Review**

Based on the review of the instrumentation data and observations from the site inspection of May 25 and 26, 2022, there were no dam safety concerns identified. The current monitoring schedule for all instruments will be generally unchanged for the 2023 monitoring period. The monitoring frequencies are summarized in Table 4.1 and are detailed for each item in Appendix III. Additional readings may be requested as required depending on trends observed during the 2023 reporting period. Based on the TSFs performance to date, the piezometers and reading frequency are considered sufficient for ongoing monitoring of the facility under current conditions (KCB 2022a).

**Table 4.1 Monitoring Frequencies for 2022 Reporting Period**

Embankment		Monitoring Frequency (3x = three times per year, 3y = every 3 years, A = annually, AV = annual visual, M = monthly, W = weekly) Consult notes for conditional changes and special regimes.				
		Piezometers	Settlement	Inclinometers	Seepage <sup>(8)</sup>	Water Levels
Iron TSF	Iron Dike	3x <sup>(1)</sup>	A + 3y <sup>(5)</sup>	-	W <sup>(7)</sup>	Daily
Old Iron TSF	Old Iron Dike	3x <sup>(2)</sup>	-	-	-	-
	Iron TSF Divider Dike	A <sup>(3)</sup>	-	-	-	-
Siliceous TSF	No. 1, 2, and 3 Dikes	A	-	-	-	-
Gypsum TSF	West Gypsum Dike	3x <sup>(2)</sup>	A + 3y <sup>(6)</sup>	-	AV	-
	East Gypsum Dike	A	A + 3y <sup>(6)</sup>	3y	AV	-
	Northeast Gypsum Dike and Recycle Dam	-	3y	-	-	-
ARD Pond	North Dam	M <sup>(4)</sup>	3y	-	-	Daily
	South Dam	M <sup>(4)</sup>	3y	-	W <sup>(7)</sup>	Daily
Sludge Impoundment	North Dike	-	A	-	-	-
	South Dike	-	A	-	-	-

**Notes:**

- <sup>1</sup> Three times per year (spring, summer, and fall) except P92-H which is recorded weekly by a datalogger and P92-02 and P92-25 which are read monthly.
- <sup>2</sup> Three times per year (spring, summer, and fall).
- <sup>3</sup> Annually in the spring if possible, to capture peak level.
- <sup>4</sup> Read pneumatic piezometers weekly when pond is above 1045 m. Read standpipe piezometers weekly when ARD pond is about 1040 m and daily when ARD pond is about 1045 m.
- <sup>5</sup> Survey of Iron Dike from Station 0+00 to 12+00 to be completed annually.
- <sup>6</sup> Settlement plates to be surveyed annually, Sondex gauge to be read every three years.
- <sup>7</sup> Weirs measured daily between March 1 and May 30. Read daily for three days following rainfall event > 10 mm in 24 hours.
- <sup>8</sup> Record pond levels when weirs read. When reading weirs, provide visual observations of ditch flows, e.g. ice build-up, flows around or under weir, etc.

Quantifiable Performance Objectives (QPOs) have been established in terms of notification levels for the instrumentation installed within the embankments and notification levels relative to pond water elevations and corresponding freeboard for the ARD Pond and the Iron Pond. In addition, a checklist of qualitative indicators (e.g., observation of cracking, slumping, erosion, etc.) for routine visual inspections, event-driven visual inspections, and annual visual inspections have been developed. Additional details, including summary tables of instrumentation data and corresponding notification levels, are provided in Appendix III.

It is important to emphasize that the current notification levels for the available instruments, including piezometers, seepage weirs, settlement systems, and inclinometer casings, are not associated with any dam safety concerns. Rather, they are based on historical trends of reading in a particular instrument with the objective of highlighting readings that could be indicative of a potential change from historical norms in order to prompt a closer review as a matter of due

diligence. The specified notification levels are well below the assumed levels for stability assessments.

Teck contracts instrument reading and monitoring data collecting to Vast Resource Solutions (Vast), who provide the raw data for upload to GeoExplorer. Monitoring is also completed by Teck personnel.

#### 4.2.1 Iron TSF

The locations of the existing instruments at the Iron Dike are shown on Figure 5. Typical sections showing geometry and pore pressure response are shown on Figures 6 and 7.

##### Piezometric Levels

Time plots of the piezometric readings received from Vast are presented on Figures IV-1 through IV-10 in Appendix IV. Peak values recorded over this period are reported in Table III-3.

The Iron Dike piezometer readings remained below notification levels and are well below the assumed levels for stability assessments.

##### Settlements

The most recent survey of settlement plates and embankment crest was carried out by Teck in October 2021. Teck is transitioning to InSAR for tracking of movements for the Legacy Facilities and recently ran a historical assessment using available data from 2018 through 2022. Data for Sullivan shows minimal settlement over the past 3 years for the Iron TSF.

##### Seepage Flows

Two weirs (Weir #3 and Weir #4) exist to monitor seepage from the toe of the west portion of the Iron Dike. Weir #3 is located near the toe of the embankment and Weir #4 is located 300 m downstream.

Weir #3 measured peak flows of 25.9 m<sup>3</sup>/day in November 2021. The flow data indicates minimum flows through the weir of 0.0 m<sup>3</sup>/day to 0.93 m<sup>3</sup>/day. Historical data for Weir #3 is presented in Figure IV- 11.

Weir #4 flow data shows a peak flow of 333.6 m<sup>3</sup>/day in March 2022. Minimum flows varied from 1.7 m<sup>3</sup>/day to 26.2 m<sup>3</sup>/day. Historic data for Weir #4 is presented in Figure IV-11. It should be noted that this weir is approximately 300 m downstream from the embankment toe and flow measurements will include surface runoff from surrounding terrain as well as seepage flows.

The weirs are read at a minimum monthly, with daily or weekly readings performed during periods of higher flows and/or when the ARD Pond elevations is above 1145 m. Additional readings occur following heavy rainfall events.

#### 4.2.2 Old Iron TSF

The locations of existing instruments at the Old Iron TSF (Old Iron Dike and Iron TSF Divider Dike) are shown on Figure 8. A typical section showing geometry is shown on Figure 9.

##### Piezometric Levels

Time plots of the piezometric readings received from Vast are presented on Figures V-1 through V-4 in Appendix IV. Peak values recorded over this period are reported in Table III-4.

All of the existing piezometers at the Old Iron TSF (9 of 9) were below the notification level for the monitoring period.

#### 4.2.3 Siliceous TSF

The location of existing instruments on the Siliceous TSF are shown on Figure 10. Typical sections are shown on Figures 11 and 12.

##### Piezometric Levels

Plots of the piezometer readings for Siliceous TSF are shown on Figures VI-1 through VI-6. Peak values recorded over this period are reported in Table III-5.

##### *No. 1 Siliceous Dike*

The piezometers at No. 1 Siliceous Dike (4 of 4) recorded slight increases or stable peak pore water pressures compared to the previous monitoring period and were below the notification level for the monitoring period. P105, a standpipe piezometer installed in the embankment adjacent to No. 3 Cell, has been reading near or above its notification level for several years including after an attempted flush in 2014. It is suspected that the piezometer may be plugged internally.

##### *No. 2 Siliceous Dike*

All of the existing piezometers at No. 2 Siliceous Dike (3 of 3) recorded reduced peak pore water pressures compared to the previous monitoring period and were below the notification level for the monitoring period.

An existing pneumatic piezometer downstream of No. 2 Siliceous Dike and along Betcher's Slough is now monitored by Teck. This monitoring is not reported to KCB but if a significant change in flow rate or cloudy flow is observed KCB should be notified to determine if any action needs to be taken.

##### *No. 3 Siliceous Dike*

All but one of the existing piezometers at No. 3 Siliceous Dike (12 of 13) recorded stable or reduced peak pore water pressures compared to the previous monitoring period and were below the notification level for the monitoring period. The remaining piezometer showed a slight increase in peak pore water pressure compared to the previous monitoring period, and remains below the notification level.

## Seepage Flows

There are currently no flow measuring capabilities in the area of the Siliceous TSFs. During the site inspection, we inspected both the shallow decant and historical decant.

### 4.2.4 East and West Gypsum TSFs

The location of existing instruments on the Gypsum TSFs are shown on Figures 13, 16, and 18. Typical sections are shown on Figures 14, 15, 17, and 19

## Piezometric Levels

Plots of the piezometer readings for Gypsum TSFs are shown on Figures VII-2 and VII-3 for West Gypsum Dike and Figures VIII-1 through VII-3 for East Gypsum Dike. Peak values recorded over this period are reported in Table III-6.

### *West Gypsum Dike*

All of the existing piezometers at West Gypsum Dike (7 of 7) recorded reduced peak pore water pressures compared to the previous monitoring period and all were below the notification level during the monitoring period.

### *East Gypsum Dike*

All of the existing piezometers at East Gypsum Dike (8 of 8) recorded stable or reduced peak pore water pressures compared to the previous monitoring period and were below the notification level during the monitoring period.

### *Northeast Gypsum Dike and Recycle Dam*

Standpipe piezometers in the Northeast Gypsum Dike and Recycle dam have not been monitored since 2004. Piezometric levels consistently matched pond elevations and were not providing information to assess embankment performance. The Dike/Dam have a long history of good performance, relatively low heights, and any impacts in the unlikely event of a failure would be wholly contained within the impoundment area; ongoing monitoring of the piezometric levels was considered unnecessary.

## Settlement

### *West Gypsum Dike*

The most recent survey of settlement plates and embankment crest was carried out by Teck in October 2021. Teck is transitioning to InSAR for tracking of movements for the Legacy Facilities and recently ran a historical assessment using available data from 2018 through 2022. InSAR data for the facility shows in the range of 3 mm per year of settlement within the Gypsum TSF.

Consolidation of the West Gypsum Cell tailings is monitored with a Sondex settlement gauge, S97-01, installed about 50 m upstream of the crest at Station 10+00 (Figure VII-1). A reading of the Sondex

gauge was taken during the 2019 DSI. The Sondex gauge has recorded total consolidation settlement of about 1.7 m since 1994. This is within the expected settlement for the facility. As indicated in KCB's report Stability Review of Gypsum Dikes dated November 26, 1993, long term creep is a common characteristic of gypsum. Continued consolidation of the gypsum tailings is not considered a dam safety concern. Regular crest surveys are conducted to confirm that the dam crest remains at or above the design elevation. The Sondex gauge is no longer readable as the manufacturer has discontinued support of this equipment. Long term settlement will now be tracked using InSAR data.

### *East Gypsum Dike*

The most recent survey of settlement plates and embankment crest was carried out by Teck in October 2021. Teck is transitioning to InSAR for tracking of movements for the Legacy Facilities and recently ran a historical assessment using available data from 2018 through 2022. InSAR data for the facility shows in the range of 3 mm per year of settlement within the Gypsum TSF.

Consolidation of the East Gypsum Cell tailings is monitored with a Sondex settlement gauge, S94-02, installed about 25 m upstream of the crest at Station 33+00 (Figure VIII-1). A reading of the Sondex gauge was taken during the 2019 DSI. The Sondex gauge has recorded total consolidation settlement of about 1.0 m since 1994. This is within expected settlement for the facility. As indicated in KCB's report Stability Review of Gypsum Dikes dated November 26, 1993, long term creep is a common characteristic in gypsum. Continued consolidation of the gypsum tailings is to be expected and is not considered a dam safety concern. Regular crest surveys are conducted to confirm that the dam crest remains at or above the design elevation. The Sondex gauge is no longer readable as the manufacturer has discontinued support of this equipment. Long term settlement will now be tracked using InSAR data.

### *Northeast Gypsum Dike and Recycle Dam*

The most recent survey of settlement plates and embankment crest was carried out by Teck in October 2021. Teck is transitioning to InSAR for tracking of movements for the Legacy Facilities and recently ran a historical assessment using available data from 2018 through 2022.. InSAR data shows minimal settlement in the past 3 years.

Past surveys, presented in Appendix IX, indicated negligible settlements since 2007.

## **4.2.5 ARD Pond**

The location of existing instruments on the ARD Pond Dams are shown on Figure 20. Typical sections are shown on Figures 21 through 24.

### **Piezometric Levels**

Historic data for the piezometers installed in ARD North and South Dams is shown on Figures X-1 through X-4.

### *North Dam*

All of the existing piezometers at ARD North Dam (8 of 8) recorded slight increases or stable peak pore water pressures compared to the previous monitoring period. All were below the notification level during the monitoring period.

### *South Dam*

All of the existing piezometers at ARD South Dam (5 of 5) recorded stable or slightly increased pore water pressures compared to the previous monitoring period. PP01-05 and PP01-06 were briefly above the notification level for the instruments for the 2022 max reading. The current notification level is based on historic readings only and this is not a dam safety concern. The instrument should continue to be monitored as per the schedule in Appendix III, Table III-7. The new instruments installed in 2020 are being monitored by an automated collection system. There are no previous records to compare maximum pore water pressures to previous monitoring periods.

## **Settlement**

### *South Dam*

The most recent survey of settlement plates and embankment crest was carried out by Teck in October 2021. Teck is transitioning to InSAR for tracking of movements for the Legacy Facilities and recently ran a historical assessment using available data from 2018 through 2022.. InSAR data shows minimal movement over the past 3 years.

Past data, included in Figure X-7, shows no notable settlement since 2001 and less than 25 mm of lateral movement since the end of construction.

### *North Dam*

The most recent survey of settlement plates and embankment crest was carried out by Teck in October 2021. Teck is transitioning to InSAR for tracking of movements for the Legacy Facilities and recently ran a historical assessment using available data from 2018 through 2022.

Past data, included in Figure X-8, shows less than 20 mm of settlement since 2001 and less than 25 mm of lateral movement since the end of construction.

## **Seepage Flows**

Two weirs (Weir #1 and Weir #2) exist to monitor seepage from the toe of the ARD South Dam. Weir #1 is located near the toe of the Dam and Weir #2 is located approximately 50 m downstream.

Weir #1 measured peak flows of 54.9 m<sup>3</sup>/day in March 2022. The flow data indicates minimum flows through the weir of 0.1 m<sup>3</sup>/day to 13.1 m<sup>3</sup>/day. Historical data for Weir #1 is presented in Figure X-5.

Weir #2 flow data shows a peak flow of 79.5 m<sup>3</sup>/day in March 2022. Minimum flows varied from 0 m<sup>3</sup>/day to 12.7 m<sup>3</sup>/day. Historic data for Weir #2 is presented in Figure X-6. It should be noted that



this weir is approximately 50 m downstream from the embankment toe and flow measurements will include surface runoff from surrounding terrain as well as seepage flows.

#### **4.2.6 Calcine TSF**

A plan view of the Calcine Dike is shown on Figure 25. Typical sections showing geometry and pore pressure response are shown on Figure 26.

#### **Water Levels**

Three standpipe piezometers are located on the embankment crest, as shown on Figure 25. The piezometers were last read in 2004 and have been dry since 1986. Piezometer monitoring at the Calcine Dike ceased in 2007. Given that the pit (where calcine was previously excavated) at the northwest side of the lower cell has always been dry and the Calcine Dike is buttressed on its downstream slope by the existing municipal landfill, continued reading of these piezometers was considered unnecessary.

#### **4.2.7 Sludge Impoundment**

A plan view of the Sludge Impoundment is shown on Figure 27. Typical sections showing geometry are shown on Figures 28.

#### **Piezometric Levels**

There are no piezometers installed to monitor water levels in the Sludge Impoundment Dikes. Water deposited during sludge deposition or due to precipitation drains through the embankment (which contains a filter zone) or into the foundation. New instruments were installed in September 2021 and have been recording data since October 2021. There are no previous records to compare maximum pore water pressures to previous monitoring periods.

#### **Settlement**

In the previous annual inspection, 2019 LiDAR survey data was used to evaluate the embankment crest elevation compared to design elevation. Embankment crest elevation on the north and south dam was found to be above design elevation apart from the south side of the south dam briefly dipping below design. This was consistent with 2012 LiDAR data which indicates that there has been little to no settlement in the last 7 years. Teck is transitioning to InSAR for tracking of movements for the Legacy Facilities and recently ran a historical assessment using available data from 2018 through 2022 which confirms the limited settlement.

## 5 TAILINGS FACILITY ASSESSMENT

### 5.1 Failure Modes Review

KCB understands that Teck's long-term goal for all of their tailings facilities is, where physically possible, to reach landform status, with all potential failure modes that could result in catastrophic release of tailings and/or water being either not present or having been reduced to non-credible. Teck's long-term goal for the Sullivan facilities is for all potential failure modes to be non-credible, based on extreme loading conditions, or to manage the risk to ALARP (i.e., as low as reasonably practicable) using appropriate loading conditions when it is not practicable to address extreme loading conditions.

The Sullivan risk register was reviewed by KCB and Teck in May 2022. There were no changes to the key hazards and the existing controls were adequate to managed potential failure modes.

To supplement the risk review, Teck, with support from KCB, conducted a credible catastrophic failure mode assessment in April 2022. Teck's definition of a "catastrophic" failure is one with a risk to life safety or irreversible impact to a rare or valued ecosystem, social or cultural heritage element. The assessment concluded that, based on the available information and current understanding of the site, there are no credible "catastrophic" failure scenarios for the Sullivan tailings facilities.

The following is a summary of the controls in place at Sullivan Mine to manage the risks associated with the key failure modes for the facilities. The slope instability failure mode is considered credible (though non-catastrophic), while the internal erosion and overtopping failure modes are not credible for the current and historic loading conditions. Based on the observations above and the available information, Teck is managing the potential failure mechanisms for the TSFs appropriately.

#### 5.1.1 Overtopping

##### *Tailings Storage Facilities*

The tailings facilities are no longer active. The Iron TSF does maintain a pond that is actively managed. The Iron Pond operates along with the ARD Pond as part of the site wide water management activities.

As previously discussed in Section 3.5, surface water collection/diversion channels and spillways have been constructed in the tailings areas for flood management, which are designed to safely pass the Probable Maximum Flood (PMF) events. The likelihood of overtopping failures leading to catastrophic consequences up to and including Extreme consequence loading conditions are considered negligible, and therefore non-credible.

##### *ARD Pond*

The ARD Pond has been designed to store the 48-hour PMF and also includes a spillway designed to safely route a 24 hr PMF (after the 48-hour PMF has been stored) (see Section 3.5). Therefore, the likelihood of overtopping is considered negligible and a non-credible failure mode.

### *Sludge Impoundment*

According to Dames and Moore (1978), the 1:200-year return period flood event was adopted for design of the Sludge Impoundment. However, as the actual sludge production rate has been much lower than assumed in the original design by others, the impoundment currently has flood storage capacity in excess of design. While overtopping of the sludge impoundment is credible, the consequences of overtopping will not result in a catastrophic consequences. The sludge is fully drained and no pond is maintained during normal operations. There is no population downstream of the sludge pond within a potential inundation area.

#### **5.1.2 Internal Erosion and Piping**

##### *Tailings Storage Facilities*

The tailings storage facilities are no longer active, and since completion of the reclamation cover, the phreatic levels within the tailings have steadily decreased. As a result, the exit seepage gradients are correspondingly low, and therefore, the likelihood of an internal erosion/piping related failure through the embankments and/or through their foundations leading to a catastrophic failure is considered to be negligible and therefore non-credible.

There are internal drains constructed in the Iron, Siliceous, and Gypsum TSFs, with pipes that extend through the embankments, which represent a potential vulnerability to internal erosion/piping as they deteriorate over time. Only the drain from the Silicious impoundment is still open and draining, all other drains have been covered with inverted filters. Because of the very low hydraulic gradients and small volume of free water available, the likelihood of this failure mode via the deteriorated conduits leading to catastrophic consequences remains negligible. A review of this vulnerability is being completed to assess this risk if local ponding occurs above these pipes due to an extreme flood events that could potentially increase the local phreatic surface and, therefore, temporarily increase the local seepage gradients. It is expected that, even under such an extreme condition, the limited amount of free water source in direct contact with the conduits will greatly limit the extent to which piped materials can be transported and the potential for a catastrophic failure mode is considered non-credible. In any event, the results of this review will inform the decision as to whether additional measures might be necessary to reduce the risk related to these structures.

##### *ARD Pond*

The likelihood of internal erosion/piping failure modes resulting in catastrophic consequences is considered to be negligible for the ARD Pond Dams. These dams have filter zones in the dam cross-section. While there are indications of a potential seepage pathway on the left abutment of the South Dam which respond to the reservoir water fluctuations, investigations and assessments have noted that the soils are internally stable and the piezometric response through the abutment is insufficient to trigger and sustain internal erosion in the abutment.

### *Sludge Impoundment*

For the Sludge Impoundment, the likelihood of an internal erosion/ piping failure leading to catastrophic consequences is negligible, and therefore noncredible, due to the inclusion of filters in the embankment and the lack of a permanent pond.

#### **5.1.3 Slope Instability**

- The dikes have been observed over many years since closure and no visual signs of instability have been documented.
- The good performance of the embankments indicates the engineering controls are adequate to prevent slope instability of the facilities under the current loading conditions.
  - ◆ A Design Basis document (KCB, 2002) was prepared for the TSFs and summarized previous stability assessments completed. The assessments recognized that loose contractive saturated tailings, such as those present in the tailings storage facilities at the Sullivan Mine, are susceptible to static and seismic liquefaction. Although a seismic hazard study was completed to estimate of the ground motions for the Maximum Credible Earthquake, the decision was made to conservatively assume that all saturated tailings would liquefy, irrespective of the earthquake ground motion, as the basis at that time for design of stabilization measures. Therefore, all saturated tailings (i.e. all tailings below the phreatic surface prevailing at the time of the analyses) were assigned the liquefied residual undrained strength for stability calculations.
  - ◆ The closure configuration design was based on these assumptions and meets current regulatory requirements for both static and seismic stability.
  - ◆ A due diligence review and update of the seismic stability of all structures is underway to better reflect existing conditions based on the current phreatic surface levels and the revised seismic hazard assessment and recent data collected on the density of the foundation soils at both the Silicious and Gypsum TSFs. However, the lack of permanent pond and low phreatic surface mean that even if there is settlement or deformations due to seismic loading the material runout will be limited and the potential for catastrophic downstream consequences is considered negligible. The lack of pond and dry tailings both represent much more favorable conditions when compared to the assumptions made during original design of the stabilization measures.
  - ◆ The results of the seismic stability updates are important as supporting documentation towards Teck's long-term goal of eventually removing credible failure modes (non-catastrophic) associated with seismic loading.
  - ◆ The ARD pond was designed to meet static and pseudo-static factors of safety.
- Visual observations indicate there are no significant erosion features on the crest or slopes of the dikes. The minor erosion rills observed on some dikes is very common for this type of facility and are not expected to rapidly develop into erosion gullies that could threaten the stability of the embankment.

- The operational controls to prevent slope instability of the facilities include active management of pond levels where ponds are present, monitoring of the phreatic surface in the facility as well as routine inspections of the condition of the embankments. Particular attention (daily monitoring) is paid to pond levels and piezometer data during freshet when the ARD pond level is highest prior to start of the DWTP.
- The design and operational controls in place manage slope instability for the current loading conditions and for earthquakes up to the 1/10,000-yr event for all TSFs. Based on Teck's tailings governance and the risk assessment framework, the potential impacts of such an event would not be catastrophic to health and safety or the environment, nor from a community relations, reputation, legal, or financial perspective.

## 5.2 OMS Manual

The most recent version of the Operation, Maintenance, and Surveillance (OMS) Manual for the Sullivan Mine tailings facilities was updated in 2022 (SUL-OMS-001, March 29, 2022) by Teck. Review of the OMS manual was in progress at the time of this report. Teck will continue to review the manual annually and make revisions as necessary, with input from the EoR.

## 5.3 Mine Emergency Response Plan

The current version of the MERP was updated in January 2019 when it was converted from the previous Emergency Preparedness and Response Plan (EPRP), and updated in April 2022. The plan meets the regulatory requirements and guidance documents from CDA and the Mining Association of Canada. The plan includes identification of communities of interest, failure modes, and responses to various emergencies.

As required by HSRC (EMCLI, 2022), the MERP is tested annually using desk-top scenarios. A table-top exercise to review and update the Emergency Preparedness Response Plan was hosted by Teck and attended by the current Sullivan EoR on April 30, 2022.

The emergency reporting contact list is also reviewed and updated as required.

## 6 SUMMARY

The Sullivan Mine TSFs, ARD Pond and the Sludge Impoundment appear to be in good physical condition and the observed performance during the 2022 site inspections is consistent with the expected design conditions and historical performance.

There were no deficiencies, non-conformances or issues of concern identified in this year's review, and therefore, there are no new recommendations.

A summary of previous annual performance review recommendations that were outstanding, and their updated status, are summarized in Table 6.1. All of the recommendations pertain to the framework of continual improvements in the dam safety management program, such as documentation and maintenance/surveillance protocols. The recommendation for the Sludge Impoundment is part of the design review and update that is already being planned by Teck and KCB.

As per previous annual reviews, deficiencies and non-conformances are grouped according to the following four categories:

- **Deficiency (D):** An unacceptable dam performance condition based on analysis results and/or site observations/instrument data with respect to criteria outlined in the 2017 HSRC and 2016 Guidance Document, best practices, and/or applicable regulatory requirements.
- **Potential (PD):** A dam performance condition that requires further evaluation to determine if the condition is a deficiency.
- **Non-Conformance (NC):** Defined as a deviation from established policies, procedures, operating instructions, maintenance requirements, or surveillance plans. A non-conformance is not an indication of unacceptable dam performance.
- **Items Requiring Updates to Meet Updated Regulatory Standards (RS):** Condition where regulatory requirements have changed and have become more stringent following initial design and/or construction.

**Table 6.1 Summary of Outstanding Recommendations from Past DSIs and New Recommendations from Current Annual Inspection**

Structure	ID No.	Deficiency of Non-Conformance	Applicable Regulation or OMS Reference	Recommended Action	Deficiency Type	Priority	Recommended Deadline/Status
<b>Previous Recommendations Closed/Superseded</b>							
<b>Previous Recommendations Ongoing</b>							
Sludge Impoundment	2017-3	A review of the Sludge Impoundment is needed.	EMLCI HSRC (2022) & CDA Guidelines: Application to Mining Dams (2019)	Review of the current design freeboard and design sludge levels is required. To facilitate the design update, the Sludge Impoundment surface should be surveyed to obtain average sludge deposition rates. Review of entire facility should be completed to address storage, life expectancy of the facility, and regulatory requirements.	RS	3	Q4 2024 UPDATE – Site investigation completed. The site investigation data will be combined with other groundwater information and form the basis for a workshop between Teck and KCB on the future of the facility. After the workshop is completed, a scope of work will be developed based on the workshop outcomes.

## 7 CLOSING

We appreciate the opportunity to continue to provide our services to Teck Metals.

**KLOHN CRIPPEN BERGER LTD.**

B.C. Permit to Practice No. 1000171

Pamela Fines, P.Eng.  
Associate, Manager, Edmonton

Senior Reviewed by: Bill Chin, P.Eng.



## REFERENCES

- Canadian Dam Association. 2019. Dam Safety Guidelines 2007 (Revised 2019).
- Dames and Moore. 1978. Report on Final Design Studies Sludge Disposal Pond.
- Davies, M.P., Dawson, B.B., and Chin, B.G. 1998. "Static Liquefaction of Mine Tailings – A Case History." Proceedings, 51st Canadian Geotechnical Conference.
- EC (2019) Canadian Climate Normals 1981-2010 (Kimberley PCC). Retrieved from:  
[https://climate.weather.gc.ca/climate\\_normals/results\\_1981\\_2010\\_e.html?searchType=stnName&txtStationName=Kimberley+PCC&searchMethod=contains&txtCentralLatMin=0&txtCentralLatSec=0&txtCentralLongMin=0&txtCentralLongSec=0&stnID=1194&dispBack=1](https://climate.weather.gc.ca/climate_normals/results_1981_2010_e.html?searchType=stnName&txtStationName=Kimberley+PCC&searchMethod=contains&txtCentralLatMin=0&txtCentralLatSec=0&txtCentralLongMin=0&txtCentralLongSec=0&stnID=1194&dispBack=1)
- GISTM, 2020. [Global Industry Standard on Tailings Management – Global Tailings Review](#). Accessed on March 14, 2021.
- Golder Associates. 2014. 2013 Dam Safety Review, Submitted to Teck Metals Ltd. September 11, 2014. Reference Number 1314270027-002-R-Rev 0-1000.
- Klohn Crippen Berger, 2007. Sullivan Mine Tailings Area, Emergency Storage Pond (ESP) Spillway Design (ESP). Submitted September 28, 2007 to TeckCominco Metals Ltd. Project No. A05807A04.
- Klohn Crippen Berger, 2018. Sullivan Mine Hydrology Update - Draft. Submitted Nov. 1, 2018 to Teck Metals Ltd. Project No. A05807B23.
- Klohn Crippen Berger, 2020. 2019 Seismic Hazard Assessment. Submitted August 2020 to Teck Metals Ltd. Project No. A05807B28.
- Klohn Crippen Consultants, 2000. Sullivan Mine – Storage Pond No. 1 Design Report. Submitted March 20, 2000 to Cominco Ltd. Project No. PM5807.34.
- Klohn Crippen Consultants, 2000b. Sullivan Mine – Storage Pond No. 1 Design Report Addendum. Submitted August 21, 2000 to Cominco Ltd. Project No. PM5807.34.
- Klohn Crippen Consultants, 2002. Sullivan Mine – Geotechnical Design Basis for Tailings Dikes – Overview Summary Report. Submitted January, 2002 to TeckCominco Ltd. Project No. PM5807.85.
- Ministry of Energy, Mines, and Petroleum Resources. 2016. "Guidance Document: Health, Safety and Reclamation Code for Mines in British Columbia. Version 1."
- Ministry of Energy, Mines, and Low Carbon Innovation. 2022. "Health, Safety and Reclamation Code for Mines in British Columbia."
- Revenue Services of British Columbia (RSBC). 1996. Mines Act.
- Service BC. 2003. Environmental Management Act.
- SRK. 2014 Sullivan Mine Post Closure Water Balance. A Report to Teck Metals Ltd.


Teck Environmental Group. 2019. "Guideline for Tailings and Water Retaining Structures."

Teck Metals Ltd., 2017. Sullivan – Seepage Collection Manual. Version 005. September 25, 2017.

Wood. 2018. 2017 Draft Risk Assessment on Tailings Dams Classified as High or Higher. August 29, 2018

## FIGURES


---



**PROJECT LOCATION PLAN**  
N.T.S

**NOTES:**

1. SURFACE TOPOGRAPHY FROM LIDAR PROVIDED BY TECK METALS LTD. DATED DECEMBER 2012.
2. ELEVATIONS ARE GEODETIC.
3. MAP COORDINATE SYSTEM = U.T.M. (NAD 83). CONTOUR INTERVAL IS ONE METRE.
4. AERIAL PHOTO PROVIDED BY TECK METALS LTD. DATE: 2008.

















Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 1\_Location and Site Plan\_2022.dwg November 18, 2022 TDo

CLIENT 	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
	TITLE LOCATION AND SITE PLAN	
	SCALE AS-SHOWN	PROJECT No. A05807A22
	FIG. No. 1	

KCB-FIG-01

**LEGEND**


-  DECANT TOWER
-  DISCHARGE
-  INTAKE
-  AIR RELIEF VALVE
-  PUMPING FACILITY
-  MANHOLE
-  BREATHER
-  FLOW DIRECTION ARROW
-  PIPE LINE
-  DWT / MINE LINE
-  DITCH
-  TOE DRAIN



**NOTES:**

1. FROM TM Tech SERVICES DRAWING K100E3007 DATED FEB. 3, 2009, REV. 1.




<p>CLIENT</p> <h1 style="text-align: center;">Teck</h1> 	<p>PROJECT</p> <p style="text-align: center;">SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT</p> <hr/> <p>TITLE</p> <p style="text-align: center;"><b>TAILINGS SEEPAGE COLLECTION AND DWT PLANT LOCATION</b></p>
<p>SCALE</p> <p>AS-SHOWN</p>	<p>PROJECT No.</p> <p>A05807A22</p>
<p>FIG. No.</p> <p>2</p>	

Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 2 Seepage Collection Plan 2022.dwg November 17, 2022 TDo

KCB\FG-B-L

Z:\A\EDM\A06807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 3\_Design Sections Arrangement 2022.dwg November 17, 2022 TDO



**NOTES:**

1. SURFACE TOPOGRAPHY FROM LIDAR PROVIDED BY TECK METALS LTD. DATED DECEMBER 2012.
2. ELEVATIONS ARE GEODETIC.
3. MAP COORDINATE SYSTEM = U.T.M. (NAD 83). CONTOUR INTERVAL IS ONE METRE.
4. LOCATIONS OF DESIGN SECTIONS ARE APPROXIMATE

**PLAN**  
SCALE = 1:12 500




CLIENT

Teck

Klohn Crippen Berger

PROJECT	SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
TITLE	GENERAL ARRANGEMENT OF DESIGN SECTIONS	
SCALE	PROJECT No.	FIG. No.
AS-SHOWN	A05807A22	3

KCB/GBL




Z:\A\EDM\A06807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 4 Photo Location 2022.dwg November 22, 2022 TDO

- NOTES:**
1. GENERAL TOPOGRAPHY FROM LIDAR DATED DECEMBER 2012.
  2. ELEVATIONS ARE GEODETIC.
  3. MAP COORDINATE SYSTEM = U.T.M. (NAD 83). CONTOUR INTERVAL IS ONE METRE.

**LEGEND**

- LOCATION AND DIRECTION OF PHOTOGRAPHS TAKEN DURING ANNUAL INSPECTION
- PHOTO NUMBER
- LOCATION WHERE PHOTO WAS TAKEN
- DIRECTION OF VIEW PANORAMA




CLIENT

# Teck

<p>PROJECT</p> <p style="text-align: center;">SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT</p>	<p>TITLE</p> <p style="text-align: center;"><b>GENERAL ARRANGEMENT OF TAILINGS FACILITIES, PHOTO LOCATIONS</b></p>
SCALE	PROJECT No.
AS-SHOWN	A05807A22
FIG. No.	4

KCB/FG-BL

Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 5 IronPond 2022.dwg November 17, 2022 TDo




**NOTES:**

1. GENERAL TOPOGRAPHY FROM LIDAR DATED DECEMBER 2012.
2. ELEVATIONS ARE GEODETIC.
3. MAP COORDINATE SYSTEM = U.T.M. (NAD83). CONTOUR INTERVAL IS ONE METRE.
4. STATIONING IS IN FEET.
5. INSTRUMENTATION LOCATIONS ARE BASED ON RECORDS PROVIDED BY TECK PERSONNEL FOR THIS REPORT. NO ATTEMPT HAS BEEN MADE TO VERIFY THE ACCURACY OF THE LOCATIONS.

**LEGEND**

- P91-07 PNEUMATIC PIEZOMETER
- SP330 SETTLEMENT GAUGE
- BI92-01 INCLINOMETER
- P92-26 STANDPIPE PIEZOMETER
- 92-H OBSERVATION WELL
- 24+00 CHAINAGE ALONG CENTRELINE (FT.)
- 1015.6 MAXIMUM RECORDED PIEZO LEVEL (m) DURING REPORTING PERIOD
- SEEPAGE COLLECTOR DITCH
- LOCATION AND DIRECTION OF PHOTOGRAPHS TAKEN DURING ANNUAL INSPECTION
- PHOTO NUMBER
- LOCATION WHERE PHOTO WAS TAKEN
- DIRECTION OF VIEW
- 101 PANORAMA




CLIENT <h1 style="text-align: center;">Teck</h1>	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT
	TITLE <h2 style="text-align: center;">INSTRUMENT LOCATION PLAN IRON DIKE</h2>
SCALE AS-SHOWN	PROJECT No. A05807A22
	FIG. No. 5


KCB-FIG-5-L



Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 6.7 Iron Dike Sections 2022.dwg November 17, 2022 TDo



**D SECTION**  
FIG 5 SCALE = 1:750




**E SECTION**  
FIG 5 SCALE = 1:750

**NOTES:**

1. SURFACE TOPOGRAPHY FROM LIDAR PROVIDED BY TECK METALS LTD. DATED DECEMBER 2012.
2. SUBSURFACE LITHOLOGY TRACED FROM 1995 ACTIVE IRON DIKE - GEOTECHNICAL DESIGN OF 1995 DIKE RAISE.

**LEGEND:**


- P91-01 PIEZOMETER
- ▼ 1023.8 MAXIMUM RECORDED PIEZO LEVEL (m) DURING REPORTING PERIOD
- | 1021.4 PIEZOMETER TIP



<p>CLIENT</p> <h1>Teck</h1>	<p>PROJECT</p> <p>SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT</p>	
	<p>TITLE</p> <p>IRON DIKE SECTIONS D AND E</p>	
<p>SCALE</p> <p>AS-SHOWN</p>	<p>PROJECT No.</p> <p>A05807A22</p>	<p>FIG. No.</p> <p>6</p>

KB-FIG-6-L

Z:\A\EDM\A05807A22.TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 6.7 Iron Dike Sections 2022.dwg November 17, 2022 TDo




**F SECTION**  
FIG 5 SCALE = 1:500

**NOTES:**

1. SURFACE TOPOGRAPHY FROM LIDAR PROVIDED BY TECK METALS LTD. DATED DECEMBER 2012.
2. SUBSURFACE LITHOLOGY TRACED FROM 1995 ACTIVE IRON DIKE - GEOTECHNICAL DESIGN OF 1995 DIKE RAISE.


**LEGEND:**

- P91-01 PIEZOMETER
- 1023.8 MAXIMUM RECORDED PIEZO LEVEL (m) DURING REPORTING PERIOD
- 1021.4 PIEZOMETER TIP




<p>CLIENT</p> <h1 style="margin: 0;">Teck</h1>	<p>PROJECT</p> <p>SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT</p>	
	<p>TITLE</p> <p>IRON DIKE SECTION F</p>	
SCALE AS-SHOWN	PROJECT No. A05807A22	FIG. No. 7

KCB-FIG-6-L



- NOTES:**
1. GENERAL TOPOGRAPHY FROM LIDAR DATED DECEMBER 2012.
  2. ELEVATIONS ARE GEODETIC.
  3. MAP COORDINATE SYSTEM = U.T.M. (NAD83).
  4. INSTRUMENTATION LOCATIONS ARE BASED ON RECORDS PROVIDED BY TECK PERSONNEL FOR THIS REPORT. NO ATTEMPT HAS BEEN MADE TO VERIFY THE ACCURACY OF THE LOCATIONS.

Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 8 Old Iron Pond 2022.dwg November 17, 2022 TDO




**LEGEND:**

- |  |  |  |  |
|--|--|--|--|
|  | SUL-01A&B  |  | LOCATION AND DIRECTION OF PHOTOGRAPHS TAKEN DURING ANNUAL INSPECTION |
|  | VIBRATING WIRE PIEZOMETER                                |  | PHOTO NUMBER   |
|  | STANDPIPE PIEZOMETER                                     |  | LOCATION WHERE PHOTO WAS TAKEN                                       |
|  | PNEUMATIC PIEZOMETER                                     |  | DIRECTION OF VIEW  |
|  | MAXIMUM RECORDED PIEZO LEVEL (m) DURING REPORTING PERIOD |  | PANORAMA   |

CLIENT 	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
	TITLE INSTRUMENT LOCATION PLAN OLD IRON & IRON TSF DIVIDER DIKES	
SCALE AS-SHOWN	PROJECT No. A05807A22	FIG. No. 8

KCB-FRG-B-L

Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 9\_Old Iron Dike Section 2022.dwg November 17, 2022 TDo




**G SECTION**  
FIG 8 SCALE = 1:750

**NOTES:**

1. SURFACE TOPOGRAPHY FROM LIDAR PROVIDED BY TECK METALS LTD. DATED DECEMBER 2012.
2. SUBSURFACE LITHOLOGY TRACED FROM 1994 SULLIVAN MINE STABILITY REVIEW OF SOUTHWEST LIMB.
3. APPROXIMATE ELEVATION OF GLACIAL TILL SURFACE FROM BOREHOLE 92-F (OFFSET 200 FT WEST).
4. APPROXIMATE LOCATION OF "SOUTH DAM", AN EARLY DYKE WHICH EXPERIENCED TWO FAILURES IN 1926 AND 1930, FROM 1964 TOPOGRAPHY. THE SOUTHWEST LIMB (WHICH INCLUDES SECTION G) OF THE IRON DYKE WAS PROBABLY THE FINAL INCREMENTAL RAISE OF THE "SOUTH DAM" ACCORDING TO THE 1994 SULLIVAN MINE STABILITY REVIEW OF SOUTHWEST LIMB.

**LEGEND:**


- P91-01 PIEZOMETER
- 1023.8 MAXIMUM RECORDED PIEZO LEVEL (m) DURING REPORTING PERIOD
- 1021.4 PIEZOMETER TIP



<p>CLIENT</p> <h1 style="margin: 0;">Teck</h1>	PROJECT		SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT
	TITLE		
SCALE	PROJECT No.	FIG. No.	
AS-SHOWN	A05807A22	9	


KCB-FG-B-L

Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 10\_Sil Dikes 2022.dwg November 17, 2022 TDO



- NOTES:**
1. GENERAL TOPOGRAPHY FROM LIDAR DATED DECEMBER 2012.
  2. ELEVATIONS ARE GEODETIC.
  3. MAP COORDINATE SYSTEM = U.T.M. (NAD83).
  4. INSTRUMENTATION LOCATIONS ARE BASED ON RECORDS PROVIDED BY TECK PERSONNEL FOR THIS REPORT. NO ATTEMPT HAS BEEN MADE TO VERIFY THE ACCURACY OF THE LOCATIONS.
  5. SPILLWAY LOCATIONS ARE APPROXIMATE.


- LEGEND:**
- SUL-SD3-VWP-18-06A&B VIBRATING WIRE PIEZOMETER
  - P91-07 PNEUMATIC PIEZOMETER
  - P205 STANDPIPE PIEZOMETER
  - SP206 STANDPIPE PIEZOMETER AND SETTLEMENT PLATE
  - EL.1032.1 MAXIMUM RECORDED PIEZO LEVEL (m) DURING REPORTING PERIOD
  - LOCATION AND DIRECTION OF PHOTOS TAKEN DURING ANNUAL INSPECTION
  - PHOTO NUMBER
  - LOCATION WHERE PHOTO WAS TAKEN
  - DIRECTION OF VIEW
  - PANORAMA



CLIENT <h1 style="text-align: center;">Teck</h1>	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT
	TITLE INSTRUMENT LOCATION PLAN NO. 1, 2 & 3 SILICEOUS DIKES
SCALE AS-SHOWN	PROJECT No. A05807A22
	FIG. No. 10

KCB-FRG-B-L

Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 11.12\_Siliceous TSF Sections 2022.dwg November 17, 2022 TDo




**A SECTION**  
FIG 10 SCALE = 1:500


**NOTES:**

1. SURFACE TOPOGRAPHY FROM LIDAR PROVIDED BY TECK METALS LTD. DATED DECEMBER 2012.
2. SUBSURFACE LITHOLOGY TRACED FROM 1994 SULLIVAN MINE STABILITY REVIEW OF SILICA DYKES.




CLIENT 	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
	TITLE NO. 1 SILICEOUS DIKE SECTION A	
SCALE AS-SHOWN	PROJECT No. A05807A22	FIG. No. 11

KB-FG-B-L



**B SECTION**  
FIG 10 SCALE = 1:500



**C SECTION**  
FIG 10 SCALE = 1:500

**NOTES:**


1. GENERAL TOPOGRAPHY FROM LIDAR DATED DECEMBER 2012.
2. SUBSURFACE LITHOLOGY TRACED FROM 1994 SULLIVAN MINE STABILITY REVIEW OF SILICA DYKES.

**LEGEND:**

- P91-01 PIEZOMETER
- 1023.8 MAXIMUM RECORDED PIEZO LEVEL (m) DURING REPORTING PERIOD
- 1021.4 PIEZOMETER TIP



CLIENT 	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
	TITLE NO. 2 AND NO. 3 SILICEOUS DIKES SECTIONS B AND C	
SCALE AS-SHOWN	PROJECT No. A05807A22	FIG. No. 12



**NOTES:**

1. GENERAL TOPOGRAPHY FROM LIDAR DATED DECEMBER 2012.
2. ELEVATIONS ARE GEODETIC.
3. MAP COORDINATE SYSTEM = U.T.M. (NAD83), CONTOUR INTERVAL IS ONE METRE.
4. STATIONING IS IN FEET.
5. INSTRUMENTATION LOCATIONS ARE BASED ON RECORDS PROVIDED BY TECK NO ATTEMPT HAS BEEN MADE TO VERIFY THE ACCURACY OF THE LOCATIONS.

**LEGEND:**

- P93-15 1993 STANDPIPE PIEZOMETER
- P94-01 STANDPIPE PIEZOMETER
- SP97-01 SETTLEMENT PLATE
- BI94-02 INCLINOMETER
- S94-02 SONDEX SETTLEMENT GAUGE
- EL.1032.1 MAXIMUM RECORDED PIEZO LEVEL (m) DURING REPORTING PERIOD

**LOCATION AND DIRECTION OF PHOTOGRAPHS TAKEN DURING ANNUAL INSPECTION**

- PHOTO NUMBER
- LOCATION WHERE PHOTO WAS TAKEN
- DIRECTION OF VIEW
- PANORAMA




CLIENT <h1 style="text-align: center;">Teck</h1>	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
	TITLE <h2 style="text-align: center;">INSTRUMENT LOCATION PLAN WEST GYPSUM DIKE</h2>	
SCALE AS-SHOWN	PROJECT No. A05807A22	FIG. No. 13

Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 13 WestGyp 2022.dwg November 17, 2022 TDO


KCB-FIG-1



Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 14\_15\_West Gypsum Dike Sections 2022.dwg November 17, 2022 TDo



**P SECTION**  
FIG 13 SCALE = 1:750




**Q SECTION**  
FIG 13 SCALE = 1:750

**NOTES:**

1. SURFACE TOPOGRAPHY FROM LIDAR PROVIDED BY TECK METALS LTD. DATED DECEMBER 2012.
2. SUBSURFACE LITHOLOGY TRACED FROM 1993 SULLIVAN MINE STABILITY REVIEW OF GYPSUM DYKES.

**LEGEND:**


- P93-01 PIEZOMETER
- 1006.30 MAXIMUM RECORDED PIEZO LEVEL (m) DURING REPORTING PERIOD
- 1000.2 PIEZOMETER TIP



CLIENT 	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
	TITLE WEST GYPSUM DIKE SECTIONS P AND Q	
SCALE AS-SHOWN	PROJECT No. A05807A22	FIG. No. 14

KB2768-L

Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 14\_15\_West Gypsum Dike Sections 2022.dwg November 17, 2022 TDo



**R SECTION**  
FIG 13 SCALE = 1:500

**NOTES:**

1. SURFACE TOPOGRAPHY FROM LIDAR PROVIDED BY TECK METALS LTD. DATED DECEMBER 2012.
2. SUBSURFACE LITHOLOGY TRACED FROM 1993 SULLIVAN MINE STABILITY REVIEW OF GYPSUM DYKES.

**LEGEND:**


- P93-01 PIEZOMETER
- 1006.30 MAXIMUM RECORDED PIEZO LEVEL (m) DURING REPORTING PERIOD
- 1000.2 PIEZOMETER TIP



CLIENT 	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
	TITLE WEST GYPSUM DIKE SECTION R	
SCALE AS-SHOWN	PROJECT No. A05807A22	FIG. No. 15




KB-FG-B-L



- NOTES:**
1. GENERAL TOPOGRAPHY FROM LIDAR DATED DECEMBER 2012.
  2. ELEVATIONS ARE GEODETIC.
  3. MAP COORDINATE SYSTEM = U.T.M. (NAD83). CONTOUR INTERVAL IS ONE METRE.
  4. STATIONING IS IN FEET.
  5. INSTRUMENTATION LOCATIONS ARE BASED ON RECORDS PROVIDED BY TECK NO ATTEMPT HAS BEEN MADE TO VERIFY THE ACCURACY OF THE LOCATIONS.

- LEGEND:**
- P93-15 1993 STANDPIPE PIEZOMETER
  - P94-01 STANDPIPE PIEZOMETER
  - SP97-01 SETTLEMENT PLATE
  - BI94-02 INCLINOMETER
  - S94-02 SONDEX SETTLEMENT GAUGE
  - EL.1032.1 MAXIMUM RECORDED PIEZO LEVEL (m) DURING REPORTING PERIOD

- LOCATION AND DIRECTION OF PHOTOGRAPHS TAKEN DURING ANNUAL INSPECTION**
- PHOTO NUMBER
  - LOCATION WHERE PHOTO WAS TAKEN
  - DIRECTION OF VIEW
  - PANORAMA




CLIENT 	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
	TITLE INSTRUMENT LOCATION PLAN EAST GYPSUM DIKE	
SCALE AS-SHOWN	PROJECT No. A05807A22	FIG. No. 16


Z:\A\EDM\A05807A22.TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 16\_EastGyp 2022.dwg November 17, 2022 TDo

KCB-FG-B-L

Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 17\_East Gypsum Dike Sections 2022.dwg November 17, 2022 TDo



**S SECTION**  
FIG 16 SCALE = 1:750




**T SECTION**  
FIG 16 SCALE = 1:750

**NOTES:**

1. SURFACE TOPOGRAPHY FROM LIDAR PROVIDED BY TECK METALS LTD. DATED DECEMBER 2012.
2. SUBSURFACE LITHOLOGY TRACED FROM 1993 SULLIVAN MINE STABILITY REVIEW OF GYPSUM DYKES.


**LEGEND:**

- P93-01 PIEZOMETER
- ▼ 1006.30 MAXIMUM RECORDED PIEZO LEVEL (m) DURING REPORTING PERIOD
- | 1000.2 PIEZOMETER TIP



<p>CLIENT</p> <h1 style="margin: 0;">Teck</h1>	<p>PROJECT</p> <p style="text-align: center;">SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT</p>	
	<p>TITLE</p> <p style="text-align: center;"><b>EAST GYPSUM DIKE SECTIONS S AND T</b></p>	
<p>SCALE</p> <p>AS-SHOWN</p>	<p>PROJECT No.</p> <p>A05807A22</p>	<p>FIG. No.</p> <p>17</p>

KB-FG-B-L




**NOTES:**

1. GENERAL TOPOGRAPHY FROM LIDAR DATED DECEMBER 2012.
2. ELEVATIONS ARE GEODETIC.
3. MAP COORDINATE SYSTEM = U.T.M. (NAD83). CONTOUR INTERVAL IS ONE METRE.
4. INSTRUMENTATION LOCATIONS ARE BASED ON RECORDS PROVIDED BY TECK PERSONNEL FOR THIS REPORT. NO ATTEMPT HAS BEEN MADE TO VERIFY THE ACCURACY OF THE LOCATIONS.

**LEGEND:**

- LOCATION AND DIRECTION OF PHOTOGRAPHS TAKEN DURING ANNUAL INSPECTION
- PHOTO NUMBER
- LOCATION WHERE PHOTO WAS TAKEN
- DIRECTION OF VIEW
- PANORAMA




Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 18\_NEGyp 2022.dwg November 17, 2022 TDo

CLIENT 	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
	TITLE INSTRUMENT LOCATION PLAN NORTHEAST GYPSUM DIKE AND RECYCLE DAM	
SCALE AS-SHOWN	PROJECT No. A05807A22	FIG. No. 18

KCB-FRG-B-L


Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 19\_Northeast Gypsum Dike and Recycle Dam Section 2022.dwg November 17, 2022 TDo




**U SECTION**  
FIG 18 SCALE = 1:500.


**NOTES:**

1. SURFACE TOPOGRAPHY FROM LIDAR PROVIDED BY TECK METALS LTD. DATED DECEMBER 2012.
2. SUBSURFACE LITHOLOGY TRACED FROM REPORT ON 1985 CONSTRUCTION ACTIVITIES: NORTHEAST RETENTION EMBANKMENT GYPSUM PONDS.



CLIENT 	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
	TITLE NORTHEAST GYPSUM DIKE AND RECYCLE DAM SECTION U	
SCALE AS-SHOWN	PROJECT No. A05807A22	FIG. No. 19

KB-FG-B-L



**NOTES:**

1. GENERAL TOPOGRAPHY FROM LIDAR DATED DECEMBER 2012.
2. ELEVATIONS ARE GEODETIC.
3. MAP COORDINATE SYSTEM = U.T.M. (NAD 83).

**LEGEND:**

- PNEUMATIC PIEZOMETER
- STANDPIPE PIEZOMETER
- SETTLEMENT PIN
- SEEPAGE COLLECTOR DITCH
- MAXIMUM RECORDED PIEZO LEVEL (m) DURING REPORTING PERIOD

**LOCATION AND DIRECTION OF PHOTOGRAPHS TAKEN DURING ANNUAL INSPECTION**

- PHOTO NUMBER
- LOCATION WHERE PHOTO WAS TAKEN DIRECTION OF VIEW
- PANORAMA





<p>CLIENT</p> <h1 style="margin: 0;">Teck</h1>	<p>PROJECT</p> <p><b>SULLIVAN MINE</b></p> <p>2022 ANNUAL INSPECTION REPORT</p>	
	<p>TITLE</p> <p><b>ARD STORAGE POND</b></p> <p>PLAN AND LAYOUT</p>	
<p>SCALE</p> <p>AS-SHOWN</p>	<p>PROJECT No.</p> <p>A05807A22</p>	<p>FIG. No.</p> <p>20</p>

Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 20\_Ard 2022.dwg November 17, 2022 TDO

KCB-FIG-20

Z:\A\EDM\A06807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 21.22\_ARD Storage Pond North Dam Sections 2022.dwg November 17, 2022 TDo




**NOTES:**

1. SURFACE TOPOGRAPHY FROM LIDAR PROVIDED BY TECK METALS LTD. DATED DECEMBER 2012.
2. SUBSURFACE LITHOLOGY TRACED FROM 2002 SULLIVAN MINE TAILINGS FACILITY STORAGE POND NO. 1 CONSTRUCTION RECORD REPORT.

**LEGEND:**


- P91-01 PIEZOMETER
- MAXIMUM RECORDED PIEZO LEVEL (m) DURING REPORTING PERIOD
- PIEZOMETER TIP




<p>CLIENT</p> <h1 style="margin: 0;">Teck</h1>	<p>PROJECT</p> <p>SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT</p>	
	<p>TITLE</p> <p>ARD STORAGE POND NORTH DAM SECTIONS H AND I</p>	
<p>SCALE</p> <p>AS-SHOWN</p>	<p>PROJECT No.</p> <p>A05807A22</p>	<p>FIG. No.</p> <p>21</p>

KCB-FIG-21





**J SECTION**  
FIG 20 SCALE = 1:250




**K SECTION**  
FIG 20 SCALE = 1:250

**NOTES:**


1. SURFACE TOPOGRAPHY FROM LIDAR PROVIDED BY TECK METALS LTD. DATED DECEMBER 2012.
2. SUBSURFACE LITHOLOGY TRACED FROM 2002 SULLIVAN MINE TAILINGS FACILITY STORAGE POND NO. 1 CONSTRUCTION RECORD REPORT.

**LEGEND:**


- P91-01 PIEZOMETER
- 1023.8 MAXIMUM RECORDED PIEZO LEVEL (m) DURING REPORTING PERIOD
- 1021.4 PIEZOMETER TIP



CLIENT 	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
	TITLE ARD STORAGE POND NORTH DAM SECTIONS J AND K	
SCALE AS-SHOWN	PROJECT No. A05807A22	FIG. No. 22



**L SECTION**  
FIG 20 SCALE = 1:250



**M SECTION**  
FIG 20 SCALE = 1:250

**NOTES:**

1. SURFACE TOPOGRAPHY FROM LIDAR PROVIDED BY TECK METALS LTD. DATED DECEMBER 2012.
2. SUBSURFACE LITHOLOGY TRACED FROM 2002 SULLIVAN MINE TAILINGS FACILITY STORAGE POND NO. 1 CONSTRUCTION RECORD REPORT.

**LEGEND:**

- P91-01 PIEZOMETER
- 1023.8 MAXIMUM RECORDED PIEZO LEVEL (m) DURING REPORTING PERIOD
- 1021.4 PIEZOMETER TIP




<b>CLIENT</b>    	<b>PROJECT</b> SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
	<b>TITLE</b> ARD STORAGE POND SOUTH DAM SECTIONS L AND M	
<b>SCALE</b> AS-SHOWN	<b>PROJECT No.</b> A05807A22	<b>FIG. No.</b> 23

Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 23.24 ARD Storage Pond South Dam Sections 2022.dwg November 17, 2022 TDo

KCB-FRG-B-L

Z:\A\EDM\A05807A22.TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 23.24\_ARD Storage Pond South Dam Sections 2022.dwg November 17, 2022 TDo




**N SECTION**  
FIG 20 SCALE = 1:250

**NOTES:**

1. SURFACE TOPOGRAPHY FROM LIDAR PROVIDED BY TECK METALS LTD. DATED DECEMBER 2012.
2. SUBSURFACE LITHOLOGY TRACED FROM 2002 SULLIVAN MINE TAILINGS FACILITY STORAGE POND NO. 1 CONSTRUCTION RECORD REPORT.


**LEGEND:**

- P91-01 PIEZOMETER
- 1023.8 MAXIMUM RECORDED PIEZO LEVEL (m) DURING REPORTING PERIOD
- 1021.4 PIEZOMETER TIP



CLIENT 	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
	TITLE ARD STORAGE POND SOUTH DAM SECTION N	
SCALE AS-SHOWN	PROJECT No. A05807A22	FIG. No. 24

KB-FG-B-L





**NOTES:**

1. GENERAL TOPOGRAPHY FROM LIDAR DATED DECEMBER 2012.
2. ELEVATIONS ARE GEODETIC.
3. MAP COORDINATE SYSTEM = U.T.M. (NAD83). CONTOUR INTERVAL IS ONE METRE.
4. INSTRUMENTATION LOCATIONS ARE BASED ON RECORDS PROVIDED BY TECK PERSONNEL FOR THIS REPORT. NO ATTEMPT HAS BEEN MADE TO VERIFY THE ACCURACY OF THE LOCATIONS.

**LEGEND:**

- MONITORING WELL - ABANDONED
- LOCATION AND DIRECTION OF PHOTOGRAPHS DURING ANNUAL INSPECTION
- PHOTO NUMBER
- LOCATION WHERE PHOTO WAS TAKEN
- DIRECTION OF VIEW
- PANORAMA




CLIENT  	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT
	TITLE INSTRUMENT LOCATION PLAN CALCINE DIKE
SCALE AS-SHOWN	PROJECT No. A05807A22
	FIG. No. 25

Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 25 Calcine 2022.dwg November 18, 2022 TDo

KCB-FRG-B-L

Z:\A\EDM\A05807A22.TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 26\_Calcine Dike Section 2022.dwg November 18, 2022 TDo




**O SECTION**  
FIG 25 SCALE = 1:500

**NOTES:**

1. SURFACE TOPOGRAPHY FROM LIDAR PROVIDED BY TECK METALS LTD. DATED DECEMBER 2012.
2. SUBSURFACE LITHOLOGY TRACED FROM 1979 SOIL INVESTIGATION AND DESIGN SECOND DYKE EXTENSION CALCINE DYKE.

**LEGEND:**


— P91-01 PIEZOMETER



CLIENT <h1>Teck</h1>	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
	TITLE <h2>CALCINE DIKE SECTION O</h2>	
SCALE AS-SHOWN	PROJECT No. A05807A22	FIG. No. 26




KB-FGS-L




**V SECTION**  
SCALE = 1:2500

NOTE: EXCESS SLUDGE DEPOSIT RELOCATED OCTOBER 2015




**X SECTION**  
SCALE = 1:2500



**W SECTION**  
SCALE = 1:2500

**VOLUME SUMMARY**

2001 SURVEY TO FULL POOL @ 0.4% GRADIENT ~ 278,000 cu.m.  
 2001 (MAY 8) SURVEY TO 2009 (SEPT 18) ~ 52,430 cu.m.  
 2012 LIDAR SURFACE TO FULL POOL ~ 182,550 cu.m.  
 2015 SURFACE TO FULL POOL ~ 163,630 cu.m.




**Y SECTION**  
SCALE = 1:2500

**LEGEND:**

- LOCATION AND DIRECTION OF PHOTOGRAPHS TAKEN DURING 2015 INSPECTION
- PHOTO NUMBER
- LOCATION WHERE PHOTO WAS TAKEN
- DIRECTION OF VIEW
- 2001 SURFACE
- 2009 SURVEY
- 2012 LIDAR SURVEY
- 2015 SURVEY (INTERVAL 0.5m)
- 2019 LIDAR SURVEY
- FULL POOL DESIGN SURFACE (INTERVAL 0.25m)
- FULL POOL PERIMETER (128,500 sq.m.)
- DENOTES SHUT OFF STANDPIPE
- CONTROL MONUMENT PLACED 2015

**NOTES:**

1. SLUDGE IMPOUNDMENT LAYOUT AND CROSS SECTIONS PROVIDED BY TM TECH SERVICES, DRAWING NO. K101A2243 DATED SEPTEMBER 9 2015.
2. EXCESS SLUDGE AT SPIGOT NO. 1 RELOCATED OCTOBER 27, 2015.




<b>Teck</b> 	CLIENT	PROJECT	
		SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
	TITLE		
	SLUDGE IMPOUNDMENT DIKES PLAN		
SCALE	PROJECT No.	FIG. No.	
AS-SHOWN	A05807A22	27	


Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 27 Sludge 2022.dwg November 18, 2022 TDo

KCB-FRG-B-L

Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure 28 - Sludge Impoundment Sections 2022.dwg November 18, 2022 TDo



**Z SECTION**  
SCALE = 1:125




**NOTES:**

1. SURFACE TOPOGRAPHY FROM LIDAR PROVIDED BY TECK METALS LTD. DATED DECEMBER 2012.
2. SUBSURFACE LITHOLOGY TRACED FROM 1978 CONSTRUCTION ACTIVITIES SLUDGE STORAGE POND - STAGE I DYKES.


CLIENT <h1 style="text-align: center;">Teck</h1>	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
	TITLE <h2 style="text-align: center;">SLUDGE IMPOUNDMENT DIKES SECTION Z</h2>	
SCALE AS-SHOWN	PROJECT No. A05807A22	FIG. No. 28




KCB-FIG-28-L




**PLAN**  
SCALE : 1:5000



STATION (m)  
**SPILLWAY**  
HOR: 1:1500  
VER: 1:300




STATION (m)  
**IRON DYKE CREST**  
HOR: 1:1500  
VER: 1:300





CLIENT <h1 style="text-align: center;">Teck</h1>	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT
	TITLE <h2 style="text-align: center;">IRON DIKE CREST AND SPILLWAY PROFILE</h2>
SCALE AS-SHOWN	PROJECT No. A05807A22
	FIG. No. IV-15



Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\400 Drawings\Annual Inspection\Figure VII-1.dwg November 18, 2022 TDo




(CAN NO LONGER READ. BLOCKED AT 4.7 m BELOW THE GROUND SURFACE)





<p>CLIENT</p> <h1 style="margin: 0;">Teck</h1>	<p>PROJECT</p> <p>SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT</p>	
<p><b>Klohn Crippen Berger</b></p>	<p>TITLE</p> <p>WEST GYPSUM DIKE SONDEX AND INCLINOMETER PLOTS</p>	
SCALE AS-SHOWN	PROJECT No. A05807A22	FIG. No. VII-1



KCB/FGSL






GYPSUM DYKES FACILITY, Inclinator BI-94-02  
SULLIVAN MINE, KIMBERLEY



CLIENT <h1>Teck</h1>	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT	
	TITLE EAST GYPSUM DIKE SONDEX AND INCLINOMETER PLOTS	
	SCALE AS-SHOWN	PROJECT No. A05807A22
	FIG. No. VIII-1	




**A PROFILE**  
 --- SCALE 1:750 HORZ.  
 1:150 VERT.



**B PROFILE**  
 --- SCALE 1:750 HORZ.  
 1:150 VERT.

**LEGEND**  
 --- 2012 LIDAR  
 --- 2019 LIDAR



Z:\A\EDM\A05807A22 TML 2022 Dam Safety Services\A00 Drawings\Annual Inspection\Figure XI-1 2022.dwg November 22, 2022 TDo

CLIENT <h1 style="text-align: center;">Teck</h1>	PROJECT SULLIVAN MINE 2022 ANNUAL INSPECTION REPORT
	TITLE <h2 style="text-align: center;">SLUDGE POND DIKE CREST PROFILES</h2>
SCALE AS-SHOWN	PROJECT No. A05807A22
	FIG. No. XI-1

KCB/FG/BL

# APPENDIX I

## 2022 Visual Inspection

---

## TML Sullivan Inspection Checklist

Structure: ARD South

Date: May 25/22

Inspected by: P. Finnes, M. Rottger

Weather: +8 cloudy

Pond Elevation: \_\_\_\_\_

Snow Cover? YES  NO

Operational Limits: \_\_\_\_\_

Inspection Item	Remarks
<b>Dam Crest Surface</b>	
Cracks	no
Erosion	no
Settlement/Depressions	no
Vegetation growth	no
Animal Activity (burrows)	no
Any unusual conditions	no well gravelled
Ponding of water	no
<b>Dam Upstream Slope</b>	
Slope protection (riprap)	good
Surface erosion/gullying	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	veg on slope, bushes
Animal Activity (burrows)	N/A
Any unusual conditions	N/A
<b>Dam Downstream Slope and Toe</b>	
Slope protection (grass)	good
Surface erosion/gullying	old erosion gully → rocks + grass
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	grass on slope, cattail in seepage ditch
Animal Activity (burrows)	burrows / animal activity at toe
Any unusual conditions	

## TML Sullivan Inspection Checklist

Structure: ARD North

Date: May 25/22

Inspected by: P. Fines & M. Rettger

Weather: +8, cloudy

Pond Elevation: \_\_\_\_\_

Snow Cover? YES /  NO

Operational Limits: \_\_\_\_\_

Inspection Item	Remarks
<b>Dam Crest Surface</b>	
Cracks	no
Erosion	no
Settlement/Depressions	no
Vegetation growth	some on crest, grass in gravel
Animal Activity (burrows)	no
Any unusual conditions	no
Ponding of water	no
<b>Dam Upstream Slope</b>	
Slope protection (riprap)	yes, adequate
Surface erosion/gullyng	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	some shrubs, mostly cut down
Animal Activity (burrows)	no
Any unusual conditions	logs mostly removed fr last time
<b>Dam Downstream Slope and Toe</b>	
Slope protection (grass)	good
Surface erosion/gullyng	no
Slides or sloughing	no
Settlement/Depressions	old depressions, no change
Bulging	no
Cracks	no
Vegetation growth	trees at toe cut down
Animal Activity (burrows)	gopher hole right abutment, animal burrow at toe
Any unusual conditions	

# TML Sullivan Inspection Checklist

Structure: Iron TSF

Date: May 25/22

Inspected by: P. Fines & M. Betzger

Weather: 40, cloudy

Pond Elevation: \_\_\_\_\_

Snow Cover? YES /  NO

Operational Limits: \_\_\_\_\_

Inspection Item	Remarks
<b>Dam Crest Surface</b>	
Cracks	no
Erosion	no
Settlement/Depressions	no
Vegetation growth	some, grass
Animal Activity (burrows)	no
Any unusual conditions	no
Ponding of water	no
<b>Dam Upstream Slope</b>	
Slope protection (riprap)	till cover & vegetation
Surface erosion/gullyng	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	yes,
Animal Activity (burrows)	no
Any unusual conditions	no
<b>Dam Downstream Slope and Toe</b>	
Slope protection (grass)	yes, adequate
Surface erosion/gullyng	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	no
Animal Activity (burrows)	not observed
Any unusual conditions	water (orange) at E toe no sediment gravel down playway in seepage ditch.

WEIRMS → D/S → "a"-notched

# TML Sullivan Inspection Checklist

Structure: Sil #1

Date: May 25/22

Inspected by: A. Fines & M. Rettger

Weather: \_\_\_\_\_

Pond Elevation: \_\_\_\_\_

Snow Cover? YES / NO

Operational Limits: \_\_\_\_\_

Inspection Item	Remarks
<b>Dam Crest Surface</b>	
Cracks	no
Erosion	no
Settlement/Depressions	no
Vegetation growth	grass
Animal Activity (burrows)	not observed
Any unusual conditions	no
Ponding of water	no
<b>Dam Upstream Slope</b>	
Slope protection (riprap)	no, grass
Surface erosion/gullyng	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	grass
Animal Activity (burrows)	no
Any unusual conditions	no
<b>Dam Downstream Slope and Toe</b>	
Slope protection (grass)	yes, grass
Surface erosion/gullyng	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	no (just grass)
Animal Activity (burrows)	not observed
Any unusual conditions	



# TML Sullivan Inspection Checklist

Structure: Sil 2 ~~#1~~

Date: Mar 25/22

Inspected by: P. Fines & M. Bettger

Weather: \_\_\_\_\_

Pond Elevation: \_\_\_\_\_

Snow Cover? YES /  NO

Operational Limits: \_\_\_\_\_

Inspection Item	Remarks
<b>Dam Crest Surface</b>	<i>seepage pipe partially blocked at toe</i>
<i>impoundment</i>	
Cracks	no
Erosion	no
Settlement/Depressions	no
Vegetation growth	yes
Animal Activity (burrows)	not observed
Any unusual conditions	no
Ponding of water	no
<b>Dam Upstream Slope</b>	
Slope protection (riprap)	
Surface erosion/gullyng	
Slides or sloughing	
Settlement/Depressions	
Bulging	
Cracks	
Vegetation growth	
Animal Activity (burrows)	
Any unusual conditions	
<b>Dam Downstream Slope and Toe</b>	
Slope protection (grass)	grass
Surface erosion/gullyng	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	sparse in places, early spring
Animal Activity (burrows)	tracks, digging
Any unusual conditions	

# TML Sullivan Inspection Checklist

Structure: Sil 3

Date: May 25/22

Inspected by: 1

Weather: +10, cloudy

Pond Elevation: \_\_\_\_\_

Snow Cover? YES / NO

Operational Limits: \_\_\_\_\_

Inspection Item	Remarks
<b>Dam Crest Surface</b> / <i>impoundment</i>	<i>50' May 29 2022</i>
Cracks	<i>no</i>
Erosion	<i>no</i>
Settlement/Depressions	<i>hammocky</i>
Vegetation growth	<i>yes,</i>
Animal Activity (burrows)	<i>not observed</i>
Any unusual conditions	<i>no</i>
Ponding of water	<i>no</i>
<b>Dam Upstream Slope</b>	
Slope protection (riprap)	
Surface erosion/gullyng	
Slides or sloughing	
Settlement/Depressions	
Bulging	
Cracks	
Vegetation growth	
Animal Activity (burrows)	
Any unusual conditions	
<b>Dam Downstream Slope and Toe</b>	
Slope protection (grass)	<i>yes, sparse in areas, cool spring?</i>
Surface erosion/gullyng	<i>no</i>
Slides or sloughing	<i>no</i>
Settlement/Depressions	<i>no</i>
Bulging	<i>no</i>
Cracks	<i>no</i>
Vegetation growth	<i>yes, some areas sparse</i>
Animal Activity (burrows)	<i>animal tracks,</i>
Any unusual conditions	<i>some areas w/ lack of veg, doesn't seem to be slump, clay top soil?</i>

## TML Sullivan Inspection Checklist

Structure: Recycle Dam

Date: Mar 25 / 22

Inspected by: P. Fines & M. Peltzer

Weather: \_\_\_\_\_

Pond Elevation: \_\_\_\_\_

Snow Cover? YES / NO

Operational Limits: \_\_\_\_\_

Inspection Item	Remarks
<b>Dam Crest Surface</b>	
Cracks	no
Erosion	no
Settlement/Depressions	no
Vegetation growth	grass, no shrubs, slightly tall <span style="float: right;"><small>could be cut</small></span>
Animal Activity (burrows)	not observed
Any unusual conditions	no
Ponding of water	no
<b>Dam Upstream Slope</b>	
Slope protection (riprap)	grass, no rip rap
Surface erosion/gullying	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	no
Animal Activity (burrows)	no
Any unusual conditions	no
<b>Dam Downstream Slope and Toe</b>	
Slope protection (grass)	rock / gravel
Surface erosion/gullying	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	no
Animal Activity (burrows)	no
Any unusual conditions	

## TML Sullivan Inspection Checklist

Structure: NE Gypsum Dam

Date: Mar 25/22

Inspected by: P. Fines & M. Rettger

Weather: \_\_\_\_\_

Pond Elevation: \_\_\_\_\_

Snow Cover? YES / NO

Operational Limits: \_\_\_\_\_

Inspection Item	Remarks
<b>Dam Crest Surface</b>	
Cracks	no
Erosion	no
Settlement/Depressions	no
Vegetation growth	well grassed
Animal Activity (burrows)	no
Any unusual conditions	no
Ponding of water	no
<b>Dam Upstream Slope</b>	
Slope protection (riprap)	N/A
Surface erosion/gullying	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	well grassed
Animal Activity (burrows)	no
Any unusual conditions	no
<b>Dam Downstream Slope and Toe</b>	
Slope protection (grass)	yes
Surface erosion/gullying	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	shrubby, trees
Animal Activity (burrows)	animal paths, tracks
Any unusual conditions	

## TML Sullivan Inspection Checklist

Structure: Old Iron TSF

Date: May 25/22

Inspected by: P. Fines & M. Bretter

Weather: \_\_\_\_\_

Pond Elevation: \_\_\_\_\_

Snow Cover? YES / NO

Operational Limits: \_\_\_\_\_

Inspection Item	Remarks
<b>Dam Crest Surface</b>	
Cracks	no
Erosion	no
Settlement/Depressions	no
Vegetation growth	sparse weeds
Animal Activity (burrows)	no
Any unusual conditions	no
Ponding of water	no
<b>Dam Upstream Slope</b>	
Slope protection (riprap)	grass
Surface erosion/gullyng	no
Slides or sloughing	↓
Settlement/Depressions	
Bulging	
Cracks	
Vegetation growth	
Animal Activity (burrows)	
Any unusual conditions	
<b>Dam Downstream Slope and Toe</b>	
Slope protection (grass)	yes inadequate
Surface erosion/gullyng	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	grass, low & manageable
Animal Activity (burrows)	not observed
Any unusual conditions	

## TML Sullivan Inspection Checklist

Structure: West Gypsum

Date: Mar 26/22

Inspected by: P. Fines & M. Rettger

Weather: 120 - cloudy

Pond Elevation: \_\_\_\_\_

Snow Cover? YES / NO 0

Operational Limits: \_\_\_\_\_

Inspection Item	Remarks
<b>Dam Crest Surface</b>	<i>-some shrubs in spillway</i>
Cracks	no
Erosion	no
Settlement/Depressions	no
Vegetation growth	some grass
Animal Activity (burrows)	yes on shoulder, gopher, 1 badger
Any unusual conditions	no
Ponding of water	no
<b>Dam Upstream Slope</b>	
Slope protection (riprap)	rocks, N/A
Surface erosion/gullyng	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	tall grass
Animal Activity (burrows)	gopher holes
Any unusual conditions	no
<b>Dam Downstream Slope and Toe</b>	
Slope protection (grass)	yes
Surface erosion/gullyng	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	grass, some tall reeds by perimeter
Animal Activity (burrows)	gopher holes at toe + slope
Any unusual conditions	

## TML Sullivan Inspection Checklist

Structure: East Dypsen

Date: May 26/22

Inspected by: P. Fines & M. Bettger

Weather: \_\_\_\_\_

Pond Elevation: \_\_\_\_\_

Snow Cover? YES / NO

Operational Limits: \_\_\_\_\_

Inspection Item	Remarks
<b>Dam Crest Surface</b>	
Cracks	no
Erosion	no
Settlement/Depressions	no
Vegetation growth	no, well gravelled
Animal Activity (burrows)	some gopher on shoulder
Any unusual conditions	no
Ponding of water	no
<b>Dam Upstream Slope</b>	
Slope protection (riprap)	N/A
Surface erosion/gullyng	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	grass
Animal Activity (burrows)	gopher holes
Any unusual conditions	no
<b>Dam Downstream Slope and Toe</b>	
Slope protection (grass)	yes
Surface erosion/gullyng	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	no
Animal Activity (burrows)	YES → gopher & large badger
Any unusual conditions	holes on E half

## TML Sullivan Inspection Checklist

Structure: N+S & S dyke

Date: \_\_\_\_\_

Inspected by: \_\_\_\_\_

Weather: \_\_\_\_\_

Pond Elevation: \_\_\_\_\_

Snow Cover? YES / NO

Operational Limits: \_\_\_\_\_

Inspection Item	Remarks
<b>Dam Crest Surface</b>	
Cracks	No
Erosion	No
Settlement/Depressions	No
Vegetation growth	No, some minor grass
Animal Activity (burrows)	on shoulder of S dyke crest
Any unusual conditions	no
Ponding of water	no
<b>Dam Upstream Slope</b>	
Slope protection (riprap)	yes
Surface erosion/gullyng	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	some vegn
Animal Activity (burrows)	no
Any unusual conditions	no
<b>Dam Downstream Slope and Toe</b>	
Slope protection (grass)	gravel + rocks
Surface erosion/gullyng	no
Slides or sloughing	no
Settlement/Depressions	no
Bulging	no
Cracks	no
Vegetation growth	lots of tall trees & shrubs
Animal Activity (burrows)	no
Any unusual conditions	



## APPENDIX II

### Site Visit Photographs

---

## Appendix II Site Visit Photographs

**Photo II.1 ARD South Dam Upstream Slope**



**Photo II.2 North Dam Upstream Slope**



**Photo II.3 Erosion adjacent to pumphouse**



**Photo II.4 ARD North Dam Downstream Slope**



**Photo II.5**      **Vegetation at toe of North Dam**



**Photo II.6**      **South Dam Downstream Slope**



**Photo II.7 Weir 1 downstream ditch**



**Photo II.8 Weir 2 – AIPWU**



**Photo II.9 Iron Dike Downstream Slope**



**Photo II.10 Iron Dike Crest and Crest of Toe Berm**



**Photo II.11 Overview of Iron Pond**



**Photo II.12 Overview of Iron TSF looking towards Iron Pond**



**Photo II.13 Weir #3**



**Photo II.14 Channel Upstream of Weir #3**





**Photo II.15 Weir #4**



**Photo II.16 Weir #4 worn notch**



**Photo II.17 Emergency Spillway Channel Inlet**



**Photo II.18 Emergency Spillway Channel upper section looking downstream from inlet**



**Photo II.19 Emergency Spillway Channel looking upstream from connection to West Gypsum TSF**



**Photo II.20 Emergency Spillway Channel outlet to Cow Creek**



**Photo II.21 No. 1 Siliceous Dike Downstream Slope**



**Photo II.22 No. 2 Siliceous Dike**



**Photo II.23 No. 3 Siliceous Dike**



**Photo II.24 Seepage downstream of No. 2 Siliceous Dike**



**Photo II.25 Decant outlet channel downstream of No. 3 Siliceous**



**Photo II.26 Siliceous TSF Spillway**



**Photo II.27 Siliceous TSF Spillway on No. 3 Siliceous TSF**



**Photo II.28 East Gypsum Dike downstream slope**



**Photo II.29 West Gypsum Dike downstream slope**



**Photo II.30 Recycle Dam downstream slope**





**Photo II.31 Northeast Gypsum Dike Downstream Side**



**Photo II.32 Sludge Impoundment North Dike downstream slope**



**Photo II.33 Sludge Impoundment South Dike Crest and Upstream Slope**



**Photo II.34 Sludge Impoundment South Dike Downstream Slope**



**Photo II.35 Calcine Dike Crest and Downstream Slope**



**Photo II.36 Old Iron Dike Crest and Upstream Slope**



**Photo II.37 Old Iron Dike downstream slope**



**Photo II.38 Iron TSF Divider Dike**



## APPENDIX III

### 2022 Instrumentation Monitoring

---

## Appendix III Quantifiable Performance Objectives and 2022 Instrumentation Monitoring

### III.1 QUANTIFIABLE PERFORMANCE OBJECTIVES

Quantifiable Performance Objectives (QPOs) have been established for all of the instrumentation and for the freeboard under normal operating conditions for those tailings facilities which have ponds, i.e., ARD Pond and Iron Pond. The QPOs are discussed below.

#### III.1.1 Piezometric

Pneumatic, standpipe, and vibrating wire piezometers are all used at site to monitor phreatic surfaces within the tailings facilities and foundations. The notification levels established for the piezometers, required monitoring frequency and current readings are summarized in Section III.2 Table AIII.3.

The following is required when a notification level is reached for a single instrument:

- Data, data reductions, and calculations are checked for accuracy and correctness
- If no errors are found in the calculations, the Mine Manager is notified that an anomalous reading has been observed and that further assessment must be conducted. The EOR is notified at this time. The EOR will evaluate data for reliability, review data within the general vicinity of the individual instrument. The EOR may require the following:
  - ◆ Check of readout equipment to verify that it is functioning correctly and to verify calibration
  - ◆ Reread instrument and other nearby instruments for confirmation
  - ◆ Adjust on-going monitoring frequency as required
- If it is observed that an instrument or piece of readout equipment has stopped functioning, the Mine Manager and subsequently, the EOR should be notified immediately. If considered critical, a replacement instrument should be installed.

If several instruments within an area of the dikes or dams are observed to exceed the notification levels, then the following is required:

- The Mine Manager and EOR should be notified within 24 hours.
- Monitoring frequency will be increased as needed based on assessment of common trend.
- EOR to assess the dam integrity and may recommend analyses, site visit, or implementation of remedial actions as required.

#### III.1.2 Settlement

There are several methods used to monitor settlement at the Sullivan Mine tailings facilities. These include settlement plates, Sondex settlement gauges, and surveys.

Notification levels have been established for the various settlement measurements. These are summarized along with survey results and required monitoring frequency in Section III.2 Table AIII.4.

The following response is required when the notification level is exceeded at one instrument:

- Notify EoR within 24 hours upon verification of reading exceedance.
- EoR to evaluate data for reliability, and review survey data within the general vicinity of the individual survey monument in question. EoR may recommend repeat measurement and increased on-going monitoring frequency.

If more than one instrument within the facility indicates exceedance of the notification level, then the following is required:

- Notify EoR within 24 hours upon verification of reading exceedance.
- Repeat reading within one week.
- EoR to assess dam integrity and may recommend analyses, site visit, or other action.

### III.1.3 Lateral Movement

There is one inclinometer installed in the East Gypsum Dike to monitor lateral movements. A notification level has been established for the inclinometer and is provided along with the required monitoring frequency in Section III.2 Table AIII.4.

The following response is required when the notification level is exceeded:

- Data reductions are checked for accuracy and correctness.
- EoR to evaluate data for reliability and review other instrumentation in vicinity of the slope inclinometer. Repeat measurement and/or measurement of other instruments may be recommended.
- EoR to assess dam integrity and may recommend analyses, site visit or other action.

### III.1.4 Seepage

There are four weirs installed to measure seepage from the ARD Pond South Dam and the Iron Dike. Notification levels have been established and are provided along with the required monitoring frequency in Section III.2 Table AIII.5.

The following response is required when the notification level is exceeded:

- Data and data reductions are checked for accuracy and correctness.
- EoR to evaluate data for reliability and review other instrumentation in the vicinity. Repeat measurement and/or measurement of other instruments may be recommended.
- EoR to assess dam integrity and may recommend analyses, site visit, or other action.

### III.1.5 Freeboard

There are three notification levels which have been set for the ARD Pond and the Iron Pond, which are provided in Section III.2 Table AIII.6.

Notification Level 1 indicates when the pumps should be started to transfer water to either the Drainage Water Treatment Plant (ARD Pond) or to the ARD Pond (Iron Pond).

Notification Level 2 indicates when water levels are approaching maximum operating levels. When Notification Level 2 is met or exceeded, transfer of water should continue as well as notifying the EOR and minimizing inflows. For the ARD Pond, this could include diverting 3700/39000 to the Iron Pond and for the Iron Pond, stop pumping to the Iron Pond and divert runoff if possible.

Notification Level 3 indicates when water levels are within 0.5 m of the spillway inverts. When Notification Level 3 is met or exceeded, continue with transfer of water, minimizing inflows, notification of the EOR, and notify MEMPR/MOE of potential spill as well as enacting Emergency Preparedness and Response Plan (EPRP).

### III.1.6 Visual Inspections

As part of the QPOs, a series of regularly scheduled inspections is required to ensure that the tailings facilities are operating as intended and to identify problems and issues so that necessary corrective actions may be implemented in a timely manner. The main types of inspections are as follows:

- routine inspections (performed by Teck staff)
- event driven inspections (performed by Teck staff, and the Engineer of Record depending on the event)
- annual inspection (performed by the Engineer of Record)
- dam safety review (performed by an independent and qualified professional engineer)

#### *Routine Visual Inspections*

Routine visual inspections are performed by Teck staff and documented using one of the standard inspection forms, which are included in Appendix E of the OMS Manual. Two types of forms are provided: one for Weekly/Bi-weekly inspections and forms for Monthly/Annual inspections.

The minimum visual inspection frequency for each of the structures can be found in Table III-1.



**Table III-1 Visual Inspection Requirements for the Dikes and Dams at Sullivan Mine**

Dike		CDA Classification	Pond Elevation	Visual Inspection Requirements
ARD Pond Dikes		Very High	< 1040 m	Monthly
			>1040 m	Weekly (a Monthly Inspection form must be filled in once per week if pond is high for an extended period of time, i.e., greater than one month)
Iron Dike (STA 0+00 to 10+00)		High	N/A	Monthly
Iron Dike (STA 10+00 to end of dam)		High	N/A <sup>1</sup>	Annually
Old Iron TSF	Old Iron Dike	Low	N/A <sup>1</sup>	Annually
	Iron TSF Divider Dike	Low		
Siliceous Cell Dikes #1, #2 and #3		Low		Annually
Gypsum TSF	West Gypsum Dike	High		Annually
	East Gypsum Dike	High		Annually
Northeast Gypsum Dike and Recycle Dam		Low		Annually
Calcine Dike		Low		Annually
Sludge Pond		Low		N/A

**Note:** <sup>1</sup> Closed facility, no active pond

The following is a list of general information that should be recorded (monthly and annual inspections):

- signs of depressions and/or movements of the downstream dam/dike slope
- general condition of the dam/dike crest, toe, and faces, looking for settlement, erosion, seepage, cracking, animal burrows, vegetation growth or other abnormal conditions
- water levels in active ponds
- depth of flow in spillways (record zero flow in spillway as 0.0 m<sup>3</sup>)
- issues related to blockage and inadequate capacity of spillway channels
- seepage noting change in flow rate and visual cloudiness and any new seepage

Documentation of the routine inspections should be submitted to the Mine Manager following each inspection. If any maintenance requirements or anomalies are identified during the inspection, these must be identified to the mine manager.

The annual routine inspection by Teck staff should be planned such that it does not coincide with the annual inspection performed by the Engineer of Record. The annual routine inspection should include photographs of key features and any potential dam/dike safety concerns.

The completed inspection forms are stored in an electronic data base system, and hard copies of the inspection forms are catalogued and stored at Sullivan Mine.

### Event Driven Inspections

In addition to routine inspections, special inspections may be required for significant seismic or climatic events, or anomalous instrumentation readings. Table III-2 presents the specific inspections to be carried out following specified events. All events involve immediate inspection by Teck staff, followed if required by notification to or inspection by the Engineer of Record.

**Table III-2 Event Driven Inspections**

Item	Event	Action	Comment
Embankments	Earthquake M5 or bigger within 100 km	Immediate inspection by Teck staff	Call the Engineer of Record if damage is noted
		Read all instruments within one week	Send instrument data to the Engineer of Record
	Earthquake M6 or bigger within 100 km	Inspection by the Engineer of Record Read all instruments	
	Rainfall (50 year event): 6 hour > 40 mm 24 hour > 56 mm Snowpack (50 year event): Accumulated snow water equivalent > 360 mm	Check and record water ponding Check dam toe seepage daily Drawdown water level if necessary	
	DWTP water delivery system fails	Check water level in the ARD Pond and Iron Pond daily Check rainfall daily Prepare standby pumps if required	Call the Engineer of Record if one pond is more than 75% full
	Instability or noticeable deformation, displacement of riprap.	Inspection by the Engineer of Record	
Surface Water Conveyance System	Rainfall (50 year event): 6 hour > 40 mm 24 hour > 56 mm Snowpack (50 year event): Accumulated snow water equivalent > 360 mm	Check and record water flow and ponding Check channels for debris Check channels for damage to riprap lining	

### Annual Inspections

Annual inspections shall be carried out by the Engineer of Record for the tailings facilities for Sullivan Mine. The objective of the annual inspection is to confirm the routine inspections carried out, and to carry out a review of the conditions of the facilities and facility operation. The site water balance is reviewed to confirm the inputs and assumptions are still valid according to the current conditions.

The Engineer of Record issues an annual inspection report to the Mine Manager containing observations and recommendations. This report provides information to be used to revise the operation, maintenance, and surveillance programs as necessary and to assist in planning for future operation of the facility. The annual inspection reports are issued to the British Columbia Ministry of Environment (BC MOE) by March 31 each year (as stated in Permit No. 74). Copies of the annual inspection report are to be stored at Sullivan Mine.

## III.2 INSTRUMENT DATA SUMMARY

The lists of active instruments and measurement points, along with alarm notification levels and maximum readings from the 2022 DSI reporting period, are shown in Tables AIII.3, AIII.4, AIII.5, and AIII.6. Updated instrument readings were provided to KCB by Vast Resources (Vast) and Teck staff on several occasions from September 2021 to August 2022. Vast of Cranbrook, British Columbia is contracted by Teck to read the pneumatic and standpipe piezometers, and WSP to survey the settlement plates and dike crests. The daily/weekly readings for the weirs and ARD Pond standpipes were performed by Teck staff. Copies of the plots that were produced for each impoundment area are included in Appendix IV through Appendix X.

**Table III-3 Active Piezometers – Iron TSF**

Group Designation	Piezometer No.	Northing	Easting	Elevation Ground (m)	Top of Casing Elevation (m)	Tip/Bottom of Casing (m)	General Location	Instrument Type	Recommended Reading Frequency	Notification Level (m)	Max Measured Piezometer Level In 2022 <sup>1</sup> (m)	Max 2022 Level Relative To 2021 <sup>2</sup>	Comment
<b>Iron TSF</b>													
Line 6+00	P91 – 1	5500541.5	576470.5	1037.3	N/A	1023.0	Dike	Pneumatic	Three times a year (spring, summer and fall)	1028.4	1023.2 2022-05-18	↓	
	P91 – 2A	5500512.5	576459.9	1029.7	N/A	1020.1	Road	Pneumatic		1026.9	1023.0 2022-05-18	↑	
	P91 – 2B	5500511.9	576462.4	1029.3	N/A	1021.5	Road	Pneumatic		1026.9	1023.1 2022-05-18	↔	
Line 16+00	SB – P15	5500739.4	576803.0	1033.9	N/A	1029.0	Iron TSF	Pneumatic		1036.2	1032.6 2022-05-18	↔	
	P91 – 3A	5500660.4	576707.5	1038.4	N/A	1008.6	Dike	Pneumatic		1024.8	1023.4 2022-05-18	↓	
	P91 – 3B	5500661.3	576708.4	1038.3	N/A	1023.7	Dike	Pneumatic		1025.8	1023.7 N/A	↔	Dry
	P91 – 3C	5500660.4	576709.0	1038.9	N/A	1021.3	Dike	Pneumatic		1025.8	1021.9 2021-10-26	↓	
	P91 – 4	5500630.6	576730.8	1031.5	N/A	1017.2	Bench	Pneumatic		1022.0	1020.2 2020-05-18	↓	
	P92 – 20	5500593.9	576760.7	1033.0	N/A	1010.4	Bench	Pneumatic		1015.9	1015.2 2022-05-18	↔	
	P92 – 21	5500595.8	576762.3	1033.0	N/A	1012.2	Bench	Pneumatic		1015.9	1015.5 2022-05-18	↑	
Line 24+00	P91 – 5A	5500482.1	576931.7	1039.7	N/A	1017.7	2400 Bench at Dike	Pneumatic		1031.8	1030.8 2022-05-18	↑	
	P91 – 5B	5500786.8	576930.2	1039.7	N/A	1026.7	2400 Bench at Dike	Pneumatic		1030.0	1027.0 2021-10-26	↓	
	P91 - 6	5500752.7	576941.0	1031.5	N/A	1020.5	2400 Bench at Dike	Pneumatic	1023.6	1022.7 2022-05-18	↔		
Line 30+00	P92 – 1	5500893.9	577066.3	1035.1	N/A	1021.1	91 Dike	Pneumatic	1033.0	1031.4 2022-05-18	↑		
	P92 – 2	5500865.9	577113.8	1028.6	N/A	1024.0	Slope	Pneumatic	Monthly	1027.8	1026.5 2022-04-01	↑	
Line 38+00	P92 – 6	5501125.1	577156.5	1042.1	N/A	1024.2	91 Dike	Pneumatic	Three times a year (spring, summer and fall)	1033.6	1031.9 2022-05-18	↑	
	P92 – 7	5501118.0	577174.9	1040.2	N/A	1029.6	Slope	Pneumatic		1032.7	1030.4 2022-05-18	↑	
	P92 – 9	5501097.9	577314.6	1029.9	N/A	1025.3	Toe	Pneumatic		1028.4	1027.7 2022-05-18	↑	
Line 42+00	P92 – 11	5501217.8	577335.4	1031.5	N/A	1025.0	Toe	Pneumatic		1028.4	1025.6 2022-05-18	↑	
	P91 – 11A	5501258.1	577172.2	1042.4	N/A	1027.0	91 Dike	Pneumatic		1036.7	1033.2 2022-05-18	↓	
	P91 – 11B	5501258.1	577172.2	1042.3	N/A	1029.9	91 Dike	Pneumatic		1036.7	1033.3 2022-05-18	↓	
	P91 – 12	5501209.4	577418.1	1040.9	N/A	1029.7	Slope	Pneumatic		1034.5	1032.9 2022-05-18	↔	

Group Designation	Piezometer No.	Northing	Easting	Elevation Ground (m)	Top of Casing Elevation (m)	Tip/Bottom of Casing (m)	General Location	Instrument Type	Recommended Reading Frequency	Notification Level (m)	Max Measured Piezometer Level In 2022 <sup>1</sup> (m)	Max 2022 Level Relative To 2021 <sup>2</sup>	Comment
<b>Iron TSF</b>													
	P92 - 16	5501237.6	577246.4	1037.3	N/A	1027.6	Slope	Pneumatic		1030.6	1029.1 2022-05-18	↑	
Line 45+00	P92 - 13	5504074.8	577182.3	1040.5	N/A	1031.3	91 Dike	Pneumatic		1037.3	1031.3 2022-05-18	↓	Dry
	P92 - 14	5504071.7	577199.9	1037.4	N/A	1029.6	Slope	Pneumatic		1036.8	1034.0 2022-05-18	↑	
	P92 - 15	5501320.2	577314.9	1030.3	N/A	1029.0	Toe	Pneumatic		1030.3	1029.3 2020-10-19	↑	
	P5	5501660.5	577228.4	1039.1	1041.6	1037.4	Toe at Siliceous Cell #1	Standpipe	Annually	1039.5	1038.6 2022-04-05	↑	
Toe Piezometers	P92 – H	5500665.1	576891.7	1025.6	N/A	998.1	21+00	VWP	Remotely monitored (hourly readings). Review data monthly.	1032.0	1025.8 2022-04-18	↔	
	P92 – 25	5500806.7	577125.8	1022.9	N/A	999.0	28+00	Pneumatic	Monthly	1032.0	1029.2 2022-04-01	↑	
	P92 – 26	5500550.3	576802.5		1019.8	1009.1	16+00	Standpipe	Three times a year (spring, summer and fall)	1015.0	1014.5 2022-04-01	↑	

**Notes:**

- 2022 reporting period runs from September 1, 2021 to August 31, 2022.
- Water levels are considered equal if differences are ≤ 0.1 m.

**Table III-4 Active Piezometers – Old Iron TSF**

Group Designation	Piezometer No.	Northing	Easting	Ground Elevation (m)	Top of Casing Elevation (m)	Tip/Bottom of Casing (m)	General Location	Instrument Type	Recommended Reading Frequency	Notification Level	Max Measured Piezometer Level In 2022 <sup>1</sup>	Max 2022 Level Relative To 2021 <sup>2</sup>	Comment	
<b>Old Iron TSF</b>														
Old Iron Dike	P93 – 17	5500680.3	575451.9	1043.0	1043.0	1025.8	Dike	Standpipe	Three times a year (spring, summer and fall)	1037.3	1036.5 2022-04-05	↑		
	P93 – 18	5500701.7	575475.6	1044.4	1044.7	1028.3	Dike	Standpipe		1039.0	1037.8 2022-04-05	↔		
	<del>P96 – 08</del>	-	-	-	N/A	Unknown	MCE Buttress	Pneumatic		2.6 <sup>3</sup>	-	-	-	Replaced with new vibrating wire piezometer in 2018.
	<del>P96 – 11</del>	Not available	Not available	Not available	Not available	Not available	MCE Buttress	Pneumatic		-1.5	-	-	-	Slow leak, erratic data, replaced with new vibrating wire piezometer in 2018.
	P96 – 12	5500652.6	575518.6		N/A	Unknown	MCE Buttress	Pneumatic		0.9 <sup>3</sup>	0.1 2022-04-05	↑		
	SUL-01D-VWP-18-01 A&B	5500688.4	575449.2	1043.4	Tip A:	1025.8	MCE Buttress	VWP	Remotely monitored (hourly readings). Review data monthly.	Pending review	1037.0 2022-05-21	↑		
					Tip B:	1036.5				Pending review	1036.5 2022-04-06	↑		
SUL-01D-VWP-18-02 A&B	5500633.2	575431.2	1040.1	Tip A:	1016.6	MCE Buttress	VWP	Pending review		1034.7 2022-04-13	↑			
				Tip B:	1035.5			Pending review		1035.4 2022-01-27	↓			
Iron TSF Divider Dike	P93 – 19	5500962.3	575892.0	1042.6	1043.6	1025.6	Dike	Standpipe	Annual	1040.15	1039.8 2022-04-05	↓		
	P93 – 20	5501191.4	575943.2	1044.1	1045.3	1026.4	Dike	Standpipe		1041.25	1040.1 2022-04-05	↔		

**Notes:**

- 2022 reporting period runs from September 1, 2021 to August 31, 2022.
- Water levels are considered equal if differences are ≤ 0.1 m.
- Installation elevation not known.

**Table III-5 Active Piezometers – Siliceous TSF**

Group Designation	Piezometer No.	Northing	Easting	Ground Elevation (m)	Top of Casing Elevation (m)	Tip/Bottom of Casing (m)	General Location	Instrument Type	Recommended Reading Frequency	Notification Level	Max Measured Piezometer Level In 2022 <sup>1</sup>	Max 2022 Level Relative To 2021 <sup>2</sup>	Comment	
<b>Siliceous Dikes</b>														
West Side Siliceous Dike #1	P5	5501660.5	577228.4	1039.1	1041.6	1037.4	Cell #1	Standpipe	P105 and P5 annually unless change > 0.5 m or at notification levels then read all Piezometers	1039.5	1038.6 2022-04-05	↑		
	SP101	5501176.3	577719.3	1035.4	1036.4	1021.6	Cell #1	Standpipe		1023.9	1021.7 2022-04-01	↔		
Middle Siliceous Dike #1	P105	5501220.6	577927.9	1033.0	1033.2	1021.3	Cell #1	Standpipe		1022.0	1030.0 2022-04-01	↓	Max. 2019, 2020 & 2021 readings above notification level. Casing likely blocked.	
	<del>SP104</del>	<del>5501248.9</del>	<del>577910.8</del>	<del>1035.4</del>	<del>1035.1</del>	<del>1021.1</del>	<del>Cell #1</del>	<del>Standpipe</del>		<del>1022.0</del>	<del>N/A</del>			Blocked at 1031.3
East Side Siliceous Dike #1	SP106	5501410.5	578028.7	1034.1	1034.7	1020.9	Cell #1	Standpipe		1021.4	1021.1 2022-04-01	↔		
Crest Siliceous Dike #2	P231	5500962.2	577497.5	1031.2	1031.2	1019.5	Cell #2	Standpipe	Annual (Spring)	1022.3	1020.7 2022-04-01	N/A	No reading in 2021	
	P257	5500971.0	577407.3	1031.3	1030.4	1022.0	Cell #2	Standpipe		1025.0	1022.4 2022-04-01	↓		
	P91 – 13	5500964.5	577413.7	1029.7	N/A	1020.0	Cell #2	Pneumatic	Three times a year (spring, summer and fall)	1025.0	1021.6 2022-05-18	↓		
Lines 3+00/7+00 Siliceous Dike #3	<del>P303</del>	<del>5500977.6</del>	<del>577855.0</del>	<del>1029.1</del>	<del>1029.3</del>	<del>1020.9</del>	<del>7+00 Crest</del>	<del>Standpipe</del>	P232, P301 and P303 annually unless change > 0.5 m then read all Piezometers	<del>1022.3</del>	<del>1020.9</del> <del>2021-04-12</del>	↔	Dry Replaced by SUL-SD3-VWP-18-08	
	<del>P301</del>	<del>5500973.6</del>	<del>577739.0</del>	<del>1028.1</del>	<del>1029.4</del>	<del>1020.6</del>	<del>3+00 Crest</del>	<del>Standpipe</del>		<del>1022.3</del>	<del>1020.6</del> <del>2021-04-12</del>	↔	Replaced by SUL-SD3-VWP-18-06	
	<del>P302</del>	<del>5500963.3</del>	<del>577739.5</del>	<del>1025.7</del>	<del>1027.2</del>	<del>1021.0</del>	<del>3+00 Slope</del>	<del>Standpipe</del>		<del>1021.2</del>	<del>1021.1</del> <del>2021-04-12</del>	↔	Replaced by SUL-SD3-VWP-18-07	
	P232	5500968.5	577854.3	1026.7	1027.3	1017.4	7+00 Slope	Standpipe		1019.3	1017.9 2022-04-01	↓		
	P233	5500959.1	577853.8	1023.6	1024.3	1017.9	7+00 Slope	Standpipe	1019.3	1017.9 2022-04-01	↔	Dry		
	SUL-SD3-VWP-18-06 A&B	5500975.7	577751.2	1029.2	Tip A:	1008.8	3+00 Crest	VWP	Remotely monitored (hourly readings). Review data monthly.	Pending review	1014.9 2022-08-31	↔		
					Tip B:	1018.5		VWP		Pending review	1018.0 2022-08-31	N/A	Dry	
	SUL-SD3-VWP-18-07	5500920.1	577753.0	1017.1	Tip A:	1006.1	3+00 Toe	VWP		Pending review	1014.7 2021-04-13	↓		
	SUL-SD3-VWP-18-08 A&B	5500985.8	577874.7	1029.6	Tip A:	1009.6	7+00 Crest	VWP		Pending review	1014.1 2020-09-08	↓		
					Tip B:	1017.3		VWP		Pending review	1018.3 2020-12-02	↔		
<del>SUL-SD3-VWP-18-09</del>	<del>5500919.4</del>	<del>577852.5</del>	<del>1016.8</del>	<del>Tip A:</del>	<del>1013.4</del>	<del>7+00 Toe</del>	<del>VWP</del>	<del>Pending review</del>				N/A	Non-functioning	
Siliceous Dike #3 East Side	P306	5501100.8	578268.9	1028.4	1029.6	1020.9	Crest	Standpipe		Monthly first 12 months then annual (in Spring)	Pending review	1021.0 2022-04-01	↔	Stopped reading in 2004 as dry since 1985. Reinstated 2019. Top of casing to be re-surveyed.
	P307	5501088.7	578278.1	1026.1	1027.0	1020.2	Crest	Standpipe			Pending review	1020.5 2022-04-01	↔	Stopped reading in 2004 as dry since 1985. Reinstated 2019. Top of casing to be re-surveyed. Notification level to be

Group Designation	Piezometer No.	Northing	Easting	Ground Elevation (m)	Top of Casing Elevation (m)	Tip/Bottom of Casing (m)	General Location	Instrument Type	Recommended Reading Frequency	Notification Level	Max Measured Piezometer Level In 2022 <sup>1</sup>	Max 2022 Level Relative To 2021 <sup>2</sup>	Comment
<b>Siliceous Dikes</b>													
													etermined following survey and review of readings since 2019.
	P308	5501293.0	578310.5	1028.8	1030.0	1020.8	Crest	Standpipe		Pending review	1021.2 2022-04-01	↔	Stopped reading in 2004 as dry since 1985. Reinstated 2019. Top of casing to be re-surveyed. Notification level to be determined following survey and review of readings since 2019.
	P311	5501659.8	578325.4	1028.8	1030.0	1022.5	Crest	Standpipe		Pending review	1022.8 2022-04-01	↔	Stopped reading in 2004 as dry since 1985. Reinstated 2019. Top of casing to be re-surveyed. Notification level to be determined following survey and review of readings since 2019.
Siliceous Dike #3	SUL-SD3-P-18-10	5501022.5	578270.0	1018.1	1019.4	1004.8	Toe	Standpipe	Monthly	Pending review	1013.5 2022-04-01	↓	
	SUL-SD3-P-18-11	5501452.7	578349.6	1022.1	1023.5	1013.1	Toe	Standpipe		Pending review	1015.5 2022-04-01	↑	

**Notes:**

- 2022 reporting period runs from September 1, 2021 to August 31, 2022.
- Water levels are considered equal if differences are ≤ 0.1 m.



**Table III-6 Active Piezometers – Gypsum TSF**

Group Designation	Piezometer No.	Northing	Easting	Ground Elevation (m)	Top of Casing Elevation (m)	Tip/Bottom of Casing Elevation (m)	General Location	Instrument Type	Recommended Reading Frequency	Notification Level	Max Measured Piezometer Level In 2022 <sup>1</sup>	Max 2022 Level Relative To 2021 <sup>2</sup>	Comment
<b>Gypsum TSF</b>													
West Gypsum Dike Line 10+00	P93 – 1	5499811.6	576419.4	1013.8	1014.9	1000.0	Upstream	Standpipe	Three times a year (spring, summer and fall)	1008.0	1004.0 2021-11-01	↓	
	P93 – 2	5499811.0	576420.9	1014.4	1014.4	996.8	Upstream	Standpipe		1008.0	1003.9 2021-11-01	↓	
	P93 – 3	5499789.6	576411.6	1017.5	1016.1	998.0	Crest	Standpipe		1008.0	1003.7 2021-11-01	↓	
	P93 – 4	5499790.2	576409.5	1017.5	1016.4	995.4	Crest	Standpipe		1008.0	1004.0 2021-11-01	↓	
	P93 – 5	5499751.1	576388.7	1011.1	1011.9	993.3	Downstream	Standpipe		1008.0	995.0 2022-04-01	↓	
West Gypsum Dike Line 20+00	<del>P93 – 6</del>	<del>5499691.8</del>	<del>576696.5</del>	<del>1014.4</del>	<del>1014.9</del>	<del>997.9</del>	<del>Upstream</del>	<del>Standpipe</del>	Three times a year (spring, summer, and fall)	<del>1008.0</del>	-	-	Standpipe blocked at ~ 10.4 m
	P93 – 7	5499670.8	576688.2	1015.3	1016.6	997.2	Crest	Standpipe	Three times a year (spring, summer, and fall)	1008.0	997.5 2021-11-01	↓	
	SUL-WG-P-18-03	5499599.9	576662.0	1001.5	1002.9	984.5	Toe	Standpipe	Monthly	Pending review	993.9 2021-09-09	↓	
East Gypsum Dike Line 33+00	P93 – 8	5499642.3	577074.1	1017.2	1017.7	1001.9	Upstream	Standpipe	Annual	1010.1	1007.9 2022-04-01	↓	
	P93 – 9	5499642.6	577072.6	1017.2	1017.8	998.9	Upstream	Standpipe		1010.1	1008.3 2022-04-01	↓	
	P93 – 10	5499640.6	580423.8	1017.5	1018.0	1002.6	Crest	Standpipe		1009.5	1007.0 2022-04-01	↓	
	P93 – 11	5499622.5	577071.1	1017.5	1018.0	998.7	Crest	Standpipe		1008.6	1007.2 (9-Jul-2019)	↔	Blocked, not read in 2020,2021 and 2022 monitoring period
	P93 – 12	5499583.8	577073.5	1013.5	1013.0	1000.8	Toe	Standpipe		1004.7	1003.6 2022-04-01	↓	
	SUL-EG-P-18-04	5499537.0	577196.9	1004.6	1005.9	998.1	Toe	Standpipe	Monthly	Pending review	1000.6 2022-04-01	↓	
East Gypsum Dike Line 48+00	P93 – 13	5499669.6	577521.5	1016.8	1017.6	1000.3	Upstream	Standpipe	Annual	1002.5	1000.4 (5-Apr-2019)	N/A	Not read in 2020,2021 and 2022
	P93 – 14	5499645.3	577521.9	1017.2	1017.7	1004.3	Crest	Standpipe		1005.6	1004.6 2021-04-15	↔	Dry, blocked at 13.3 m
	SUL-EG-P-18-05	5499566.3	577527.0	1003.1	1004.5	995.8	Toe	Standpipe	Monthly	Pending review	999.5 2022-04-01	↓	

**Notes:**

- 2022 reporting period runs from September 1, 2021 to August 31, 2022.
- Water levels are considered equal if differences are ≤ 0.1 m.

**Table III-7 Active Piezometers – ARD Storage Pond**

Group Designation	Piezometer No.	Northing	Easting	Ground Elevation (m)	Top of Casing Elevation (m)	Tip/Bottom of Casing Elevation (m)	General Location	Instrument Type	Recommended Reading Frequency	Notification Level	Max Measured Piezometer Level In 2021 <sup>1</sup>	Max 2022 Level Relative To 2021 <sup>2</sup>	Comment	
<b>ARD Storage Pond</b>														
North Dam	PP01-01	5500675.6	575840.0	N/A	N/A	1041.7	North Dam	Pneumatic	Monthly, with additional readings taken weekly when the Pond level is above 1040 masl, or daily when the Pond level is above 1045 masl. The pneumatic piezometers are to be read monthly.	1042.7	1042.0 2022-03-06	↑		
	PP01-02	5500682.7	575834.9	N/A	N/A	1041.9	North Dam	Pneumatic		1042.7	1042.3 2022-03-06	↑		
	PP01-03	5500552.0	575738.1	N/A	N/A	1038.8	North Dam	Pneumatic		1039.8	1039.6 2022-03-06	↑		
	PP01-04	5500549.5	575743.1	N/A	N/A	1040.8	North Dam	Pneumatic		1041.8	1041.5 2022-04-01	↑		
	ND-01	5500756.6	575907.3	1042.2	1042.7	1032.0	North Abutment	Standpipe		1042.2	1040.6 2022-04-01	↑		
	ND-02D	5500636.4	575769.0	1042.2	1042.7	1019.5	Toe	Standpipe		1041.5	1040.6 2022-01-21	↑		
	ND-02S	5500636.3	575768.9	1042.2	1042.7	1040.3	Toe	Standpipe		1041.5	1041.4 2021-03-25	↔		
	ND-03	5500542.8	575693.1	1038.4	1039.2	1025.1	Toe	Standpipe		1039.2	1038.7 2022-04-01	↑		
South Dam	PP01-05	5500026.7	575892.8	N/A	N/A	1030.0	South Dam	Pneumatic	Remotely monitored (hourly readings). Review data monthly.	1031.0	1031.2 2022-02-08	↑	2022 max above notification level	
	PP01-06	5500020.4	575893.4	N/A	N/A	1029.2	South Dam	Pneumatic		1030.5	1031.1 2022-02-08	↑	2022 max and most recent reading above notification level	
	SD-01	5500056.6	576006.3	1041.0	1041.6	1029.6	South Abutment	Standpipe		1041.0	1034.3 2022-04-01	↔		
	SD-02	5499985.4	575904.0	1029.9	1030.5	1026.9	Toe	Standpipe		1029.9	1029.7 2022-07-01	↑		
	SD-03	5499995.4	575737.2	1037.0	1038.1	1036.0	South Abutment	Standpipe		1037.0	1036.9 2022-03-18	↑		
	SUL-ARDSD-VWP-20-01	5500086.0	576003.0	1048.0	N/A	1037.54		VWP		Pending Review	1040.5	1040.5 2022-03-22	N/A	Instrument began recording in October 2021
	SUL-ARDSD-VWP-20-02	5500060.0	576015.0	1041.0	N/A	1036.28		VWP			1037.9	1037.9 2022-04-03	N/A	Instrument began recording in October 2021
	SUL-ARDSD-VWP-20-03	5500036.0	576030.0	1037.0	N/A	1033.19		VWP			1033.5	1033.5 2022-04-13	N/A	Instrument began recording in October 2021
SUL-ARDSD-VWP-20-04	5500009.0	575972.0	1031.0000	N/A	1026.7700		VWP	1030.4	1030.4 2022-03-08		N/A	Instrument began recording in October 2021		

- Notes:**
- 2022 reporting period runs from September 1, 2021 to August 31, 2022.
  - Water levels are considered equal if differences are ≤ 0.1 m.

**Table III-8 Active Piezometers – Sludge Impoundment**

Group Designation	Piezometer No.	Northing	Easting	Ground Elevation (m)	Top of Casing Elevation (m)	Tip/Bottom of Casing Elevation (m)	General Location	Instrument Type	Recommended Reading Frequency	Notification Level	Max Measured Piezometer Level In 2021 <sup>1</sup>	Max 2021 Level Relative To 2020 <sup>2</sup>	Comment
<b>Sludge Impoundment</b>													
North Dam	SUL-SPND-VWP-21-01	5497697.0	574643.0	890.5	N/A	884.71	North Dam	VWP	Remotely monitored (hourly readings). Review data monthly.	Pending review	887.13 2022-04-07	N/A	Instrument began recording in October 2021
	SUL-SPND-VWP-21-02	5497643.0	574659.0	894.5	N/A	879.57	North Dam	VWP			887.33 2022-04-07	N/A	Instrument began recording in October 2021
	SUL-SPND-VWP-21-05	5497663.0	574643.0	894.5	N/A	884.04	North Dam	VWP			886.73 2022-04-07	N/A	Instrument began recording in October 2021
South Dam	SUL-SPSD-VWP-21-03	5497285.0	574865.0	888.0	N/A	879.85	South Dam	VWP			886.20 2022-04-07	N/A	Instrument began recording in October 2021
	SUL-SPSD-VWP-21-04	5497186.0	574842.0	894.5	N/A	874.18	South Dam	VWP			885.80 2022-04-07	N/A	Instrument began recording in October 2021
	SUL-SPSD-VWP-21-06	5497240.0	574844.0	894.5	N/A	879.56	South Dam	VWP			885.3 2022-06-28	N/A	Instrument began recording in October 2021

**Notes:**

1. 2022 reporting period runs from September 1, 2021 to August 31, 2022.
2. Water levels are considered equal if differences are ≤ 0.1 m.

**Table III-9 Active Settlement and Inclinator Measuring Instruments**

Type	Instrument Number	Initial Elevation (m)	Location	Notification Level	Recommended Reading Frequency	Measured Level in 2021 (m)	Comment <sup>2</sup>
<b>Iron Dike</b>							
Settlement plates	SP330 <sup>1</sup>	1037.40	2+00	>25 mm over 3 years	Every 3 Years	N/A	Surveyed in 2018. Less than 40 mm of settlement since 2007.
	SP331 <sup>1</sup>	1042.44	9+00			N/A	Surveyed in 2018. Less than 65 mm of settlement since 2007.
	SP332 <sup>2</sup>	1041.79	9+00			N/A	Surveyed in 2018. Less than 45 mm of settlement since 2007.
	SP 92 – 07	1034.91	16+00			N/A	Surveyed in 2018. Less than 35 mm of settlement since 2007.
	SP 99 – 01 <sup>3</sup>	1042.07	4+00			N/A	Surveyed in 2018. Less than 45 mm of settlement since 2007.
Dike Crest Survey	-	-	0+00 to 12+00 centerline, U/S, D/S dike crest	1042 m	Annually	N/A	Moved to InSAR monitoring.
<b>Gypsum TSF Dikes</b>							
Settlement plates at West Gypsum Dike	SP97 – 01	1014.592	Line 10+00 Slope	>60 mm over 3 years	Annually	N/A	Settled 0 mm since 2017.
	SP97 – 05	1015.568	Line 10+00 Crest			N/A	Settled 23 mm since 2017.
	SP97 – 06	1015.936	Line 20+00 Slope			N/A	Settled 22 mm since 2017.
Sondex gauge and Inclinator at West Gypsum Dike	S94 – 01	N/A	Line10+00 Upstream	>90 mm over 3 years	Every 3 Years	N/A	Reading taken in 2019. Cumulative change since 1994 of 1.720, incremental change since 2016 of 0.14.
	<del>BI94-01</del>	<del>N/A</del>	<del>Line10+00 Upstream</del>	<del>N/A</del>	<del>Inactive</del>	<del>N/A</del>	Inclinator blocked since 2006 (last read in 2004). Do not replace unless other instruments indicate signs of movement.
Settlement plates at East Gypsum Dike	SP97 – 03	1017.676	Line 33+00	>60 mm over 3 years	Annually	N/A	Settled 17 mm since 2017..
	SP97 – 04	1017.457	Line 48+00		Annually	N/A	Settled 28 mm since 2017.
Sondex gauge and Inclinator at East Gypsum Dike	S94 – 02	N/A	Line 33+00 Upstream	>60 mm over 3 years	Every 3 Years	N/A	Reading taken in 2019. Cumulative change since 1994 of 1.02, incremental change since 2016 of 0.08.
	BI94 – 02	N/A	Line 33+00 Upstream	>25 mm horizontal movement over 3 years	Every 3 Years	N/A	Reading in inclinometer are now very unreliable due to settlement of the casing. Do not replace unless other monitoring indicate signs of movement.
Settlement plates at N.E. Gypsum Dike	SW (S1)	1019.264	Main Dike	>5 mm over 3 years	Every 3 Years	N/A	Surveyed in 2018. Less than 2 mm of settlement since 2007.
	SE (S2)	1019.073	Main Dike		Every 3 Years	N/A	Surveyed in 2018. Essentially 0 mm of settlement since 2007.
<b>ARD Storage Pond</b>							
Settlement Plates	SP01-01	1048.009	North Dam	>25 mm over 3 years	Every 3 Years	N/A	Surveyed in 2018. Less than 7 mm of settlement since 2001
	SP01-02	1048.224	North Dam			N/A	Surveyed in 2018. Less than 15 mm of settlement since 2001.
	SP01-03	1048.113	North Dam			N/A	Surveyed in 2018. Less than 19 mm of settlement since 2001.
	SP01-04	1048.311	South Dam			N/A	Surveyed in 2018. Less than 8 mm of settlement since 2001.
	SP01-05	1048.310	South Dam			N/A	Surveyed in 2018. Essentially 0 mm of settlement since 2001.
	SP01-06	1048.351	South Dam			N/A	Surveyed in 2018. Less than 9 mm of settlement since 2001.
<b>Sludge Impoundment Dikes</b>							
Dike Crest Survey	-	-	North Dike centerline, U/S, D/S dike crest	894.6	Annually	N/A	
			South Dike centerline, U/S, D/S dike crest	894.6	Annually	N/A	

**Notes:**

1. SP330 and 331 lowered in 2006. (2) SP332 raised in 2004. (3) SP99-01 lowered in 2006.
2. Ground based survey is being replaced with InSAR review of settlement and movement trends.

**Table III-10 Active Seepage Measurements September 1, 2021 – August 31, 2022**

Structure/ Weir	Min. Current Reading Frequency	Notification Level	Weir Readings and Observations – September 1, 2021 to August 31, 2022																							
			September		October		November		December		January		February		March		April		May		June		July		August	
			Max. flow	Min. flow	Max. flow	Min. flow	Max. flow	Min. flow	Max. flow	Min. flow	Max. flow	Min. flow	Max. flow	Min. flow	Max. flow	Min. flow	Max. flow	Min. flow	Max. flow	Min. flow	Max. flow	Min. flow	Max. flow	Min. flow	Max. flow	Min. flow
			m <sup>3</sup> /day		m <sup>3</sup> /day		m <sup>3</sup> /day		m <sup>3</sup> /day		m <sup>3</sup> /day		m <sup>3</sup> /day		m <sup>3</sup> /day		m <sup>3</sup> /day		m <sup>3</sup> /day		m <sup>3</sup> /day		m <sup>3</sup> /day		m <sup>3</sup> /day	
ARD Pond/Weir #1 (ARDWU)	Weekly with daily readings between March 1 and May 30. Daily readings when the pond level is > 1045 m. Read for 3 days following rainfall event >10 mm.	150 m <sup>3</sup> /day	20.42	0.11	7.68	0.11	2.77	0.11	0.11	0.11	13.13	0.11	41.17	0.11	54.93	13.13	29.71	3.87	29.71	1.51	7.68	0.11	0.11	0.11	7.68	0.11
ARD Pond/Weir #2	Weekly with daily readings between March 1 and May 30. Daily readings when the pond level is > 1045 m. Read for 3 days following rainfall event >10 mm.	175 m <sup>3</sup> /day	0.88	Dry	5.78	Dry	5.78	Dry	0.88	Dry	10.40	Dry	16.73	Dry	79.50	12.72	24.93	0.88	24.93	0.11	5.78	Dry	Dry	Dry	Dry	Dry
AIP <sup>1</sup> Dike/Weir #3 (AIPWU)	Weekly with daily readings between March 1 and May 30. Read for 3 days following rainfall event >10 mm.	50 m <sup>3</sup> /day	0.93	0.12	2.82	Dry	25.93	0.12	0.34	Dry	Dry	Dry	Dry	Dry	2.82	Dry	2.82	0.12	2.82	0.12	2.82	0.12	2.82	0.93	2.82	0.12
AIP <sup>1</sup> Dike/Weir #4	Weekly with daily readings between March 1 and May 30. Read for 3 days following rainfall event >10 mm.	500 m <sup>3</sup> /day	26.17	9.56	20.76	1.73	34.01	3.51	26.17	Dry	19.53	Dry	27.64	Dry	333.59	26.17	93.33	14.02	65.35	14.02	26.17	14.02	14.02	9.56	14.02	3.51
West Gypsum Cell/Toe of Gravel Buttress at Cow Creek (STA. 11+00)	Visual Reading Annually	Cloudy flow	Flow is clear (observed as part of May 2022 site visit)																							
East Gypsum Cell/Toe of Dike Adjacent to James Creek	Visual Reading Annually	Cloudy flow	Flow is clear (observed as part of May 2022 site visit)																							

Notes:  
1. AIP = Iron Pond

**Table III-11 Active Pond Water Level Monitoring Locations**

Type	Description	Location	Primary Purpose	Reading Frequency	Notification Level 1	Notification Level 2	Notification Level 3	General Water Level Information (m)
Iron Pond Water Level	Electronic readout unit.	Iron Dike Pump Station	Overtopping	Daily	1038.5 (Pump to ARD Pond)	1038.9 (As for Level 1 and notify EOR, minimize inflows, consider pumping to DWTP)	1040.5 (As for Level 2 and notify MEMPR/MOE, enact EPRP)	1037.3 Measured low water
								1041.61 Measured high water
								1041.0 <sup>1</sup> (Spillway invert)
								1042.0 (Top of dike)
Pond Water Level	Electronic readout unit with pressure transducer in bottom of wet well at el. 1034 m.	Pump wet well, data transmitted to DWT control room through the PLC system	Dam Stability	Daily	1045.5 (Pump to DWTP)	1046.5 (As for Level 1 and notify EOR, minimize inflows (e.g. divert 3700/3900 to Iron Pond))	1046.9 (As for Level 2 and notify MEMPR/MOE, enact EPRP)	1036.6 Measured low water
								1043.4 Measured high water
								1046.5 9 Maximum operating level)
								1047.4 (Spillway invert)
								1048.0 (Top of dam)

**Notes:**

1. The surveyed as-constructed invert elevations for the Iron Pond/Emergency Spillway varied from 1040.8 m to 1041.4 m, with the design elevation being 1041.0 m.

## **APPENDIX IV**

### **Iron Dike Instrumentation**

---

### Iron Dike Line 6+00 Piezometer Readings





Figure IV-1 STN 6+00



### Iron Dike Line 16+00 Piezometer Readings (Foundation)



Straight lines same colour as data plots indicate tip elevation.

Red lines are the maximum threshold values.

Standpipe piezometers were flushed in July/August 2014. Not all sediment was removed and some casings also cut or extended/repared at this time. Therefore a new top of casing and new depth to bottom of standpipe was recorded for many instruments. Older data will appear below tip elevation if previously read "dry" or if previous top of casing elevation was incorrect due to damage.

SPxxx represents readings to point of flushing. SPxxx(R1) represents readings post flushing. If no (R1) plot then no change to top of casing elevation or depth to bottom of standpipe.

Figure IV-2 STN 16+00 Foundation

### Iron Dike Line 16+00 Piezometer Readings (Tailings)




Figure IV-3 STN 16+00 Tailings

### Iron Dike Line 24+00 Piezometer Readings




Figure IV-4 STN 24+00

### Iron Dike Line 30+00 Piezometer Reading




Figure IV-5 STN 30+00

### Iron Dike Line 38+00 Piezometer Readings




Figure IV-6 STN 38+00

### Iron Dike Line 42+00 Piezometer Readings




Figure IV-7 STN 42+00

### Iron Dike Line 45+00 Piezometer Readings




Figure IV-8 STN 45+00

### Iron Dike Line 54+00 (Approximate)




Standpipe piezometers were flushed in July/August 2014. Not all sediment was removed and some casings also cut or extended/repared at this time. Therefore a new top of casing and new depth to bottom of standpipe was recorded for many instruments. Older data will appear below tip elevation if previously read "dry" or if previous top of casing elevation was incorrect due to damage.

SPxxx represents readings to point of flushing. SPxxx(R1) represents readings post flushing. If no (R1) plot then no change to top of casing elevation or depth to bottom of standpipe.

Figure IV-9 Line 54+00



### Iron Dike Toe Piezometer Readings



- P92-25 • Water Elevation (m)    ▲ P92-26 • Water Elevation (m)    ● P92-H (pressure gauge) • Water Elevation (m)    ✕ P92-H (VWP) (Old RST) • Water Elevation (m)
- Iron Pond • Water Elevation (m)    ★ P92-H (SP) • Water Elevation (m)    ✕ P92-H (VWP) • Water Elevation (m)


Straight lines same colour as data plots indicate tip elevation.

Red lines are the maximum threshold values.

Standpipe piezometers were flushed in July/August 2014. Not all sediment was removed and some casings also cut or extended/repared at this time. Therefore a new top of casing and new depth to bottom of standpipe was recorded for many instruments. Older data will appear below tip elevation if previously read "dry" or if previous top of casing elevation was incorrect due to damage.

Figure IV-10 Toe Piezometers


### IRON TSF WEIR #3 (AIPWU) Flows



● WEIR3 AIPWU • Calc1    ● Iron Pond • Water Elevation (m)

Figure IV-11 AIP and AIPWU Weir Plots

# IRON TSF WEIR #4 Flows



● Iron Pond • Water Elevation (m) ● WEIR 4 ID • Calc1

# Active Settlement Plate Data

Iron TSF (Iron Pond)




Figure IV-12 SP 92-07

# Active Settlement Plate Data

Iron TSF (Iron Pond)




Figure IV-13 SP 330 - 332 and SP 99-01

# Active Settlement Plate Data

Iron TSF (Iron Pond)








Figure IV-14 SP 330 - 332 and SP 99-01

\\nt.klhn.com\ProjData\AIEDM\A05807A2.1 TML 2021 Annual Inspection\Figure IV-15 2021.dwg Layout=Figure 4 October 15, 2021 6:22:19 PM



**IRON DYKE CREST**  
HOR: 1:1500  
VER: 1:300



<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> <p><b>Teck</b></p> <p><b>Klohn Crippen Berger</b></p>	<p>PROJECT</p> <p>SULLIVAN MINE 2021 ANNUAL INSPECTION REPORT</p>
		<p>TITLE</p> <p>IRON DIKE CREST AND SPILLWAY PROFILE</p>
<p>PROJECT No. A05807A21</p>		<p>FIG No. FIGURE IV-15</p>

KCC-D-B


## APPENDIX V

### Old Iron Instrumentation

---



### Old Iron Dike Buttress Pneumatic Piezometer Readings (Old Iron TSF)




Elevations are relative to elevation of top of tailings or original ground prior to construction of the toe berm in 1996, i.e. m of head measured - difference between top of berm in 1996 and estimated top of ground prior to berm construction.

P96-02: Destroyed  
P96-11: Slow leak 2008 unable to get reading until 2011, erratic data since 2012, replaced in 2018

Figure V-1 Old Iron Dike Buttress

### Old Iron Dike Piezometer Readings




Standpipe piezometers were flushed in July/August 2014. Not all sediment was removed and some casings also cut or extended/repaired at this time. Therefore a new top of casing and new depth to bottom of standpipe was recorded for many instruments. Older data will appear below tip elevation if previously read "dry" or if previous top of casing elevation was incorrect due to damage.

P-xxx old represents readings to point of flushing. P-xxx represents readings post flushing. If no "old" plot then no change to top of casing elevation or depth to bottom of standpipe.

Figure V-2 Old Iron Dike

### Iron TSF Divider Dike



Standpipe piezometers were flushed in July/August 2014. Not all sediment was removed and some casings also cut or extended/repared at this time. Therefore a new top of casing and new depth to bottom of standpipe was recorded for many instruments. Older data will appear below tip elevation if previously read "dry" or if previous top of casing elevation was incorrect due to damage.

Figure V-3 Iron TSF Divider Dike

### Old Iron Pond Southwest Limb VW Piezometers





Figure V-4 Old Iron Dike VWP

## APPENDIX VI

### Siliceous Dike Instrumentation

---

### Siliceous Dike #1 - East Side and Middle Piezometer Readings



- SP104 old • Water Elevation (m)
- SP104 • Water Elevation (m)
- ▲ P105 old • Water Elevation (m)
- ▲ P105 • Water Elevation (m)
- SP106 old • Water Elevation (m)
- SP106 • Water Elevation (m)

**Notes:**

Straight lines same colour as data plots indicate bottom of standpipe/tip elevation.


Read lines are threshold values.

Standpipe piezometers were flushed in July/August 2014. Not all sediment was removed and some casings also cut or extended/repaired at this time. Therefore a new top of casing and new depth to bottom of standpipe was recorded for many instruments. Older data will appear below tip elevation if previously read "dry" or if previous top of casing elevation was incorrect due to damage.

Pxxx old represents readings to point of flushing. Pxxx represents readings post flushing. If no "old" plot then no change to top of casing elevation or depth to bottom of standpipe.

Figure VI-1

### Siliceous Dike #1 West Piezometer Readings



**Notes:**

Straight lines same colour as data plots indicate bottom of standpipe/tip elevation.


Red lines are the maximum threshold values.

Standpipe piezometers were flushed in July/August 2014. Not all sediment was removed and some casings also cut or extended/repaired at this time. Therefore a new top of casing and new depth to bottom of standpipe was recorded for many instruments. Older data will appear below tip elevation if previously read "dry" or if previous top of casing elevation was incorrect due to damage.

Pxxx old represents readings to point of flushing. Pxxx represents readings post flushing. If no "old" plot then no change to top of casing elevation or depth to bottom of standpipe.

Figure VI-2

### Silicesou Cell #2 - Piezometer Readings



● P231 • Water Elevation (m)   ● P231 old • Water Elevation (m)   ▲ P257 old • Water Elevation (m)   ▲ P257 • Water Elevation (m)   ✕ P91-13 • Water Elevation (m)

**Notes:**

Straight lines same colour as data plots indicate bottom of standpipe/tip elevation.

Red lines are the threshold values.


Standpipe piezometers were flushed in July/August 2014. Not all sediment was removed and some casings also cut or extended/repairs at this time. Therefore a new top of casing and new depth to bottom of standpipe was recorded for many instruments. Older data will appear below tip elevation if previously read "dry" or if previous top of casing elevation was incorrect due to damage.

Pxxx old represents readings to point of flushing. Pxxx represents readings post flushing. If no "old" plot then no change to top of casing elevation or depth to bottom of standpipe.

Figure VI-3



Lines 3+00/7+00 Piezometer Readings (Cell #3 Siliceous TSF) (Foundation & Dike)



- P302 old • Water Elevation (m)    ■ P302 • Water Elevation (m)    ✕ P232 old • Water Elevation (m)    ✕ P232 • Water Elevation (m)
- ◆ P233 old • Water Elevation (m)    ◆ P233 • Water Elevation (m)    ● SUL-SD3-VWP-18-06A • Water Elevation (m)
- ★ SUL-SD3-VWP-18-07 • Water Elevation (m)    ▲ SUL-SD3-VWP-18-08A • Water Elevation (m)

Straight lines same colour as data plots indicate tip elevation.


Red lines are the maximum threshold values.

Standpipe piezometers were flushed in July/August 2014. Not all sediment was removed and some casings also cut or extended/repared at this time. Therefore a new top of casing and new depth to bottom of standpipe was recorded for many instruments. Older data will appear below tip elevation if previously read "dry" or if previous top of casing elevation was incorrect due to damage.

Pxxx old represents readings to point of flushing. Pxxx represents readings post flushing. If no "old" plot then no change to top of casing elevation or depth to bottom of standpipe.

Figure VI-4 Siliceous Cell #3 TSF Line 3 +00/7+00 (Foundation and Dike)

Lines 3+00/7+00 Piezometer Readings (Cell #3 Siliceous TSF) (Tailings)



Straight lines same colour as data plots indicate tip elevation.


Red lines are the maximum threshold values.

Standpipe piezometers were flushed in July/August 2014. Not all sediment was removed and some casings also cut or extended/repared at this time. Therefore a new top of casing and new depth to bottom of standpipe was recorded for many instruments. Older data will appear below tip elevation if previously read "dry" or if previous top of casing elevation was incorrect due to damage.

Pxxx old represents readings to point of flushing. Pxxx represents readings post flushing. If no "old" plot then no change to top of casing elevation or depth to bottom of standpipe.

Figure VI-5 Siliceous Cell #3 TSF Line  
3+00/7+00 (Tailings)

East Side Piezometer Readings (Cell #3 Siliceous TSF) (Foundation)



● SUL-SD3-P-18-10 • Water Elevation (m) ■ SUL-SD3-P-18-11 • Water Elevation (m)

Straight lines same colour as data plots indicate tip elevation.

Red lines are the maximum threshold values.

Standpipe piezometers were flushed in July/August 2014. Not all sediment was removed and some casings also cut or extended/repared at this time. Therefore a new top of casing and new depth to bottom of standpipe was recorded for many instruments. Older data will appear below tip elevation if previously read "dry" or if previous top of casing elevation was incorrect due to damage.




Pxxx old represents readings to point of flushing. Pxxx represents readings post flushing. If no "old" plot then no change to top of casing elevation or depth to bottom of standpipe.

Figure VI-6 Siliceous Cell #3  
TSF East (Foundation)

## APPENDIX VII

### W Gypsum Dike Instrumentation

---




AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.	<b>Teck</b>	PROJECT <b>SULLIVAN MINE 2021 ANNUAL INSPECTION REPORT</b>	
		TITLE <b>WEST GYPSUM DIKE SONDEX AND INCLINOMETER PLOTS</b>	
	PROJECT No. <b>A05807A21</b>	FIG. No. <b>FIGURE VII-1</b>	

A05807A21\_FIGURE VII-1.dwg

KCC-F-BM

### Line 10+00 Piezometer Readings (West Gypsum Dike)



Straight lines same colour as data plots indicate tip elevation.


Red lines are the maximum threshold values.

Standpipe piezometers were flushed in July/August 2014. Not all sediment was removed and some casings also cut or extended/repared at this time. Therefore a new top of casing and new depth to bottom of standpipe was recorded for many instruments. Older data will appear below tip elevation if previously read "dry" or if previous top of casing elevation was incorrect due to damage.

SPxxx old represents readings to point of flushing. SPxxx represents readings post flushing. If no "old" plot then no change to top of casing elevation or depth to bottom of

Figure VII-2 Line 10+00

### Line 20+00 Piezometer Readings (West Gypsum Dike)



Straight lines same colour as data plots indicate tip elevation.

Red lines are the maximum threshold values.

Standpipe piezometers were flushed in July/August 2014. Not all sediment was removed and some casings also cut or extended/repared at this time. Therefore a new top of casing and new depth to bottom of standpipe was recorded for many instruments. Older data will appear below tip elevation if previously read "dry" or if previous top of casing elevation was incorrect due to damage.

SPxxx old represents readings to point of flushing. SPxxx represents readings post flushing. If no "old" plot then no change to top of casing elevation or depth to bottom of standpipe.

Figure VII-3 Line 20+00

SETTLEMENT PLATES - WEST GYPSUM DIKE

**SP97-01 Line 10+00**  
SETTLEMENT PLATES - WEST GYPSUM DIKE





Figure VII-4-SP97-01



SETTLEMENT PLATES - WEST GYPSUM DIKE

**SP97-05 Line 10+00**  
SETTLEMENT PLATES - WEST GYPSUM DIKE





Figure VII-5-SP97-05

SETTLEMENT PLATES - WEST GYPSUM DIKE

**SP97-06 Line 20+00**  
SETTLEMENT PLATES - WEST GYPSUM DIKE






Figure VII-6-SP97-06

## APPENDIX VIII


### E Gypsum Dike Instrumentation

---




GYP SUM DYKES FACILITY, Inclinator BI-94-02  
SULLIVAN MINE, KIMBERLEY

Sondex settlement gauge S94-02  
Cumulative settlement relative to Ring 1




Sondex settlement gauge S94-02  
Cumulative settlement relative to Ring 1



<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	CLIENT	<p><b>Teck</b></p>	
	PROJECT	<p>SULLIVAN MINE 2021 ANNUAL INSPECTION REPORT</p>	
	TITLE	<p>EAST GYP SUM DIKE SONDEX AND INCLINOMETER PLOTS</p>	
	PROJECT No.	A05807A21	FIG. No.
			FIGURE VIII-1

### Line 33+00 Piezometer Readings (East Gypsum Dike)



- P93-08 • Water Elevation (m)    ■ P93-09 • Water Elevation (m)    ▲ P93-10 • Water Elevation (m)    ✕ P93-11 • Water Elevation (m)
- ★ P93-12 • Water Elevation (m)    ◆ SUL-EG-P-18-04 • Water Elevation (m)


Straight lines same colour as data plots indicate tip elevation.

Red lines are the maximum threshold values.

Standpipe piezometers were flushed in July/August 2014. Not all sediment was removed and some casings also cut or extended/repairs at this time. Therefore a new top of casing and new depth to bottom of standpipe was recorded for many instruments. Older data will appear below tip elevation if previously read "dry" or if previous top of casing elevation was incorrect due to damage.

Figure VIII-2 Line 33+00

### Line 48+00 Piezometer Readings (East Gypsum Dike)



Straight lines same colour as data plots indicate tip elevation.

Red lines are the maximum threshold values.

Standpipe piezometers were flushed in July/August 2014. Not all sediment was removed and some casings also cut or extended/repaired at this time. Therefore a new top of casing and new depth to bottom of standpipe was recorded for many instruments. Older data will appear below tip elevation if previously read "dry" or if previous top of casing elevation was incorrect due to damage.

Figure VIII-3 Line 48+00

SETTLEMENT PLATES - EAST GYPSUM DIKE

**SP97-03 Line 33+00**  
SETTLEMENT PLATES - EAST GYPSUM DIKE





Figure VIII-4-SP97-03

SETTLEMENT PLATES - EAST GYPSUM DIKE

**SP97-04 Line 48+00**  
SETTLEMENT PLATES - EAST GYPSUM DIKE





Figure VIII-5-SP97-04



## APPENDIX IX

### NE Gypsum Dike Instrumentation

---

SETTLEMENT PLATES - NE GYPSUM DIKE

**W Pipe**  
NE Gypsum Dike





Figure IX-1 NE Gypsum Dike W pipe

SETTLEMENT PLATES - NE GYPSUM DIKE

**E Pipe**  
NE Gypsum Dike





Figure IX-2 NE Gypsum Dike E pipe




Figure IX-3

# APPENDIX X

## ARD Instrumentation

---

ARD Pond South Dam Pneumatic Piezometers (Interface of Fill and Foundation)





Figure X-1 South Dam


### ARD South Dam Standpipe Piezometers (Foundation)



Standpipe piezometers were flushed in July/August 2014. Not all sediment was removed and some casings also cut or extended/repared at this time. Therefore a new top of casing and new depth to bottom of standpipe was recorded for many instruments. Only noticeable for those instruments which record "dry" or if previous top of casing elevation was incorrect due to damage.

Figure X-2 South Dam Standpipe

### ARD North Dam Standpipe Piezometers (Foundation)



● ND-01 • Water Elevation (m)   
 ✕ ND-02D • Water Elevation (m)   
 + ND-02S • Water Elevation (m)   
 ★ ND-03 • Water Elevation (m)   
 — ARD Pond • Water Elevation (m)

Standpipe piezometers were flushed in July/August 2014. Not all sediment was removed and some casings also cut or extended/repared at this time. Therefore a new top of casing and new depth to bottom of standpipe was recorded for many instruments. Only noticeable for those instruments which record "dry" or if previous top of casing elevation was incorrect due to damage.

Figure X-3 North Dam Standpipes



ARD Pond North Dam Pneumatic Piezometers (Interface of Fill and Foundation)





Figure X-4 North Dam Piezometers

### ARD South Dam - Left Abutment



- SUL-ARSD-VWP-20-01 • Water Elevation (m)
- SUL-ARSD-VWP-20-02 • Water Elevation (m)
- SUL-ARSD-VWP-20-03 • Water Elevation (m)
- SUL-ARSD-VWP-20-04 • Water Elevation (m)
- ARD Pond • Water Elevation (m)

Figure X-5 South Dam - Left Abutment

### ARD POND - South Dam Weir #1 (ARDWU) Flows




Figure X-6 ARD Weir #1 (ARDWU) time plot

● WEIR 1 ARDWU • Calc1    
 — ARD Pond • Water Elevation (m)

### ARD POND - South Dam Weir #2 Flows




Figure X-7 ARD Weir #2 time plot

ARD Pond • Water Elevation (m) WEIR 2 ARD • Calc1

ARD Pond - South Dam Settlement Plate Data





Figure X-8

ARD Pond - North Dam Settlement Plate Data



◆ ARD SP1 • Elevation (m)    ■ ARD SP2 • Elevation (m)    ▲ ARD SP3 • Elevation (m)


Figure X-9

# APPENDIX XI

## Sludge Pond Instrumentation

---

Sludge Pond - North Dike




● SUL-SPND-VWP-21-01 • Water Elevation (m) ● SUL-SPND-VWP-21-02 • Water Elevation (m) ● SUL-SPND-VWP-21-05 • Water Elevation (m)

Figure XI-1 Sludge Pond North Dike



Sludge Pond - South Dike



● SUL-SPSD-VWP-21-03 • Water Elevation (m) ● SUL-SPSD-VWP-21-04 • Water Elevation (m) ● SUL-SPSD-VWP-21-06 • Water Elevation (m)

Figure XI-2 Sludge Pond South Dike



## **APPENDIX XII**

### **Sludge Pond Dike Crest Survey**


---

W:\it\kcb\projdata\A\EDM\A05807A21.TML 2021 Annual Inspection\400 Drawings\Annual Inspection\Figure XI-1 2021.dwg Layout=FIGURE XI-1 October 15, 2021 6:17:06 PM



**NORTH DAM CREST**



**A PROFILE**  
 SCALE 1:750 HORIZ.  
 1:150 VERT.




**SOUTH DAM CREST**



**B PROFILE**  
 SCALE 1:750 HORIZ.  
 1:150 VERT.

**LEGEND**

- 2012 LIDAR
- 2019 LIDAR



AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.	<b>Teck</b>  	CLIENT  <b>SULLIVAN MINE</b> 2021 ANNUAL INSPECTION REPORT
	PROJECT  <b>SLUDGE POND</b> <b>DIKE CREST PROFILES</b>	PROJECT No. A05807A21
PROJECT No. A05807A21		FIG No. FIGURE XI-1

KCC-09

## **APPENDIX XIII**

### **Pond Storage Curves**

---

## Appendix XII Pond Storage Curves

Figure XII-1 ARD Storage Pond Area - Volume Curve




Figure XII-2 Iron Pond Stage - Volume Curve

